

Village of Mamaroneck

# ILLICIT DISCHARGE DETECTION AND ELIMINATION – PHASE 5 REPORT

Mamaroneck, NY

February 4, 2016

# **VERSION CONTROL**

Issue	Revision No	Date Issued	Page No	Description	Reviewed by

# **CONTENTS**

1	Backg	ground	1
2	Storm	water Outfall Inventory and Inspection	2
		Conclusions and Recommendations	3
3	Rye N	leck High School Dye Testing and Sampling	3
	3.1	Dye Testing	3
	3.2	Stream and Outfall Sampling	5
		Conclusions and Recommendations	6
4	East E	Basin Abandoned Sewer Line Investigation	7
	4.1	East Basin Siphon	7
	4.2	West Basin Siphon	8
5	Otter	Creek Inspection	9
		Conclusions and Recommendations	9
6	Draina	age Area Investigations	. 10
	6.1	Outfall Vg 24 Concord Avenue	. 12
	6.2	Outfall 26 - Halstead Ave	. 13
7	As-Ne	eeded Illicit Discharge Detection and Elimination Assistance	. 15
	7.1	Responding to Observations of Citizens and Representatives	. 15
		7.1.1 River Sampling – Surface Foam Observed	. 15
		7.1.2 River Sampling – Surface Film Observed	. 15
		7.1.3 Gasoline Odor Investigation Near Creek Road	. 16
		7.1.4 Storm Sewer Inspection – Stanley Avenue	. 17
	7.2	River Sampling and DNA Testing	. 17
		7.2.1 Fecal Coliform Samples	. 17
		7.2.2 DNA Testing	. 17
	7.3	Sanitary Sewer Lateral Connection - Grout Pilot Program	. 18
	7.4	Septic System Analysis	. 20
	7.5	EPA Quarterly Reports	. 21

# **TABLES**

Table 2-1.	Outfall Inventory and Inspection	2
Table 2-2.	Bathrooms and Drains Dye Tested	5
Table 6-1.	Previous Outfall Sampling Results Compared to 2015 1	1

# **FIGURES**

Figure 1.	Rye Neck High School Sewer Schematic	Page 4
Figure 2.	Rye Neck High School Beaver Swamp Brook Sample Results	After Page 6
Figure 3.	Approximate Location of Abandoned Siphons	After Page 7
Figure 4.	Harbor Island Park Abandoned Manholes	After Page 7
Figure 5.	Otter Creek	After Page 9
Figure 6.	Outfall Vg 24 – Concord Avenue Drainage Area Investigation Results	After Page 12
Figure 7.	Outfall 26 – Halstead Avenue Drainage Area Investigation Results	After Page 13
Figure 8.	Gasoline Odor Investigation Location	After page 16

# **APPENDICES**

- A 2015 Outfall Inspection Forms
- B 2015 Laboratory Results
- C Otter Creek Investigation Photo Log
- D River Foam Sampling Events
- E Gasoline Odor Investigation Photo Log
- F River Sampling Results Map
- G DNA Sampling Results
- H Grouting Pilot CCTV Inspection Logs and Videos on CD
- I Septic Distance to Sewer Map and Table

# 1 BACKGROUND

In 2010, the Environmental Protection Agency (EPA) collected samples at three stream locations in the Village of Mamaroneck (Village). The results of these samples showed high levels of fecal and total coliform bacteria and were the basis for the issuance of an Administrative Order CWA-02-2001-3022 (Order) to the Village. This Order was the impetus for the Village to conduct a system wide Illicit Discharge Detection and Elimination program (IDDE). Malcolm Pirnie, now Arcadis, was awarded a contract in July of 2012 to assist the Village with their IDDE program and has been engaged in the work each consecutive year since then.

This report summarizes the 2015 engineering services completed for sewer system investigations in the Village of Mamaroneck to identify sources of illicit discharges.

# 2 STORMWATER OUTFALL INVENTORY AND INSPECTION

Arcadis began an inventory, inspection and GIS mapping update of outfalls in 2013. Arcadis visited the remaining eleven outfalls in 2015. Of these eleven, four outfalls were located in areas where they could not be accessed, and two outfalls could not be located. The Arcadis field team did a thorough survey in attempt to locate each outfall, but heavy vegetation or sand, may have prevented them from being identified in the field. Storm sewer manholes in the vicinity of the outfalls were inspected to confirm there was no dry weather flow in the storm sewer that drains to the outfall. In addition, the outfalls that could not be accessed or located were not part of a large drainage system, they were either private area drainage systems, or small systems consisting of a few catchbasins and drainage pipe. The six outfalls that could not be located or accessed are still shown on the GIS map as "record" locations.

Of the five outfalls inspected, only one outfall Vk 4a, had dry weather flow (<1 gpm) during the inspection. No abnormal colors or odors were observed in the discharge from this outfall. Due to the very low flow rate and lack of other indicators of illicit discharge, Arcadis did not collect a sample at this outfall. Outfall 71 is in disrepair and should be considered for repair.

A complete summary of the outfalls investigated in 2015 and their illicit discharge potentials are presented in Table 2-1, below. The inspection forms for these outfalls are included as Appendix A.

Outfall Name	Illicit Discharge Potential		
52	Unlikely		
63	Unlikely		
64	Unlikely. Could not locate outfall but the upgradient catchbasin did not have dry weather flow or odors.		
71	Unlikely		
78	Unlikely. Could not locate, potentially covered in sand. Upgradient catchbasin did not have dry weather flow or odors.		
160	Unlikely. No access to outfall. Upgradient manhole shows no signs of illicit discharge; no dry weather flow		
VI 1	Unlikely		
VI 1a	Unlikely. No access to outfall (on private beach). Upgradient catchbasin part of large system, no odors.		
Vk 4a	Unlikely. Trickling (< 1 gpm)		
Vk 10e	Unlikely. No access to outfall (on private beach); Upgradient catch basin submerged with debris and sediment; Poor operating condition		
Vk 13a	Unlikely. No access. Upgradient manhole no flow, no odor.		

#### Table 2-1. Outfall Inventory and Inspection

### **Conclusions and Recommendations**

Arcadis findings do not suggest that any of the outfalls in the table above had likelihood of illicit discharge. The outfall inspection program was completed in less time than is required by the Village's municipal separate storm sewer system (MS4) General Permit. This compressed schedule was implemented to more quickly determine if there were significant illicit discharges so they could be eliminated.

The outfall program has previously identified some significant problems, which have been corrected. Section 6, Drainage Area Investigations, discusses additional outfall sampling results that were collected as part of drainage area investigations.

# 3 RYE NECK HIGH SCHOOL DYE TESTING AND SAMPLING

Water sampling from both Arcadis and Save the Sound has consistently shown elevated fecal coliform concentrations in Beaver Swamp Brook at the Village's east border. Rye Neck High School lies on the border of the Village of Mamaroneck and the City of Rye. No sampling had previously been completed with the intent of investigating for illicit discharges associated with the school. The Village wanted to rule out the school as a source of illicit discharges by completing a thorough investigation of the school and the stormwater outfalls in the surrounding area.

The Rye Neck High School sanitary sewer drains were dye tested to ensure no sewage drains to Beaver Swamp Brook. The stormwater outfalls and Beaver Swamp Brook were sampled in an attempt to isolate sections of the Brook that had high fecal coliform concentrations. Samples were also collected from a minor branch of Beaver Swamp Brook to determine if this small stream contributes to elevated fecal coliform sample results from the Brook. The location of the samples can be found in Figure 2.

## 3.1 Dye Testing

Arcadis staff met with the high school janitor at 9 am on July 28, 2015. The investigation began by opening manholes in the parking lot on the west side of the building (the back of the school). After looking in multiple manholes, Arcadis staff determined that the sanitary flow comes from both sides of the high school (A Corridor and E Corridor), and combines at a manhole located at a handicap parking spot near the middle of the building between B Corridor and D Corridor. From this manhole, flow travels towards Beaver Swamp Brook and is believed to cross under the brook and connect to the County intercepting sewer. A schematic of high school sanitary sewer system is provided as Figure 1.



Figure 1. Rye Neck High School Sewer Schematic

During dye testing, an Arcadis staff visited each of the bathrooms and janitor closets adjacent to each bathroom, poured sewer tracing dye, and flushed water down the drain. The locations tested are shown in Table 2-2. Two additional Arcadis staff stayed outside to monitor the downgradient sanitary sewer manhole, storm sewer manhole, and the stormwater outfalls along Beaver Swamp Brook.

Table 2-2. Bathrooms and Drains Dye Tested

Dye Tested Bathrooms
A Corridor Bathrooms
A Corridor Faculty Bathrooms
A Corridor Faculty Bathrooms –
Middle School Faculty
B Corridor Bathrooms
D Corridor Bathrooms
E Corridor Bathrooms
Kitchen Bathroom toilet
Administrative Building <sup>(1)</sup>

Note: <sup>(1)</sup> Administrative Building was dye tested during follow up work on September 2, 2015

Each dye test took between 10 and 20 minutes depending on the location of the bathroom relative to the sanitary sewer manhole that receives the sewage. Arcadis staff confirmed for each dye test that dye appeared in the sanitary manhole and that the stormwater outfalls remained dry and had no signs of dye. One stormwater outfall was trickling prior to the start of the testing and continued to trickle during dye testing.

The sanitary manhole located directly outside of the A Corridor bathrooms receives flow when the toilets are flushed. At the time of the July 28, 2015 dye testing event, the next downstream manhole was half full of sewage and the inflow pipes were not visible. Arcadis notified the school of this maintenance issue and they hired a contractor to flush out the blockage.

On September 2, 2015, Arcadis returned to the school to dye test the A Corridor bathroom again and the Administration Building to confirm proper discharge. For each location, dye was visible in the sanitary manhole and no flow was observed in the storm sewer or outfalls.

## 3.2 Stream and Outfall Sampling

There are five stormwater outfalls in the vicinity of the school. All but one (BSB-03, located on the east bank of Beaver Swamp Brook) were dry during the investigation. Arcadis staff collected a sample from outfall BSB-03 during the July 28, 2015 sampling event. The fecal coliform concentration was 1200 cfu/100 ml, but the flow was less than 1 gpm.

Samples were collected from Beaver Swamp Brook both upstream and downstream of the high school and from a minor branch of the brook. All results showed elevated fecal coliform concentrations, particularly the minor branch of

the Beaver Swamp Brook near Rye Neck High School. The sample results are presented on Figure 2. All sample results for this investigation are provided as Appendix B.

### **Conclusions and Recommendations**

Arcadis findings do not suggest that the sanitary sewer at Rye Neck High School is connected to the storm sewer or discharges to outfalls on Beaver Swamp Brook. The school has one outfall with intermittent dry weather flow with elevated fecal coliform concentrations. It is recommended that the high school complete a CCTV inspection in this storm sewer line to identify the source. The intermittent pollutant load from this outfall is currently very low and would not make a significant impact to the water quality in the Brook. However, an inspection would help determine if there is a source that could increase concentrations in the future.

There is an elevated fecal coliform concentration in both the main branch of the Beaver Swamp Brook and the minor branch that flows into the main branch across from the High School; both are upgradient of the Village border. The minor branch is located in the Town of Harrison and main branch is bordered by the Town of Harrison and the City of Rye. These communities were notified by the Village regarding the elevated fecal coliform concentrations on October 21, 2015.

# **Town of Harrison**

Beaver Swamp Brook follows municipal boundary.

Minor Branch of Beaver Swamp Brook (DS) 7,300; 8/6/2015

Minor Branch of Beaver Swamp Brook (US) 5,000; 7/28/2015 6,500; 8/6/2015

**City of Rye** 

Upstream of High School 700, 500; 7/21/2015 2,900; 7/28/2015

Hd 19 116,000; 10/7/2014; 6 3,900; 7/16/2015; 2

> OFELN **BSB-03** <20; 4/22/2014 -; 7/16/2015; dry 1,200; 7/28/2015; <1 -; 8/6/2015; dry

> > **BSB-01** 350; 4/21/2014

# **Village of** Mamaroneck

#### Notes

Stream Sample Results - "700, 500; 7/21/2015" -Fecal coliform concentration(s); sampling date.

Outfall Sample Results - "1,200; 7/28/2015; <1" Fecal coliform concentration(s); sampling date; flow (gpm) if applicable.

All concentrations in CFU/100mL

#### Legend **Stormwater Outfalls**

- ARCADIS Inspected
- Record Outfalls
- 2015 ARCADIS Stream Sampling Locations
- Streams
- Municipal Boundary Village Boundary
- **Property Line**

**Rye Neck High School** 

Downstream of High School 1,900, 1,000; 7/21/2015 1,500; 7/28/2015

SCALE IN FEET

500

2

VILLAGE OF MAMARONECK MAMARONECK, NY

### RYE NECK HIGH SCHOOL AND BEAVER SWAMP BROOK SAMPLE RESULTS

FIGURE gn & Consultancy ARCAD for natural and built assets

Service Layer Credits: Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AEX, Getmapping, Aerogrid, IGN, IGP, swisstopo, and the GIS User Community

1/25/2016 12:52:21 PN Its.mxd DATE SAVED: PM: KCH TM: ea2015ArcRes PIC: ë CMS Ш

# 4 EAST BASIN ABANDONED SEWER LINE INVESTIGATION

Historically, there was one inverted siphon that transported sewage under the East Basin of Mamaroneck Harbor and one under the West Basin. These inverted siphons were abandoned years ago, and the sewage is now pumped to the wastewater treatment plant without crossing a water body. Arcadis staff investigated the abandoned infrastructure to confirm it was properly sealed and not discharging sewage into the Harbor. Inspections were completed by Arcadis staff on September 16, 2015 and December 7, 2015. Figure 3 shows generally where these siphons were located based on historic maps. Locations "A" and "B" are the approximate end points of the East Basin siphon and locations "C" and "D" are the approximate end points of the West Basin siphon.

# 4.1 East Basin Siphon

As-built drawings from 1987, titled East Basin Sewer, developed from the engineering firm O'Brien and Gere, show how the upgradient end of the siphon was abandoned and sewage redirected to the pump station located on South Barry Avenue. The reconstructed manhole, Vj 1, is located in between 600 and 604 Shore Acres Drive. This is shown as location "A" in Figure 3. The manhole was reconstructed to direct sewage from the two adjacent homes to a new gravity sewer on Shore Acres Drive, instead of discharging to a siphon located under the harbor. The opening of the 12-inch outlet pipe that lead to the siphon was abandoned by filling it with watertight non-shrink grout.

Manhole Vj 1 was inspected by Arcadis staff and found to be operating as designed. There was very little sewage flow since only two homes discharge to the manhole. The grout was still in good condition and completely covered the pipe that historically discharged to the siphon. Based on observations, there is very little chance of sewage entering the harbor from a faulty repair at this location.

The downgradient end of the historic East Basin Siphon was located at Harbor Island Park, next to what is currently the Parks and Recreation building. This is shown as location "B" on Figure 3. The abandoned sewer line runs parallel to the active Parks and Recreation building sewage line, which flows toward the parking lot adjacent to the tennis courts.

A diagram of the manholes in the Harbor Island Park is included as Figure 4. The abandoned manholes, labelled MH 1 and MH 2, were partially submerged with stagnant water. MH 1 is 7.3 feet deep and, and the water depth was 6.5 feet at the time of the inspection. The stagnant water in the manhole was murky, but a survey rod was used to probe the manhole walls and a pipe opening was discovered. This opening is oriented toward the Parks and Recreation building and agrees with historic maps. MH 2 was also partially submerged. This manhole is 14.5 feet deep and the water depth was 7.5 feet at the time of the inspection. A survey rod was again used to probe the bottom of the manhole, and another opening was discovered. MH 3, which would have been the closest manhole to the Harbor could not be located. MH 4 and MH 5, which are downgradient and closer to the wastewater treatment plant, appear to have been paved over.

Based on observations of the manholes on this abandoned sewer line, it is not likely that sewage could enter the Harbor at this location. The water in these manholes is stagnant which means the pipe is blocked at both ends. In addition, the sewer was designed to flow from the Harbor to the plant, so there would have to be significant flow or head for a discharge to travel upgradient and reach the Harbor.



Service Layer Credits: Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AEX, Getmapping, Aerogrid, IGN, IGP, swisstopo, and the GIS User Community

PM: KCH TM:

LD: PIC: ( IDDE



# 4.2 West Basin Siphon

The West Basin Pump Station was constructed to replace the West Basin siphon. The upgradient siphon structure was located in the vicinity of what is currently Nichols Yacht Yard, at 500 Rushmore Avenue, and the downgradient structure was located on the west end of the Harbor Island Park. Locations "C" and "D" on Figure 3 show generally where the west basin siphon was located based on historic documents.

The field team searched the grounds of the marina and the west side of Harbor Island Park, but could not locate any abandoned or repurposed structures. The field team spoke with the owner of the Yacht Yard, but he did not know of any abandoned structures in the yard or in the area.

# 5 OTTER CREEK INSPECTION

Residents have contacted the Village to express concerns about debris in Otter Creek that they believed could be the result of illicit discharges. Historic records show there are six outfalls between the confluence of the Creek and the Harbor and where it originates at an upstream pool. Only five of these outfalls were located in 2014 when Arcadis performed outfall inventory and inspection in this area. There is a minimal amount of storm sewer infrastructure in the streets in this area; some of the outfalls are likely area drains for properties. Arcadis investigated Otter Creek partly on foot and partly by kayak to inspect known outfalls for dry weather flow, to locate any previously unidentified outfalls, and to look for signs of illicit discharges.

Arcadis field staff began an inspection during low tide (around 8:00 am) on August 21, 2015 with the intent to survey the entire creek for outfalls that may be submerged during high tide. The field staff launched a kayak from the bridge on South Barry Lane and paddled upstream, but quickly found that there was not enough flow at low tide to do so. The field team then attempted to walk upstream, but found themselves sinking deep into the mud. After an unsuccessful attempt to travel upstream, the field team turned around and paddled toward the outlet to the Harbor. Between the South Barry Lane bridge and the Harbor, the field team was able to identify outfall BSB-23, which was trickling. Though the field team was equipped to take a sample, this outfall could not be safely accessed from the water or by walking on the saturated mud and sand.

At Harbor Island Park, the Arcadis field team was advised that mid-tide may be the best time to paddle Otter Creek. At high tide, the bridge is impassable and at low tide there is not enough flow to make the waterway navigable. When the field team returned to the Creek at mid-tide, they were able to reach 911 Soundview Drive which is about <sup>3</sup>/<sub>4</sub> of the way to the upstream pool. By that point, the water levels had again reached low levels that made paddling further impossible. By reaching that location, the field team should have been able to see the three outfalls located in the area: BSB-22, BSB-24, and Vj 60. The outfalls were not visible as the vegetation was very dense. The field team was not able to walk in this area to investigate further without sinking.

Analytical sampling completed in Otter Creek by Arcadis in previous years has been low. However, this year sample results were consistently elevated.

Figure 5 shows the area investigated. A photo log documenting the investigation efforts provided in Appendix C. A map showing the River sampling results is provided as Appendix F.

### **Conclusions and Recommendations**

Though sampling at the bridge on South Barry Lane suggests there may be an illicit discharge in Otter Creek, no distinguishable sources of fecal coliform have been identified. If Otter Creek were to be revisited in the winter, there would be less vegetation, making outfalls more visible and the ground easier to traverse during low tide. There are several homes with septic systems adjacent to Otter Creek. These septic systems should be inspected to confirm the leach fields are functioning properly.



Service Layer Credits: Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AEX, Getmapping, Aerogrid, IGN, IGP, swisstopo, and the GIS User Community

CITY: CLIFTON PARK, NY DIV/GROUP: WTR DB: CMS LD: PIC: PM: KCH TM: PROJECT: VILLAGE OF MAMARONECK IDDE PATH: Path: G:/GISMOD/01547034.0000/0tterCreekFigure.mxd Date Saved: 1/25/2016 1:36:14 PM

# 6 DRAINAGE AREA INVESTIGATIONS

Outfall inventory and inspections completed by Arcadis since 2012 have identified outfalls that flowed during dry weather conditions. This is very typical and is most often associated with groundwater infiltration in the pipes, or historic underground streams that are now conveyed through the sewer system. Most of these outfalls will have some fecal coliform bacteria from background sources, such as wild and domestic animals, but it is important to monitor them to confirm bacteria levels have not increased.

During the 2015 drainage area investigation, Arcadis revisited and sampled outfalls that have not been sampled recently and have historically had a dry weather flow greater than 1 gpm. In addition, several samples collected at the close of the of the 2014 outfall sampling program identified stormwater outfalls with elevated fecal coliform concentrations. These outfalls were resampled in 2015 to determine if the bacteria concentrations were still elevated, or if some of the historically elevated concentrations may have been isolated incidents.

Table 6-1 below presents the results of the 2015 outfall sampling program and compares it with previous sampling events. Appendix B provides a summary of all 2015 water sampling results.

Outfall ID	Previous Sample Results (cfu/100 ml; flow (gpm); date)	2015 Sample Results (cfu/100 ml; flow (gpm); date)		
17 (previously identified as 132)	8,000; 13 gpm; 10/7/2014	1,800; >5 gpm; 10/7/2015		
Vd 51b	1,600; 2 gpm; 10/7/2014	200; ~ 1-2 gpm; 7/16/2015		
Vd 70	3,000; 2 gpm; 9/30/2014	400; 1 gpm; 7/16/2015		
Vj 04	1,400; 93 gpm; 4/21/2014	800; ~ 30-50 gpm; 7/21/2015		
Vg 24	9,000; 1 gpm; 9/30/2014 1,500: -: 10/7/2014	3,700; 1.6 gpm; 7/21/2015 15,000; 3.2 gpm; 8/6/2015		
Vn 1	4,300; 1 gpm; 9/30/2014	700; 1.3 gpm; 7/21/2015		
Vj 58	3,950; 3 gpm; 4/21/2014 1,600; 4 gpm; 9/30/2014	800; 1.5 gpm; 7/21/2015		
Vf 17	3,000; <1 gpm; 9/30/2014	Dry – 7/21/2015 and 10/7/2015		
47	1,200; 2.5 gpm; 10/23/2012	6,000; 0.5 gpm; 10/7/2015		
Vg 42	600; 5-10 gpm; 10/23/2012	300; 7 gpm; 10/7/15		
BSB-11	Not sampled; 8 gpm; 4/2014	Dry – 10/8/2015		
		2,000; <1 gpm; 7/28/2015 2,000; 1 gpm; 8/6/2015		
	34,000; 20 gpm; 3/4/2013	1,900; 1 gpm; 9/2/2015		
26	(Repair made in 2013)	3,900; 2 gpm; 10/7/2015		
Ve 22	900; 1 gpm; 9/30/2014	41,000; ¼ gpm; 10/7/2015		
127		9,800; 1 gpm; 7/16/2015 200; 1 gpm; 7/28/2015		

#### Table 6-1. Previous Outfall Sampling Results Compared to 2015

It is generally not beneficial or economically feasible to track down sources of fecal coliform bacteria that result in a minor pollutant load (flow multiplied by concentration) to a water body. There is often some minor concentration of fecal coliform discharging from storm water outfalls. Resources are better spent focusing on sources with greater pollutant loads. For this investigation, samples with fecal coliform concentrations below 1,000 cfu/100 ml and/or collected from outfalls with flow rates of less than one gpm were not considered to have pollutant loads substantial enough to warrant further investigation at this time. The outfalls that had elevated fecal coliform concentrations are discussed below.

- Outfall 127 This is an outlet to a culvert with a very small drainage area. The first sample had elevated bacteria concentrations, but there was construction occurring upgradient of the culvert the day of sampling. A follow-up sample was collected after the construction was completed and the bacteria concentration was low.
- Outfall 17 (previously 132) Arcadis field staff returned to what was thought to be outfall 132 to collect a sample. The field staff determined that the outfall previously thought to be 132 was actually outfall 17, and

was located on the Town of Harrison side of the Mamaroneck River. This was confirmed by reviewing the outfall description of the previous outfall inspection report, and photos. Outfall 17 was resampled on October 7, 2015. The outfall flow rate was estimated to be greater than 5 gpm and the concentration was 1,800 cfu/100 ml. The Village provided the sample results to the Town of Harrison and recommended that they investigate further to find the source(s).

- Outfall 132 could not be located, it is suspected to be covered by rip rap along the shore. An upgradient
  catchbasin was discovered, and there was no dry weather flow in the catch basin at the time of the
  inspection.
- Outfall Ve 22 This outfall has historically had very low flow, and during the 2015 field investigation the flow
  was less than a quarter of a gallon a minute. However, the fecal coliform concentration of the collected
  sample was high. This outfall was sampled at the end of the 2015 IDDE season and since the overall
  pollutant load was low, additional field investigations were not completed. This outfall will be sampled again
  in 2016, and if bacteria concentrations are high the sewershed will be investigated to locate the source(s) of
  bacteria.
- Outfall 47 This outfall has very low flow. It is located in the vicinity of outfall Vg 24 and was sampled because dry weather flow was observed. The sample collected at the end of the 2015 field investigation had elevated fecal coliform concentrations. This outfall will be sampled again in 2016, and if bacteria concentrations are high the sewershed will be investigated to locate the source(s) of bacteria.

Two of the outfalls were selected for additional sampling and follow-up investigation, which is discussed in detail below.

## 6.1 Outfall Vg 24 Concord Avenue

This outfall was sampled on July 21, 2015. The fecal coliform concentration was 3,700 cfu/100 ml, with a flow of 1.6 gpm. Arcadis field staff began a drainage area investigation by opening manholes and catchbasins upgradient of the outfall, looking for dry weather flow, and sampling flow for fecal coliform concentration. The field team isolated the problem(s) to the sewer downgradient of manhole Vg 33. Manhole Vg 33 had a fecal coliform concentration of 100 cfu/100 ml and sample results from upgradient manholes did not show any concentration of fecal coliform. Sampling concentrations varied downgradient of the isolated area, but the highest sample was >200,000 cfu/100ml at manhole Vg 29. Sample results are shown on Figure 6.

Arcadis coordinated CCTV inspection of the storm sewer with subcontractor Fred Cook Inc. to look for illegal connections, cracks or breaks in the pipe, or signs of bacteria indicative of sewage flow. Arcadis staff added dye to sanitary manholes that either crossed or were in close vicinity of the storm sewers, to determine if sewage was entering the storm sewer from any direct or indirect connections. Televising began at Concord Avenue from manhole Vg 29. Fred Cook Inc. televised from Vg 29 to Vg 29A. The next section was televised was Vg 32 to Vg 33. Between Vg 32 and Vg 33, there were two laterals that enter the east side of the sewer and were both flowing at the time of the inspection. Upstream of these two laterals, the evidence of bacteria along the bottom of the pipe decreased dramatically. CCTV was also completed between Vg 31 and Vg 32, but there were no signs of illicit discharge in this section. Between Vg 31 and Vg 30, there was raccoon scat observed in the sewer.



Service Layer Credits: Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AEX, Getmapping, Aerogrid, IGN, IGP, swisstopo, and the GIS User Community

Based on the sampling results and the CCTV investigation, it was reasonable to ascertain there was an illicit discharge coming from the stormwater building laterals identified between manholes Vg 32 and Vg 33. The Village notified the building owner at that location that additional investigations would need to be conducted at the building.

The building owners hired a plumber to perform a video inspection of their sewer laterals. Arcadis oversaw the video inspection of the building storm and sanitary sewer laterals and inspected the sump pit where the cleanouts are located. There was evidence of toilet paper in the sump pit, which suggests there had previously been a sanitary sewer backup. The covers on both cleanout pipes were tightly secured at the time of the inspection. During the day of inspection, the plumber added a riser to the storm sewer lateral piping to bring the storm sewer lateral out of the sump pit.

The CCTV inspection of the storm lateral showed the pipe was in good condition. The inspection of the sanitary sewer lateral showed heavy root intrusion, and the camera could not pass through the roots to complete the inspection. The building owner subsequently repaired the sanitary sewer building lateral, and Arcadis collected two samples in storm sewer manhole Vg 32, downgradient of the building. The post repair fecal coliform concentrations for the two samples were both 3,000 cfu/100 ml at about 5 gpm. Previous samples from storm sewer manholes downgradient were generally above 10,000 cfu/100 ml and as high as >200,000 cfu/100 ml. The post-repair sample results indicate a considerable reduction in fecal coliform concentrations, but further investigations should be completed in 2016 to uncover the additional source(s).

### 6.2 Outfall 26 - Halstead Ave

The drainage area that drains to outfall 26 was investigated in 2013 and a significant illicit discharge was discovered and eliminated on Union Avenue. Outfall 26 is sampled each year to monitor fecal coliform concentrations, but is often dry during dry weather. When it is flowing, the flow varies between a trickle and 2 gpm. Fecal coliform concentrations have been around 2,000 cfu/100 ml. Racoon scat was previously found in the storm sewer, so some bacteria concentrations are expected.

Arcadis investigated the storm sewer on Halstead Avenue again this year to confirm there are no new illicit discharges. Field staff inspected manholes and catchbains on Halstead Avenue for dry weather flow and visual signs of illicit discharges. Many of the structures were dry, or had flows too low to collect samples. Samples were collected from manholes Vh 6 and Vh 3 on September 2, 2015. Manhole Vh 6 had a fecal coliform concentration of 200 cfu/100 ml and manhole Vh 3 had a fecal coliform concentration of <100 cfu/100 ml. Neither of these manholes had flow, but they both had stagnant water that was collected for the samples. Based on these low results, no additional sampling was completed. Sample results from outfall 26 and the associated drainage structures are shown in Figure 7.

CCTV inspection was completed between manholes Vh 1a and Vh 1, continuing to Vh 2. At manhole Vh 2, the inspection had to be discontinued because a lateral in the storm sewer line protruded too far into the sewer to allow the camera to pass. A water main enters the storm sewer 40 feet upgradient of manhole Vh 1. None of the sections of storm sewer included in this inspection had evidence of bacteria.

The investigation did not uncover a direct illicit discharge that could be corrected. During the CCTV inspections, it was observed that ground water was infiltrating into the storm sewer at the pipe joints, as the flow in the pipe decreased slowly as the pipe moved from the downgradient sections to the upgradient sections of sewer. There was not noticeable infiltration but a slow increase in the amount of flow. The bacteria may be slowly migrating from a small leak in an adjacent sanitary sewer or lateral, or from animal scat in the storm sewer. The pollutant load from this



Service Layer Credits: Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AEX, Getmapping, Aerogrid, IGN, IGP, swisstopo, and the GIS User Community

outfall is not concerning at this time. Arcadis recommends sampling this outfall annually to monitor the fecal coliform concentrations.

# 7 AS-NEEDED ILLICIT DISCHARGE DETECTION AND ELIMINATION ASSISTANCE

Arcadis provided as-needed technical assistance in support of the Village's IDDE program. This included office and field services to investigate potential illicit discharges identified by the Village, concerned citizens, or environmental organizations, as well as assisting the Village with correspondences to regulatory agencies. Each component of this as-needed assistance is described below.

# 7.1 Responding to Observations of Citizens and Representatives

Arcadis staff investigated several concerns expressed by Village residents and representatives. The Village keeps an open line of communication with residents and as suspected sources of illicit discharge are reported, the Village instructs Arcadis to conduct CCTV inspections, water sampling, and field investigation as necessary. These asneeded field investigations are described below.

### 7.1.1 River Sampling – Surface Foam Observed

At the Village's request, Arcadis collected samples from the Mamaroneck and Sheldrake Rivers due to concerns from area residents regarding foam floating on the surface of the River in several locations. This surface foam on the Sheldrake and Mamaroneck Rivers has been observed and photographed by Arcadis, the Village residents, and Village staff. The origin and composition of the foam were not known, so the Village directed Arcadis to sample the foam and to have it analyzed for common pollutants. A detailed accounting of these sampling events is provided as Appendix D.

Arcadis collected samples of the actual foam and surface water on two occasions, April 16, 2015 and May 29, 2015. Samples were collected and analyzed for fecal coliform, oil & grease, and anionic surfactants. Fecal coliform is present in high concentrations in wastewater and anionic surfactants are present in high concentrations in detergents and foaming agents. The standard test for surfactants is methylene blue active substances assay (MBAS).

The concentrations of oil and grease and for surfactants for both sampling events were very low. The physical appearance for both events matched the appearance of naturally occurring foam presented in illicit discharge guidance documents. There could be non-point sources that are aiding in the process. For example, non-ionic surfactants are used as a wetting agent for herbicides and pesticides. It is feasible that runoff from application of these products could be contributing to a decrease in the surface tension of the water and aiding in the formation of small bubbles that constitute the foam.

The fecal coliform concentration for the April event was low, but elevated during the May event. Additional sampling completed by Arcadis in the Sheldrake and Mamaroneck rivers did not uncover any illicit discharges besides the ones discussed in this document. In addition, the results of 2015 sampling completed by Save the Sound, do not show a point source of pollution in the Village. In fact, the geometric mean of enterococcus for samples taken upstream of the Village was the same as the concentrations in the river as it enters the Mamaroneck Harbor.

### 7.1.2 River Sampling – Surface Film Observed

Arcadis responded to a resident's report of a sheen along the edge of the Mamaroneck River, near the Jefferson Avenue bridge. Two samples were collected and sent to Envirotest Laboratory for oil and grease analysis (Analytical Method 1664A). The sample results were <5.32 mg/l and <5.43 mg/l which are very low and below the labs reporting

limit. A reporting limit is the laboratory's limit of detection for the target analyst in a specific sample after adjustments have been made for dilutions or percent moisture.

There is a wholesale meat company located within 50-feet from the River shore, and where the sheen was seen. This company has received notification from the Village in the past regarding cleaning equipment on the property. The appearance of the sheen was not consistent with oil which typically has color. The sheen observed by the Village resident was more of a gray film. The field team walked the area to look for sources, including the meat company grounds, but a source was not identified.

It is recommended that the Village discuss these observations with the wholesale meat company and ask them about their best management practices. The water surface should be monitored in this location in the future to determine if it was an isolated incident or a recurring problem, and to help determine the source.

### 7.1.3 Gasoline Odor Investigation Near Creek Road

Arcadis staff visited the Vj 61 outfall drainage area at the request of the Village in response to a Village resident's detection of a gasoline odor at the outfall. Figure 8 shows the location of outfall Vj 61, to the east of Beaver Swamp Brook. A preliminary investigation of the drainage area was completed on July 16<sup>th</sup>, 2015 and samples were collected and sent to the lab for analysis on July 21<sup>st</sup>, 2015.

Vj 61 is a 12-inch diameter reinforced concrete pipe. During the first site visit, Outfall Vj 61 was wet, but no dry weather flow. There were no odors; no evidence of oil, grease, or petroleum; and no dead vegetation. All of the storm sewer structures within the Vj 61 sewershed were also inspected. This includes a total of seven catch basins and one storm manhole. Again, no evidence of oil or grease was found and no unusual smells were detected. A nearby sanitary sewer manhole was also inspected to determine if the odor could be coming from the adjacent sanitary sewer.

The field team returned on July 21<sup>st</sup> prepared for sample collection. When the samples were collected, no unusual scent or signs of oil or grease were observed by Arcadis staff. Arcadis staff also investigated a wooded area adjacent to the outfall and found no evidence of oil dumping. At the time the sample was collected it was flowing less than one gpm. There was a stagnant puddle less than one inch deep immediately outside of the outfall. It should also be noted that there was construction work being completed on Creek Road near the intersection of the Parkway and Creek Road at the time of the investigation. This is being included in this summary as a potential source for the odors originally detected.

Samples were analysed for volatile organic compounds (VOCs) (EPA method 624) and Oil/Grease (EPA Method 1664A) analysis by Envirotest Laboratory. The results did not show any evidence of gasoline, oil or grease; all parameters tested were non-detect. Based on our investigation we did not find evidence of a spill or dumping at this outfall. Photos of the investigation are included as Appendix E. Laboratory results are provided in Appendix B.



Service Layer Credits: Source: Esri, Digital Globe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AEX, Getmapping, Aerogrid, IGN, IGP, swisstopo, and the GIS User Community

CITY: CLIFTON PARK, NY DIV/GROUP: WTR DB: CMS LD: PIC: PM: KCH TM: PROJECT: VILLAGE OF MAMARONECK IDDE PATH: Path: G:/GISMOD/01547034.0000/Outfail\_Vj61\_GasolineOdor.mxd Date Saved: 1/26/2016 11:14:55 AM

### 7.1.4 Storm Sewer Inspection – Stanley Avenue

On September 24, 2015 Arcadis responded to a call from the Village regarding sewage odor coming from catch basins on Stanley Ave near Mount Pleasant Ave. The Village had received many calls from residents expressing concern over the strong odor for several days. There had been a sewer backup in the sanitary sewer in the vicinity of Stanley Ave, but it was resolved.

Arcadis coordinated a video inspection of the storm sewer on Stanley Avenue, with Fred Cook Jr., Inc. The video inspection was completed on Stanley Avenue between Maple Avenue and Mount Pleasant Avenue. The bottom of the storm sewer had gray bacteria, which is indicative of sewage flow, but no broken or leaking pipes were observed. Upon further investigation the source of the sewage flow is believed to have been pumped to the ground surface from a home near the intersection of Stanley and Maple Avenue. The driveway and sidewalk was wet leading to a catchbasin, sewage odors were detected, and flies were present around the wet area of the driveway and sidewalk. Also, the bacteria in the storm sewer ended at the catchbasin where the flow was discharged.

When we approached the house a man came to the door and was questioned, but he did not admit to any wrongdoing. The storm sewer was flushed by the Village and this dramatically reduced the odors. The Village returned to the location several times after the event and did not see any evidence that the problem was still occurring.

# 7.2 River Sampling and DNA Testing

### 7.2.1 Fecal Coliform Samples

Water samples were collected at various locations on the Mamaroneck River, the Sheldrake River, the Beaver Swamp Brook, and Otter Creek. Samples were analyzed for fecal coliform bacteria. Perhaps the most important observation from the results of this sampling effort is that the results show there are elevated concentrations of fecal coliform in the Sheldrake River, Mamaroneck River, and Beaver Swamp Brook near the Village of Mamaroneck border, which indicates the waters are receiving fecal coliform bacteria from upgradient municipalities.

Furthermore, the sampling results from the Mamaroneck and Sheldrake Rivers and Beaver Swamp Brook did not show a significant increase in fecal coliform concentrations from the Village borders to the confluence with the harbor. This shows there are not significant sources of fecal coliform pollution discharging to the waterbodies from the Village, which has also been confirmed through the completion of outfall sampling. Some outfalls did have elevated concentrations, and further investigation is recommended, but the flow is so low that there is a low pollutant load. In addition, as with any municipality, continuing to monitor the waterbodies and outfalls is recommended to discover new illicit discharges so they can be addressed.

Otter Creek, which originates in the Village, showed elevated fecal coliform concentrations this year, so further investigations are recommended for 2016.

### 7.2.2 DNA Testing

Deoxyribonucleic acid (DNA) samples were also collected to determine if the elevated fecal coliform concentrations were from human or animal sources. DNA testing is a sensitive and specific test that can be used to determine the

presence of fecal or sewage contamination. The most promising to date has been the use of Polymerase Chain Reaction (PCR) technology, which can be used to test for total and human Bacteroides, which have proven to be highly specific and sensitive indicators for wastewater contamination. PCR is used to selectively target specific genes and amplify trace quantities from polluted waters.

Bacteroides are bacteria that are present in very large concentrations in feces and are highly specific for fecal contamination. They are anaerobic, so they cannot survive in an oxygen environment. Human Bacteroides is largely specific for human sources, although there is some cross reactivity with dog and pig feces DNA.

There are numerous PCR based assays available to characterize human fecal pollution in ambient waters. An assay is an investigative procedure for qualitatively measuring the presence or amount of a target entity, in this case DNA. Each assay employs distinct DNA or Ribonucleic acid (RNA) molecules and many target different genes and microorganisms leading to potential variations in assay performance. Many of the reported human-associated PCR-based assays target 16S rRNA genes from the Bacteroidales order.

The samples were analysed by Microbial Insight. They use three human Bacteroides assays which include, HF183, H-EPA1, and H-EPA2. In addition to human and general Bacteroides analysis, the laboratory also analyzed the samples for dog, Canadian goose, and sea gull Bacteroides.

Two samples were collected with a duplicate sample. One set was collected in the Mamaroneck River at the Jefferson Bridge and other set of samples was collected at the confluence of the Mamaroneck and Sheldrake Rivers. The predominant component in all four samples was Human Bacteroides. Dog, Canadian goose, and sea gull were not prevalent in large quantities in any of the samples.

Sample results are included as Appendix B and Appendix G.

### 7.3 Sanitary Sewer Lateral Connection - Grout Pilot Program

The 2015 West Basin Pump Station Drainage Area Inflow and Infiltration Report recommended the Village grout approximately 400 lateral connections to the mainline sewer in the in the West Basin Pump Station service area. A test and grout sealing pilot program was completed in the Village in the summer of 2015 to gain valuable information to streamline the work to be completed in 2016.

Proposals were reviewed from two firms, and Heitkamp, Inc. was selected as the contractor to perform the grout sealing. The pilot study was conducted on Rushmore Avenue between Claflin Avenue and Bleeker Avenue during the week of September 21<sup>st</sup>, 2015. Arcadis staff met Heitkamp staff in the Village the first morning and successfully completed all required field and calibration test on the grouting equipment and began the video inspection of the sewer. There are two types of pipe on Rushmore Avenue, a 16-inch cast iron pipe and a 10-inch cast iron pipe that has been lined with a cured-in-place pipe.

Several problems arose while the contractor was attempting to complete lateral grouting. The main issue was heavy tuberculation along the main trunk. Tuberculation is localized corrosion resulting in knob-like mounds on the inside of the pipe, which make the pipe out of round and reduces the internal diameter. An example of the tuberculation observed during the grouting pilot program is shown in Photo 1 below. The 16-inch cast iron pipe was found to have

heavy tuberculation which impeded mobility of the grouting packer through the pipe. There were additional obstructions that caused the packer to get stuck in the main line. An example of a pipe obstruction is shown in Photo



Photo 1 - Example of tuberculation with the 16-inch cast iron pipe



#### Photo 2 - Example of obstruction

2, above. The 10-inch cast iron line had been lined previously with a cured-in place pipe. However, this pipe was also corroded with tuberculate, so the same problems applied when attempting pass the packer through the pipe to grout the laterals.

Unfortunately since these problems prohibited the contractor from completing the work, the pilot was cut short after grouting only three laterals. An example of a lateral connection after grouting is shown in Photo 3. The pressure grouting effectively stopped the water infiltrating at the connection.





The pilot provided valuable information for the Village for the full scale program. Attempting to grout sewer lateral pipe connections in a cast iron pipe for the full scale program is not recommended. Cast iron pipe is typically not as common a construction material in older sewer systems as vitrified clay pipes. Based on a review of the historic Village drawings, most of the pipes in the area planned to be grouted are vitrified clay pipe. Pressure testing and grouting vitrified clay pipe should not present a problem unless the pipe has structural defects or offset joints. One alternative to quickly confirm pipe material and condition would be to use a sewer zoom camera to inspect the pipe segments from the manhole surface prior to developing the final plan for pipe segments to will be grouted. One other potential problem is with pipes that have been previously lined with cured-in place liner. If the holes for the laterals were not trimmed back properly the grouting contractor may need to spend some time making the pipe condition right for air testing and grout sealing.

A CD containing the CCTV logs and videos of the pilot project are provided as Appendix H.

### 7.4 Septic System Analysis

The Village of Mamaroneck currently has 76 septic systems; several in areas that have public sewers. Section 873.727 of the Westchester County Sewer Code, states that habitable buildings may be required to connect to the public sewer system if the public sewer is within 100 feet of the property line of the habitable building. Arcadis performed a GIS desktop analysis to determine the distance of all known properties with septic systems to the public sewer. According to the data currently available in GIS, there are 76 septic tanks in the Village, 23 or fewer are within

100 feet of a public sewer. A map of the septic tanks within the Village boundary and a table with their distances from the sanitary sewer are included as Appendix I.

# 7.5 EPA Quarterly Reports

At the request of the Village, Arcadis assisted in the preparation of quarterly reports to be submitted to the EPA. These quarterly reports are required by the EPA Administrative Order CWA-02-2011-3022. The reports include a summary of work completed and work planned for the future to address the Administrative Order. The reports submitted in 2015 summarize work completed under Phase 5 of the Village of Mamaroneck IDDE program.

# **APPENDIX A**

2015 Outfall Inspection Forms



# **OUTFALL INSPECTION PROGRAM**

STRUCTURE							
Structure ID	52	Diameter (in)		24		Outfall Typ	be
Material	RCP	Waterbody		Sheldrake Rive	er	Culvert	
Shape	Culvert	Submerged ir	Water	No			
Quantity	Single	Submerged i	n Sediment	No			
INSPECTION EVENT							
Inspector	JL, MS	Air Temperature (F)		85	Photo Numbers		52, 52 (1)
Date	8/13/2015	Rainfall, Past 24 hrs (in)		0			
Time	11:30 am	Rainfall, Past 48 hrs (in)	. [	1			
INSPECTION EVENTCO	MMENTS		ŗ				
ASSESSMENT		FLOW			FIELD PARA	METERS	
Structural Condition	Good	Flow Description	. No Flo	w	Sample Temper	ature (F)	
Operational Condition	Good	Flow (gpm)			Sample pH		<u> </u>
Illicit Discharge Potential	Unlikely	Determination:	·		Sample Ammon	ia (mg/mL)	
DISCHARGE CHARACT	ERISTICS						
Color		Turbidity			Flow Line		Yes
Color Strength		Floatables (Suds)			Abnormal Vega	atation	
Odor Type		Floatables (Sewage)	· _		Bacteria Growt	h	
Odor Severity		Floatables (Oil)			[		
POOL QUALITY POOL QUALITY COMMENTS					ENTS		
Color		Suds					
Color Strength		Oil Sheen					
Odor		Algae					
Odor Severity					ļ		

#### ✓ Display Multiple Image



# **OUTFALL INSPECTION PROGRAM**

STRUCTURE						
Structure ID	57	Diameter (in)		Outfall Ty	ре	
Material	[	Waterbody	Sheldrake	NA		
Shape		Submerged in Water	r			
Quantity		Submerged in Sedin	ment			
INSPECTION EVENT						
Inspector	JL, MS	Air Temperature (F)	85	Photo Numbers	57	
Date	8/13/2015	Rainfall, Past 24 hrs (in)	0			
Time	12:00 pm	Rainfall, Past 48 hrs (in)	1			
INSPECTION EVENTCO	MMENTS					
Unable to locate; No upg	radient MH/CB					
ASSESSMENT		FLOW		FIELD PARAMETERS		
Structural Condition		Flow Description		Sample Temperature (F)		
Operational Condition		Flow (gpm)		Sample pH		
Illicit Discharge Potential		Determination:		Sample Ammonia (mg/mL)		
DISCHARGE CHARACT	ERISTICS					
Color		Turbidity		Flow Line		
Color Strength		Floatables (Suds)		Abnormal Vegatation		
Odor Type		Floatables (Sewage)		Bacteria Growth		
Odor Severity		Floatables (Oil)		Ĩ		
POOL QUALITY POOL QUALITY COMMENTS						
Color		Suds				
Color Strength		Oil Sheen				
Odor		Algae				
Odor Severity				ļ		

### ✓ Display Multiple Image


STRUCTURE							
Structure ID	Vk 4a	Diameter (in)		18		Outfall Ty	ре
Material	RCP	Waterbody		Mamaroneck Sound		Culvert	
Shape	Circular	Submerged in Water		No			
Quantity	Single	Submerged in Se	ediment	No			
INSPECTION EVENT							
Inspector	JL, MS	Air Temperature (F)		75	Photo Numbers		Vk 4a, Vk 4a (1)
Date	8/13/2015	Rainfall, Past 24 hrs (in)		0		r	
Time	7:00 am	Rainfall, Past 48 hrs (in)		1			
INSPECTION EVENTCO	MMENTS		r				
ASSESSMENT		FLOW			FIELD PARAN	IETERS	
Structural Condition	Good	Flow Description	Trickle		Sample Tempera	ature (F)	
Operational Condition	Good	Flow (gpm)	<1 gpm		Sample pH		
Illicit Discharge Potential	Unlikely	Determination:	eye		Sample Ammoni	a (mg/mL)	
DISCHARGE CHARACT	ERISTICS						
Color	Clear	Turbidity			Flow Line		Yes
Color Strength	-	Floatables (Suds)			Abnormal Vega	tation	No
Odor Type	None	Floatables (Sewage)			Bacteria Growth	ı	No
Odor Severity	ŀ	Floatables (Oil)					
POOL QUALITY					POOL QUALI	ТҮ СОММ	ENTS
Color	Clear	Suds	No		Muddy		
Color Strength	ŀ	Oil Sheen	No				
Odor	None	Algae	No				
Odor Severity	ŀ						





STRUCTURE									
Structure ID	Vk 10e	Diameter (in)			Outfall Type				
Material		Waterbody	Mamaroneck So	ound	System Outfall				
Shape		Submerged in Water							
Quantity		Submerged in Sedime	ent						
INSPECTION EVENT									
Inspector	JL, MS	Air Temperature (F)	80	Photo Numbers	Vk 10e, Vk 10e (1)				
Date	8/13/2015	Rainfall, Past 24 hrs (in)	0						
Time	10:30 am	Rainfall, Past 48 hrs (in)	1						
INSPECTION EVENTCO	MMENTS	k.							
Private beach, fenced in property, no access to outfall. Investigated upgradient catchbasin - submerged with debris and sediment. Unlikely illicit discharge potential. Likely to have poor operating condition.									
ASSESSMENT		FLOW		FIELD PARAME	TERS				
Structural Condition		Flow Description		Sample Temperatu	re (F)				
Operational Condition		Flow (gpm)		Sample pH					
Illicit Discharge Potential		Determination:		Sample Ammonia (	img/mL)				
DISCHARGE CHARACT	ERISTICS								
Color		Turbidity		Flow Line					
Color Strength		Floatables (Suds)		Abnormal Vegatat	ion				
Odor Type		Floatables (Sewage)		Bacteria Growth					
Odor Severity		Floatables (Oil)							
POOL QUALITY					Y COMMENTS				
Color		Suds							
Color Strength		Oil Sheen		1					
Odor		Algae							
Odor Severity				ļ					



STRUCTURE				
Structure ID	Vk 13a	Diameter (in)		Outfall Type
Material	[	Waterbody	Mamaroneck Sound	System Outfall
Shape		Submerged in Water		
Quantity		Submerged in Sedimen	t	
INSPECTION EVENT				
Inspector	JL, MS	Air Temperature (F)	80 Photo Num	nbers Vk 13a, Vk 13a (1)
Date	8/13/2015	Rainfall, Past 24 hrs (in)	0	
Time	10:45 am	Rainfall, Past 48 hrs (in)	1	
INSPECTION EVENTCO	MMENTS	k.		
Could not access outfall.	Upgradient manhole subm	nerged. No flow. No odor. Unlikel	y potential of illicit discharge.	
ASSESSMENT		FLOW	FIELD P/	ARAMETERS
Structural Condition		Flow Description	Sample Te	emperature (F)
Operational Condition		Flow (gpm)	Sample pH	I
Illicit Discharge Potential		Determination:	Sample Ar	nmonia (mg/mL)
DISCHARGE CHARACT	ERISTICS			
Color		Turbidity	Flow Line	
Color Strength		Floatables (Suds)	Abnormal	Vegatation
Odor Type		Floatables (Sewage)	Bacteria (	Growth
Odor Severity		Floatables (Oil)		
POOL QUALITY			POOLQ	UALITY COMMENTS
Color		Suds		
Color Strength		Oil Sheen		
Odor		Algae		
Odor Severity				



STRUCTURE								
Structure ID	63		Diameter (in)		12		Outfall Typ	be
Material	Corrugated Metal		Waterbody Mamaroneck F		Mamaroneck R	River		Dutfall
Shape	Circular		Submerged in Water		Partially			
Quantity	Single		Submerged in Se	ediment No				
INSPECTION EVENT								
Inspector	JL, MS	Air Tempe	rature (F)		85	Photo Numbers.		63, 63 (1), 63 (2), 63
Date	8/13/2015	Rainfall, P	ast 24 hrs (in)		0			
Time	11:00 am	Rainfall, P	ast 48 hrs (in)		1			
INSPECTION EVENTCO	MMENTS			L				
Outfall has drilled holes along piping to allow discharge to infiltrate into ground. Discharges into a puddle in a backyard. No apparent body of water.								
ASSESSMENT		FLOW				FIELD PARAM	METERS	
Structural Condition	Good	Flow Des	cription	No Flow		Sample Temperature (F)		
Operational Condition	Good	Flow (gpr	n)	í —		Sample pH		
Illicit Discharge Potential	Unlikely	Determina	ation:	eye		Sample Ammoni	a (mg/mL)	
DISCHARGE CHARACTI	ERISTICS							ĺ
Color		Turbidity				Flow Line		No
Color Strength		Floatable	s (Suds)			Abnormal Vega	tation	No
Odor Type		Floatable	s (Sewage)			Bacteria Growth	יייייי ו	No
Odor Severity		Floatable	s (Oil)					
POOL QUALITY						POOL QUALI	ТҮ СОММІ	ENTS
Color		Suds						
Color Strength		Oil Shee	n					
Odor		Algae						
Odor Severity						I		



STRUCTURE									
Structure ID	64		Diameter (in)		12		Outfall Typ	De	
Material	RCP		Waterbody		Mamaroneck R	System Outfall		Dutfall	
Shape	Circular		Submerged in Water No						
Quantity	Single		Submerged in Sediment No						
INSPECTION EVENT									
Inspector	JL, MS	Air Temper	ature (F)		85	Photo Numbers.		64, 64 (1), 64 (2)	
Date	8/13/2015	Rainfall, Pa	st 24 hrs (in)		0				
Time	12:30 pm	Rainfall, Pa	st 48 hrs (in)		1				
INSPECTION EVENTCO	MMENTS		,						
No visible outfall present. Proposed location is higher elevation than the catchbasin. Investigated upgradient catchbasin. Outfall does not appear to be submerged in water - no flow. Found another catchbasin - marked on map.									
ASSESSMENT		FLOW				FIELD PARAM	IETERS		
Structural Condition		Flow Desc	ription			Sample Tempera	ature (F)		
Operational Condition		Flow (gpm	)			Sample pH			
Illicit Discharge Potential		Determina	tion:	İ –		Sample Ammoni	a (mg/mL)		
DISCHARGE CHARACT	ERISTICS								
Color		Turbidity				Flow Line			
Color Strength		Floatables	(Suds)			Abnormal Vega	tation		
Odor Type		Floatables	(Sewage)			Bacteria Growth	۱		
Odor Severity		Floatables	(Oil)						
POOL QUALITY						POOL QUALI		ENTS	
Color		Suds							
Color Strength		Oil Sheer	۱						
Odor		Algae							
Odor Severity						1			





STRUCTURE						
Structure ID	71	Diameter (in)		12		Outfall Type
Material	Corrugated Metal	Waterbody		Mamaroneck S	ound	System Outfall
Shape	Circular	Submerged in Wa	Submerged in Water			
Quantity	Single	Submerged in Se	diment	Partially		
INSPECTION EVENT						
Inspector	JL, MS	Air Temperature (F)		75	Photo Numbers.	71, 71 (1)
Date	8/13/2015	Rainfall, Past 24 hrs (in)		0		
Time	8:00 am	Rainfall, Past 48 hrs (in)		1		
INSPECTION EVENTCO	MMENTS					
ASSESSMENT		FLOW			FIELD PARAM	METERS
Structural Condition	Poor	Flow Description	No flow	,	Sample Temper	ature (F)
Operational Condition	Poor	Flow (gpm)	í —		Sample pH	
Illicit Discharge Potential	Potential	Determination:	eye		Sample Ammon	ia (mg/mL)
DISCHARGE CHARACT	ERISTICS					
Color		Turbidity			Flow Line	
Color Strength		Floatables (Suds)			Abnormal Vega	atation
Odor Type		Floatables (Sewage)			Bacteria Growt	h
Odor Severity		Floatables (Oil)			ĺ	
POOL QUALITY					POOL QUAL	ITY COMMENTS
Color		Suds			Algae growth	on flowline
Color Strength		Oil Sheen				
Odor		Algae			1	
Odor Severity					ļ	



STRUCTURE									
Structure ID	78	Diameter (in)	18	Outfall Type					
Material	RCP	Waterbody	Mamaroneck Sound	System Outfall					
Shape	Circular	Submerged in Water	No						
Quantity	Single	Submerged in Sediment	No						
INSPECTION EVENT									
Inspector	JL, MS	Air Temperature (F)	80 Photo Numbe	ers 78, 78 (1), 78 (2), 78					
Date	8/13/2015	Rainfall, Past 24 hrs (in)	0						
Time	10:00 am	Rainfall, Past 48 hrs (in)	1						
INSPECTION EVENTCO	MMENTS	r							
Resident indicates that outfall exists along the wall. No evidence of outfall - could be covered by sand. Upgradient CB has no odor and is unlikely to be illicit discharge. No flow, pipe visible and not submerged in CB.									
ASSESSMENT		FLOW	FIELD PAR	AMETERS					
Structural Condition		Flow Description	Sample Tem	perature (F)					
Operational Condition		Flow (gpm)	Sample pH						
Illicit Discharge Potential		Determination:	Sample Amm	nonia (mg/mL)					
DISCHARGE CHARACT	ERISTICS								
Color		Turbidity	Flow Line						
Color Strength		Floatables (Suds)	Abnormal V	egatation					
Odor Type		Floatables (Sewage)	Bacteria Gro	owth					
Odor Severity		Floatables (Oil)							
POOL QUALITY			POOL QU	ALITY COMMENTS					
Color		Suds							
Color Strength		Oil Sheen							
Odor		Algae							
Odor Severity									









STRUCTURE								
Structure ID	160	Diameter (in)		Outfall Ty	pe			
Material	Corrugated Metal	Waterbody	Mamaroneck S	System Outfall				
Shape		Submerged in Wa	Submerged in Water					
Quantity		Submerged in Se	diment					
INSPECTION EVENT								
Inspector	JL, MS	Air Temperature (F)	80	Photo Numbers	160, 160 (1)			
Date	8/13/2015	Rainfall, Past 24 hrs (in)	0					
Time	12:00 pm	Rainfall, Past 48 hrs (in)	1					
INSPECTION EVENTCO	MMENTS							
No access to outfall, upgradient manhole has no odor and shows no sign of illicit discharge. Outfall slightly upgradient with dirt and leaves but is not submerged. No flow.								
ASSESSMENT		FLOW		FIELD PARAMETERS				
Structural Condition		Flow Description		Sample Temperature (F)				
Operational Condition		Flow (gpm)		Sample pH				
Illicit Discharge Potential		Determination:		Sample Ammonia (mg/mL)				
DISCHARGE CHARACTE	ERISTICS							
Color		Turbidity		Flow Line				
Color Strength		Floatables (Suds)		Abnormal Vegatation				
Odor Type		Floatables (Sewage)		Bacteria Growth				
Odor Severity		Floatables (Oil)						
POOL QUALITY				POOL QUALITY COMM	ENTS			
Color		Suds						
Color Strength		Oil Sheen						
Odor		Algae						
Odor Severity				1				





STRUCTURE							
Structure ID	VI 1	Diameter (in)	]	36		Outfall Typ	De
Material	RCP	Waterbody	]	Sheldrake Rive	r	System (	Dutfall
Shape	Circular	Submerged in Wa	Submerged in Water No				
Quantity	Single	Submerged in Se	Submerged in Sediment No				
INSPECTION EVENT							
Inspector	JL	Air Temperature (F)		85	Photo Numbers.		VI 1, VI 1 (1), VI 1 (2)
Date	8/13/2015	Rainfall, Past 24 hrs (in)		0			
Time	11:30 am	Rainfall, Past 48 hrs (in)		1			
INSPECTION EVENTCO	MMENTS		L				
		FLOW					
Structural Condition	Good	Flow Description	No flow		Sample Temper	ature (F)	
Operational Condition	Good	Flow (apm)			Sample nH		
Illicit Discharge Potential	Unlikely	Determination:	eye		Sample Ammoni	ia (mg/mL)	
DISCHARGE CHARACT	ERISTICS		,				,
Color		Turbidity			Flow Line		Yes
Color Strength		Floatables (Suds)	í —		Abnormal Vega	atation	No
Odor Type		Floatables (Sewage)	í —		Bacteria Growt	h	No
Odor Severity		Floatables (Oil)	<u> </u>				,
POOL QUALITY					POOL QUAL	ІТҮ СОММІ	ENTS
Color	Clear	Suds	None				
Color Strength	NA	Oil Sheen	Yes, ve	ery little	1		
Odor	none	Algae	None				
Odor Severity	NA				1		







STRUCTURE				
Structure ID	VI 1a	Diameter (in)		Outfall Type
Material		Waterbody	Mamaroneck Sound	System Outfall
Shape		Submerged in Water		
Quantity		Submerged in Sediment		
INSPECTION EVENT				
Inspector	JL, MS	Air Temperature (F)	80 Photo Numbers	s VI 1a
Date	8/13/2015	Rainfall, Past 24 hrs (in)	0	
Time	9:00 am	Rainfall, Past 48 hrs (in)	1	
INSPECTION EVENTCO	MMENTS			
Outfall on private beach - discharge unlikely.	unable to visit. Upgradier	nt catchbasin (4' x 12') part of large	system. No odor or smell comino	g from catchbasin. Illicit
ASSESSMENT	-	FLOW	FIELD PARA	METERS
Structural Condition		Flow Description	Sample Tempe	erature (F)
Operational Condition		Flow (gpm)	Sample pH	
Illicit Discharge Potential		Determination:	Sample Ammo	nia (mg/mL)
DISCHARGE CHARACT	ERISTICS			
Color		Turbidity	Flow Line	
Color Strength		Floatables (Suds)	Abnormal Veg	atation
Odor Type		Floatables (Sewage)	Bacteria Grow	rth
Odor Severity		Floatables (Oil)		
POOL QUALITY			POOL QUA	LITY COMMENTS
Color		Suds		
Color Strength		Oil Sheen		
Odor		Algae		
Odor Severity				



# **APPENDIX B**

2015 Laboratory Results



# ARCADIS Design & Consultancy for natural and built assets

#### Village of Mamaroneck Arcadis 2015 Sampling Results Outfalls, Manholes, Storm Drainage Structures, Streams

		Collection								
Client Sample ID	Sample Type	Date	Analysis Date	Analyte	Result	Unit	Sampling Event Notes	Flag	High Limit	Low Limit
Columbus Park	Stream	4/15/2015	4/16/2015	HEM	<5.21	mg/L	River Foam Sampling		5.21	5.21
Columbus Park	Stream	4/15/2015	4/16/2015	SGT-HEM	<5.21	mg/L	River Foam Sampling		5.21	5.21
Columbus Park	Stream	4/15/2015	4/16/2015	MBAS	0	mg/l LAS MW	River Foam Sampling		0.1	0.1
Columbus Park	Stream	4/15/2015	4/15/2015	Coliform, Fecal	130	CFU/100mL	River Foam Sampling		10	10
N Berry Bridge	Stream	4/15/2015	4/16/2015	HEM	< 5.00	mg/L	River Foam Sampling		5	5.21
N Berry Bridge	Stream	4/15/2015	4/16/2015	SGT-HEM	< 5.00	mg/L	River Foam Sampling		5	5.21
N Berry Bridge	Stream	4/15/2015	4/16/2015	MBAS	< 0.100	mg/l LAS MW	River Foam Sampling		0.1	0.1
N Berry Bridge	Stream	4/15/2015	4/15/2015	Coliform, Fecal	190	CFU/100mL	River Foam Sampling		10	10
SW-MAM-Halstead-S-2015-05-29	Stream	5/29/2015	5/29/2015	MBAS	0	mg/L	River Foam Sampling		0.1	0.1
SW-MAM-Halstead-S-2015-05-29	Stream	5/29/2015	5/29/2015	Coliform, Fecal	1,200	CFU/100mL	River Foam Sampling		100	100
Downstream HS	Stream	7/21/2015	7/21/2015	Coliform, Fecal	1,000	CFU/100mL	High School Investigation		100	100
Downstream HS 2	Stream	7/21/2015	7/21/2015	Coliform, Fecal	1,900	CFU/100mL	High School Investigation		100	100
Upstream HS	Stream	7/21/2015	7/21/2015	Coliform, Fecal	700	CFU/100mL	High School Investigation		100	100
Upstream HS 2	Stream	7/21/2015	7/21/2015	Coliform, Fecal	500	CFU/100mL	High School Investigation		100	100
US HS	Stream	7/28/2015	7/28/2015	Coliform, Fecal	2,900	CFU/100mL	High School Investigation		100	100
DS HS	Stream	7/28/2015	7/28/2015	Coliform, Fecal	1,500	CFU/100mL	High School Investigation		100	100
Outfall HS (BSB-03)	Outfall	7/28/2015	7/28/2015	Coliform, Fecal	1,200	CFU/100mL	High School Investigation		100	100
DPW	Stream	7/28/2015	7/28/2015	Coliform, Fecal	5,000	CFU/100mL	High School Investigation		100	100
DPW	Stream	8/6/2015	8/6/2015	Coliform, Fecal	6,500	CFU/100mL	High School Investigation		100	100
DPW Enterbrook	Stream	8/6/2015	8/6/2015	Coliform, Fecal	7,300	CFU/100mL	High School Investigation		100	100
MH Brook	Manhole	8/6/2015	8/6/2015	Coliform, Fecal	<100	CFU/100mL	High School Investigation		100	100
VJ 61	Outfall	7/21/2015	7/21/2015	1,1,1-Trichloroethane	<1.00	ug/L	Gasoline Odor Investigation		1	0.16
VJ 61	Outfall	7/21/2015	7/21/2015	1,1,2,2-Tetrachloroethane	<1.00	ug/L	Gasoline Odor Investigation		1	0.16
VJ 61	Outfall	7/21/2015	7/21/2015	1,1,2-Trichloroethane	<1.00	ug/L	Gasoline Odor Investigation		1	0.09
VJ 61	Outfall	7/21/2015	7/21/2015	1,1-Dichloroethane	<1.00	ug/L	Gasoline Odor Investigation		1	0.12
VJ 61	Outfall	7/21/2015	7/21/2015	1,1-Dichloroethene	<1.00	ug/L	Gasoline Odor Investigation		1	0.18
VJ 61	Outfall	7/21/2015	7/21/2015	1,2-Dichloroethane	<1.00	ug/L	Gasoline Odor Investigation		1	0.11
VJ 61	Outfall	7/21/2015	7/21/2015	1,2-Dichloropropane	<1.00	ug/L	Gasoline Odor Investigation		1	0.19
VJ 61	Outfall	7/21/2015	7/21/2015	2-Chloroethyl vinyl ether	<1.00	ug/L	Gasoline Odor Investigation		1	0.14
VJ 61	Outfall	7/21/2015	7/21/2015	Acrolein	<2.00	ug/L	Gasoline Odor Investigation		2	0.49
VJ 61	Outfall	7/21/2015	7/21/2015	Acrylonitrile	<1.00	ug/L	Gasoline Odor Investigation		1	0.16
VJ 61	Outfall	7/21/2015	7/21/2015	1,2-Dichlorobenzene	<1.00	ug/L	Gasoline Odor Investigation		1	0.13
VJ 61	Outfall	7/21/2015	7/21/2015	1,3-Dichlorobenzene	<1.00	ug/L	Gasoline Odor Investigation		1	0.13
VJ 61	Outfall	7/21/2015	7/21/2015	1,4-Dichlorobenzene	<1.00	ug/L	Gasoline Odor Investigation		1	0.12
VJ 61	Outfall	7/21/2015	7/21/2015	Benzene	<1.00	ug/L	Gasoline Odor Investigation		1	0.12
VJ 61	Outfall	7/21/2015	7/21/2015	Chlorobenzene	<1.00	ug/L	Gasoline Odor Investigation		1	0.1
VJ 61	Outfall	7/21/2015	7/21/2015	Ethylbenzene	<1.00	ug/L	Gasoline Odor Investigation		1	0.16
VJ 61	Outfall	7/21/2015	7/21/2015	Styrene	<1.00	ug/L	Gasoline Odor Investigation		1	0.13
VJ 61	Outfall	7/21/2015	7/21/2015	Toluene	<1.00	ug/L	Gasoline Odor Investigation		1	0.12
VJ 61	Outfall	7/21/2015	7/21/2015	Xylenes, Total	<1.00	ug/L	Gasoline Odor Investigation		1	0.17
VJ 61	Outfall	7/21/2015	7/21/2015	o-Xylene	<1.00	ug/L	Gasoline Odor Investigation		1	0.11
VJ 61	Outfall	7/21/2015	7/21/2015	m-Xylene & p-Xylene	<2.00	ug/L	Gasoline Odor Investigation		2	0.17
VJ 61	Outfall	7/21/2015	7/21/2015	Bromodichloromethane	<1.00	ug/L	Gasoline Odor Investigation		1	0.1
VJ 61	Outfall	7/21/2015	7/21/2015	Bromoform	<1.00	ug/L	Gasoline Odor Investigation		1	0.11

1/29/2016



		Collection								
Client Sample ID	Sample Type	Date	Analysis Date	Analyte	Result	Unit	Sampling Event Notes	Flag	High Limit	Low Limit
VJ 61	Outfall	7/21/2015	7/21/2015	Bromomethane	<1.00	ug/L	Gasoline Odor Investigation		1	0.14
VJ 61	Outfall	7/21/2015	7/21/2015	Carbon tetrachloride	<1.00	ug/L	Gasoline Odor Investigation		1	0.2
VJ 61	Outfall	7/21/2015	7/21/2015	Chloroethane	<1.00	ug/L	Gasoline Odor Investigation		1	0.17
VJ 61	Outfall	7/21/2015	7/21/2015	Chloroform	<1.00	ug/L	Gasoline Odor Investigation		1	0.16
VJ 61	Outfall	7/21/2015	7/21/2015	Chloromethane	<1.00	ug/L	Gasoline Odor Investigation		1	0.15
VJ 61	Outfall	7/21/2015	7/21/2015	cis-1,2-Dichloroethene	<1.00	ug/L	Gasoline Odor Investigation		1	0.13
VJ 61	Outfall	7/21/2015	7/21/2015	cis-1,3-Dichloropropene	<1.00	ug/L	Gasoline Odor Investigation		1	0.1
VJ 61	Outfall	7/21/2015	7/21/2015	Dibromochloromethane	<1.00	ug/L	Gasoline Odor Investigation		1	0.15
VJ 61	Outfall	7/21/2015	7/21/2015	Dichlorodifluoromethane	<1.00	ug/L	Gasoline Odor Investigation	*	1	0.13
VJ 61	Outfall	7/21/2015	7/21/2015	Methylene Chloride	<1.00	ug/L	Gasoline Odor Investigation		1	0.08
VJ 61	Outfall	7/21/2015	7/21/2015	Tetrachloroethene	<1.00	ug/L	Gasoline Odor Investigation		1	0.16
VJ 61	Outfall	7/21/2015	7/21/2015	trans-1,2-Dichloroethene	<1.00	ug/L	Gasoline Odor Investigation		1	0.11
VJ 61	Outfall	7/21/2015	7/21/2015	trans-1,3-Dichloropropene	<1.00	ug/L	Gasoline Odor Investigation		1	0.05
VJ 61	Outfall	7/21/2015	7/21/2015	Trichloroethene	<1.00	ug/L	Gasoline Odor Investigation		1	0.16
VJ 61	Outfall	7/21/2015	7/21/2015	Trichlorofluoromethane	<1.00	ug/L	Gasoline Odor Investigation		1	0.21
VJ 61	Outfall	7/21/2015	7/21/2015	Vinyl chloride	<1.00	ug/L	Gasoline Odor Investigation		1	0.14
VJ 61	Outfall	7/21/2015	7/28/2015	HEM	< 5.00	mg/L	Gasoline Odor Investigation		5	5
Ve 44 Steam	Stream	7/16/2015	7/16/2015	Coliform, Fecal	100	CFU/100mL	Outfall Investigations		100	100
Vd70 Stream	Stream	7/16/2015	7/16/2015	Coliform, Fecal	400	CFU/100mL	Outfall Investigations		100	100
Vh26	Stream	7/16/2015	7/16/2015	Coliform, Fecal	1,000	CFU/100mL	Outfall Investigations		100	100
Vd70	Outfall	7/16/2015	7/16/2015	Coliform, Fecal	400	CFU/100mL	Outfall Investigations		100	100
127	Outfall	7/16/2015	7/16/2015	Coliform, Fecal	9,800	CFU/100mL	Outfall Investigations		100	100
Vd51b	Outfall	7/16/2015	7/16/2015	Coliform, Fecal	200	CFU/100mL	Outfall Investigations		100	100
Hd19	Outfall	7/16/2015	7/16/2015	Coliform, Fecal	3,900	CFU/100mL	Outfall Investigations		100	100
Vh30 (Stream)	Stream	7/16/2015	7/16/2015	Coliform, Fecal	900	CFU/100mL	Outfall Investigations		100	100
113 Stream	Stream	7/16/2015	7/16/2015	Coliform, Fecal	600	CFU/100mL	Outfall Investigations		100	100
VG 24	Outfall	7/21/2015	7/21/2015	Coliform, Fecal	3,700	CFU/100mL	Outfall Investigations		100	100
VJ 4	Outfall	7/21/2015	7/21/2015	Coliform, Fecal	800	CFU/100mL	Outfall Investigations		100	100
VN 1	Outfall	7/21/2015	7/21/2015	Coliform, Fecal	700	CFU/100mL	Outfall Investigations		100	100
VJ 58	Outfall	7/21/2015	7/21/2015	Coliform, Fecal	800	CFU/100mL	Outfall Investigations		100	100
26 DS	Stream	7/28/2015	7/28/2015	Coliform, Fecal	200	CFU/100mL	Outfall Investigations		100	100
26 US	Stream	7/28/2015	7/28/2015	Coliform, Fecal	500	CFU/100mL	Outfall Investigations		100	100
127	Outfall	7/28/2015	7/28/2015	Coliform, Fecal	200	CFU/100mL	Outfall Investigations		100	100
26	Outfall	7/28/2015	7/28/2015	Coliform, Fecal	2,000	CFU/100mL	Outfall Investigations		1000	1000
48A	Outfall	7/28/2015	7/28/2015	Coliform, Fecal	500	CFU/100mL	Outfall Investigations		100	100
116 (Stream)	Stream	7/28/2015	7/28/2015	Coliform, Fecal	800	CFU/100mL	Outfall Investigations		100	100
26	Outfall	8/6/2015	8/6/2015	Coliform, Fecal	2,000	CFU/100mL	Outfall Investigations		100	100
CB Near Vn1	Catchbasin	8/6/2015	8/6/2015	Coliform, Fecal	100	CFU/100mL	Outfall Investigations		100	100
Vg 24	Outfall	8/6/2015	8/6/2015	Coliform, Fecal	15,000	CFU/100mL	Outfall Investigations		1000	1000
Vg 24	Outfall	8/26/2015	8/26/2015	Coliform, Fecal	800	CFU/100mL	Outfall Investigations		100	100
Vg24	Manhole	9/2/2015	9/2/2015	Coliform, Fecal	16,000	CFU/100mL	Outfall Investigations		1000	1000
OF26	Outfall	9/2/2015	9/2/2015	Coliform, Fecal	1,900	CFU/100mL	Outfall Investigations		100	100
26 Upstream	Stream	9/2/2015	9/2/2015	Coliform, Fecal	100	CFU/100mL	Outfall Investigations		100	100
26 Downstream	Stream	9/2/2015	9/2/2015	Coliform, Fecal	300	CFU/100mL	Outfall Investigations		100	100

# ARCADIS Design & Consultancy for natural and built assets

		Collection								
Client Sample ID	Sample Type	Date	Analysis Date	Analyte	Result	Unit	Sampling Event Notes	Flag	High Limit	Low Limit
ANITA	Stream	9/2/2015	9/2/2015	Coliform, Fecal	100	CFU/100mL	Outfall Investigations		100	100
47	Outfall	10/7/2015	10/7/2015	Coliform, Fecal	6,000	CFU/100mL	Outfall Investigations		1000	1000
Vg 42	Outfall	10/7/2015	10/7/2015	Coliform, Fecal	300	CFU/100mL	Outfall Investigations		100	100
17	Outfall	10/7/2015	10/7/2015	Coliform, Fecal	1,800	CFU/100mL	Outfall Investigations		100	100
26	Outfall	10/7/2015	10/7/2015	Coliform, Fecal	3,900	CFU/100mL	Outfall Investigations		100	100
Ve 22	Outfall	10/7/2015	10/7/2015	Coliform, Fecal	41,000	CFU/100mL	Outfall Investigations		1000	1000
Vg31 (manhole)	Manhole	9/16/2015	9/16/2015	Coliform, Fecal	12,000	CFU/100mL	Vg 24 Area Investigation		1000	1000
Vg32 (manhole)	Manhole	9/16/2015	9/16/2015	Coliform, Fecal	21,000	CFU/100mL	Vg 24 Area Investigation		1000	1000
Vg 29 (manhole)	Manhole	8/26/2015	8/26/2015	Coliform, Fecal	>200,000	CFU/100mL	Vg 24 Area Investigation		1000	1000
Vg 33 (manhole)	Manhole	8/26/2015	8/26/2015	Coliform, Fecal	100	CFU/100mL	Vg 24 Area Investigation		100	100
Vg 35 (manhole)	Manhole	8/26/2015	8/26/2015	Coliform, Fecal	<100	CFU/100mL	Vg 24 Area Investigation		100	100
Vg 36 (manhole)	Manhole	8/26/2015	8/26/2015	Coliform, Fecal	<100	CFU/100mL	Vg 24 Area Investigation		100	100
Church Lateral	Lateral	8/26/2015	8/26/2015	Coliform, Fecal	<100	CFU/100mL	Vg 24 Area Investigation		100	100
Vg29 (manhole)	Manhole	9/2/2015	9/2/2015	Coliform, Fecal	36,000	CFU/100mL	Vg 24 Area Investigation		1000	1000
Palmer Ter 1 (Vg 32)	Manhole	12/4/2015	12/4/2015	Coliform, Fecal	3,000	CFU/100mL	Vg 24 Area Investigation		100	100
Palmer Tier 2 (Vg 32)	Manhole	12/4/2015	12/4/2015	Coliform, Fecal	3,000	CFU/100mL	Vg 24 Area Investigation		100	100
Vh6 (manhole)	Manhole	9/2/2015	9/2/2015	Coliform, Fecal	200	CFU/100mL	Outfall 26 Area Investigation		100	100
Vh3 (manhole)	Manhole	9/2/2015	9/2/2015	Coliform, Fecal	<100	CFU/100mL	Outfall 26 Area Investigation		100	100
S. Barry DS1	Stream	10/1/2015	10/1/2015	Coliform, Fecal	5,200	CFU/100mL	Stream Sampling		100	100
S. Barry DS2	Stream	10/1/2015	10/1/2015	Coliform, Fecal	5,900	CFU/100mL	Stream Sampling		100	100
Tomkins US1	Stream	10/1/2015	10/1/2015	Coliform, Fecal	4,300	CFU/100mL	Stream Sampling		100	100
Tomkins US2	Stream	10/1/2015	10/1/2015	Coliform, Fecal	5,100	CFU/100mL	Stream Sampling		100	100
Anita US1	Stream	10/1/2015	10/1/2015	Coliform, Fecal	2,500	CFU/100mL	Stream Sampling		100	100
Anita US2	Stream	10/1/2015	10/1/2015	Coliform, Fecal	3,000	CFU/100mL	Stream Sampling		100	100
Jeff US1	Stream	10/1/2015	10/1/2015	Coliform, Fecal	2,600	CFU/100mL	Stream Sampling		100	100
Jeff US2	Stream	10/1/2015	10/1/2015	Coliform, Fecal	1,500	CFU/100mL	Stream Sampling		100	100
Shel-Mam1	Stream	10/1/2015	10/1/2015	Coliform, Fecal	3,400	CFU/100mL	Stream Sampling		100	100
Shel-Mam2	Stream	10/1/2015	10/1/2015	Coliform, Fecal	1,600	CFU/100mL	Stream Sampling		100	100
Plaza 1	Stream	10/1/2015	10/1/2015	Coliform, Fecal	1,800	CFU/100mL	Stream Sampling		100	100
Plaza 2	Stream	10/1/2015	10/1/2015	Coliform, Fecal	1,900	CFU/100mL	Stream Sampling		100	100
Vg US1	Stream	10/1/2015	10/1/2015	Coliform, Fecal	2,300	CFU/100mL	Stream Sampling		100	100
Vg US2	Stream	10/1/2015	10/1/2015	Coliform, Fecal	2,900	CFU/100mL	Stream Sampling		100	100
Mr Urban1	Stream	10/1/2015	10/1/2015	Coliform, Fecal	11,000	CFU/100mL	Stream Sampling		1000	1000
Mr Urban2	Stream	10/1/2015	10/1/2015	Coliform, Fecal	5,100	CFU/100mL	Stream Sampling		100	100
N.Barry DS1	Stream	10/1/2015	10/1/2015	Coliform, Fecal	2,900	CFU/100mL	Stream Sampling		100	100
N.Barry DS2	Stream	10/1/2015	10/1/2015	Coliform, Fecal	2,500	CFU/100mL	Stream Sampling		100	100
Anita 1	Stream	10/7/2015	10/7/2015	Coliform, Fecal	600	CFU/100mL	Stream Sampling		100	100
Anita 2	Stream	10/7/2015	10/7/2015	Coliform, Fecal	800	CFU/100mL	Stream Sampling		100	100
Jefferson Ave US1	Stream	10/7/2015	10/7/2015	Coliform, Fecal	300	CFU/100mL	Stream Sampling		100	100
Jefferson Ave US2	Stream	10/7/2015	10/7/2015	Coliform, Fecal	100	CFU/100mL	Stream Sampling		100	100
Shel-Man 1	Stream	10/7/2015	10/7/2015	Coliform, Fecal	400	CFU/100mL	Stream Sampling		100	100
Shel-Man 2	Stream	10/7/2015	10/7/2015	Coliform, Fecal	500	CFU/100mL	Stream Sampling		100	100
Plaza 1	Stream	10/7/2015	10/7/2015	Coliform, Fecal	200	CFU/100mL	Stream Sampling		100	100
Plaza 2	Stream	10/7/2015	10/7/2015	Coliform, Fecal	<100	CFU/100mL	Stream Sampling		100	100

# ARCADIS Design & Consultancy for natural and built assets

		Collection								
Client Sample ID	Sample Type	Date	Analysis Date	Analyte	Result	Unit	Sampling Event Notes	Flag	High Limit	Low Limit
Vg 24 US-1	Stream	10/7/2015	10/7/2015	Coliform, Fecal	500	CFU/100mL	Stream Sampling		100	100
Vg 24 US-2	Stream	10/7/2015	10/7/2015	Coliform, Fecal	300	CFU/100mL	Stream Sampling		100	100
N Barry DS-1	Stream	10/7/2015	10/7/2015	Coliform, Fecal	900	CFU/100mL	Stream Sampling		100	100
N Barry DS-2	Stream	10/7/2015	10/7/2015	Coliform, Fecal	1,100	CFU/100mL	Stream Sampling		100	100
Mr Urban St 1	Stream	10/7/2015	10/7/2015	Coliform, Fecal	600	CFU/100mL	Stream Sampling		100	100
Mr Urban St 2	Stream	10/7/2015	10/7/2015	Coliform, Fecal	700	CFU/100mL	Stream Sampling		100	100
Tompkins Us 1	Stream	10/7/2015	10/7/2015	Coliform, Fecal	600	CFU/100mL	Stream Sampling		100	100
Tompkins Us 2	Stream	10/7/2015	10/7/2015	Coliform, Fecal	500	CFU/100mL	Stream Sampling		100	100
Tompkins Ds 1	Stream	10/7/2015	10/7/2015	Coliform, Fecal	600	CFU/100mL	Stream Sampling		100	100
Tompkins Ds 2	Stream	10/7/2015	10/7/2015	Coliform, Fecal	300	CFU/100mL	Stream Sampling		100	100
Otter Creek 1	Stream	10/7/2015	10/7/2015	Coliform, Fecal	1,100	CFU/100mL	Stream Sampling		100	100
Otter Creek 2	Stream	10/7/2015	10/7/2015	Coliform, Fecal	1,600	CFU/100mL	Stream Sampling		100	100
S Barry 1	Stream	10/7/2015	10/7/2015	Coliform, Fecal	500	CFU/100mL	Stream Sampling		100	100
S Barry 2	Stream	10/7/2015	10/7/2015	Coliform, Fecal	<100	CFU/100mL	Stream Sampling		100	100
Jefferson	Stream	9/16/2015	9/16/2015	Coliform, Fecal	1,100	CFU/100mL	DNA Sampling		100	100
Shel/Mam	Stream	9/16/2015	9/16/2015	Coliform, Fecal	1,400	CFU/100mL	DNA Sampling		100	100
Jefferson 1	Stream	9/16/2015	9/22/2015	DBACT	4	gene copies/mL	DNA Sampling	J	1.00E-01	4.80E+00
Jefferson 1	Stream	9/16/2015	9/22/2015	GenBac	245	gene copies/mL	DNA Sampling	=	1.00E-01	4.80E+00
Jefferson 1	Stream	9/16/2015	9/22/2015	H-EPA1	3,360	gene copies/mL	DNA Sampling	=	1.00E-01	4.80E+00
Jefferson 1	Stream	9/16/2015	9/22/2015	H-EPA2	5	gene copies/mL	DNA Sampling	<	1.00E-01	4.80E+00
Jefferson 1	Stream	9/16/2015	9/22/2015	HF183	5	gene copies/mL	DNA Sampling	<	1.00E-01	4.80E+00
Jefferson 1	Stream	9/16/2015	9/22/2015	Gull-CAT	5	gene copies/mL	DNA Sampling	<	1.00E-01	4.80E+00
Jefferson 1	Stream	9/16/2015	9/22/2015	CG BACT1	1	gene copies/mL	DNA Sampling	J	1.00E-01	4.80E+00
Jefferson 1	Stream	9/16/2015	9/22/2015	CG BACT2	0	gene copies/mL	DNA Sampling	J	1.00E-01	4.80E+00
Jefferson 2	Stream	9/16/2015	9/22/2015	DBACT	3	gene copies/mL	DNA Sampling	J	1.00E-01	4.70E+00
Jefferson 2	Stream	9/16/2015	9/22/2015	GenBac	421	gene copies/mL	DNA Sampling	=	1.00E-01	4.70E+00
Jefferson 2	Stream	9/16/2015	9/22/2015	H-EPA1	1,710	gene copies/mL	DNA Sampling	=	1.00E-01	4.70E+00
Jefferson 2	Stream	9/16/2015	9/22/2015	H-EPA2	5	gene copies/mL	DNA Sampling	<	1.00E-01	4.70E+00
Jefferson 2	Stream	9/16/2015	9/22/2015	HF183	5	gene copies/mL	DNA Sampling	<	1.00E-01	4.70E+00
Jefferson 2	Stream	9/16/2015	9/22/2015	Gull-CAT	5	gene copies/mL	DNA Sampling	<	1.00E-01	4.70E+00
Jefferson 2	Stream	9/16/2015	9/22/2015	CG BACT1	0	gene copies/mL	DNA Sampling	J	1.00E-01	4.70E+00
Jefferson 2	Stream	9/16/2015	9/22/2015	CG BACT2	0	gene copies/mL	DNA Sampling	J	1.00E-01	4.70E+00
Shel/Mam 1	Stream	9/16/2015	9/22/2015	DBACT	2	gene copies/mL	DNA Sampling	J	1.00E-01	4.70E+00
Shel/Mam 1	Stream	9/16/2015	9/22/2015	GenBac	276	gene copies/mL	DNA Sampling	=	1.00E-01	4.70E+00
Shel/Mam 1	Stream	9/16/2015	9/22/2015	H-EPA1	5	gene copies/mL	DNA Sampling	<	1.00E-01	4.70E+00
Shel/Mam 1	Stream	9/16/2015	9/22/2015	H-EPA2	37,400	gene copies/mL	DNA Sampling	=	1.00E-01	4.70E+00
Shel/Mam 1	Stream	9/16/2015	9/22/2015	HF183	5	gene copies/mL	DNA Sampling	<	1.00E-01	4.70E+00
Shel/Mam 1	Stream	9/16/2015	9/22/2015	Gull-CAT	5	gene copies/mL	DNA Sampling	<	1.00E-01	4.70E+00
Shel/Mam 1	Stream	9/16/2015	9/22/2015	CG BACT1	0	gene copies/mL	DNA Sampling	J	1.00E-01	4.70E+00
Shel/Mam 1	Stream	9/16/2015	9/22/2015	CG BACT2	5	gene copies/mL	DNA Sampling	<	1.00E-01	4.70E+00
Shel/Mam 2	Stream	9/16/2015	9/22/2015	DBACT	4	gene copies/mL	DNA Sampling	J	1.00E-01	4.80E+00
Shel/Mam 2	Stream	9/16/2015	9/22/2015	GenBac	493	gene copies/mL	DNA Sampling	=	1.00E-01	4.80E+00
Shel/Mam 2	Stream	9/16/2015	9/22/2015	H-EPA1	908	gene copies/mL	DNA Sampling	=	1.00E-01	4.80E+00
Shel/Mam 2	Stream	9/16/2015	9/22/2015	H-EPA2	9,950	gene copies/mL	DNA Sampling	=	1.00E-01	4.80E+00



		Collection								
Client Sample ID	Sample Type	Date	Analysis Date	Analyte	Result	Unit	Sampling Event Notes	Flag	High Limit	Low Limit
Shel/Mam 2	Stream	9/16/2015	9/22/2015	HF183	5	gene copies/mL	DNA Sampling	<	1.00E-01	4.80E+00
Shel/Mam 2	Stream	9/16/2015	9/22/2015	Gull-CAT	5	gene copies/mL	DNA Sampling	<	1.00E-01	4.80E+00
Shel/Mam 2	Stream	9/16/2015	9/22/2015	CG BACT1	1	gene copies/mL	DNA Sampling	J	1.00E-01	4.80E+00
Shel/Mam 2	Stream	9/16/2015	9/22/2015	CG BACT2	5	gene copies/mL	DNA Sampling	<	1.00E-01	4.80E+00
Jeff Bridge 1	Stream	12/4/2015	12/9/2015	HEM	<5.32	mg/L	Oil Slick Investigation		5.32	5.32
Jeff Bridge 2	Stream	12/4/2015	12/9/2015	HEM	<5.43	mg/L	Oil Slick Investigation		5.43	5.43

# **APPENDIX C**

Otter Creek Investigation Photo Log





Photo filename (.jpg): Otter Creek (1) Arcadis visited Otter Creek at low tide to locate outfalls to investigate potential for illicit discharges. Otter Creek is very shallow at low tide.



Photo filename (.jpg): Otter Creek (2) Bank Arcadis paddled upstream until the creek became too shallow to continue. 2

1

Village of Mamaroneck Mamaroneck, NY Illicit Discharge Detection and Elimination Photographs of Site Inspection 08–21–2015

Pesign & Consultancy for natural and built assets APPENDIX C



Photo filename (.jpg): Otter Creek (3) Mud Arcadis staff were unable to walk through mud because it was soft and unstable.



Photo filename (.jpg): Otter Creek (4) The width of the creek and dense vegetation along the shoreline prevented Arcadis staff from seeing outfalls from the kayak. 3

4

Village of Mamaroneck Mamaroneck, NY Illicit Discharge Detection and Elimination

## Photographs of Site Inspection 08–21–2015

ARCADIS Unsign & Consultancy for natural and bulk assets APPENDIX C



5

6

Village of Mamaroneck Mamaroneck, NY

Illicit Discharge Detection and Elimination

## Photographs of Site Inspection 08-21-2015

ARCADIS Design & Consultancy for natural and built assets



Photo filename (.jpg): Otter Creek (7) At mid-tide, the water depth in the Creek is greater, such that Arcadis staff could travel further than at low tide.



Photo filename (.jpg): Otter Creek (8)

8

7



Village of Mamaroneck Mamaroneck, NY **Illicit Discharge Detection and Elimination** 

APPENDIX



10

9

Village of Mamaroneck Mamaroneck, NY

Illicit Discharge Detection and Elimination

## Photographs of Site Inspection 08-21-2015

ARCADIS Design & Consultancy fornatural and full states APPENDIX C

continue.

Photo filename (.jpg): Otter Creek (10)

Even at mid-tide, Arcadis staff reached a point at which the vegetation was too dense and the water was too shallow to



Photo filename (.jpg): BSB 23 Arcadis staff located one outfall, at the mouth of Otter Creek, close to the Harbor.

12

11

Village of Mamaroneck Mamaroneck, NY Illicit Discharge Detection and Elimination

## Photographs of Site Inspection 08-21-2015

ARCADIS Design & Consultancy for natural and bulk assets APPENDIX C



13

Photo filename (.jpg): Vj 60 (not verified) The approximate location of outfall Vj 60 was located, but the outfall could not be seen.

> Village of Mamaroneck Mamaroneck, NY Illicit Discharge Detection and Elimination Photographs of Site Inspection 08–21–2015

ARCADIS Design & Consultancy for natural and built assets APPENDIX C

# **APPENDIX D**

**River Foam Sampling Events** 





Richard Slingerland Village Manager Village of Mamaroneck 123 Mamaroneck Avenue Mamaroneck, NY 10543

Subject: River Sampling Event – Foam in the Mamaroneck River

Dear Mr. Slingerland:

At the Village of Mamaroneck's (Village) request, ARCADIS of New York (ARCADIS) collected samples from the Mamaroneck River due to concerns from area residents regarding foam in the Mamaroneck River. The origin and composition of the foam were not known, so the Village directed ARCADIS to sample the foam and to have it analyzed for common pollutants.

ARCADIS collected samples on the River on April 16<sup>th</sup>. Two sampling locations were selected, one location where foam was prominent and one upriver location where foam was not observed. The first sampling location was located under the Jefferson Avenue bridge, on the west bank of the river. The second upriver location was located under the North Barry Extension bridge, on the east bank of the river. Foam was collected in each of the downgradient sample bottles to ensure the perceived contaminant was analyzed.

Photographs of the two sample locations are provided as Appendix A. These photos show the sampling locations and the foam that was observed at each site. One set of samples were collected at each location and analyzed for Fecal Coliform, Oil & Grease, and Anionic Surfactants. Fecal coliform is present in high concentrations in wastewater and anionic surfactants are present in high concentrations in detergents and foaming agents. The standard test for surfactants is methylene blue active substances assay (MBAS).

The samples were tested by EnviroTest Laboratories, in Newburgh, NY. The lab is certified for environmental testing in New York, New Jersey, and Connecticut. The testing results were received by ARCADIS on April 17th. The complete testing results are provided as Appendix B. Table 1 on the next page provides a summary of the testing results.

ARCADIS of NY, Inc. 44 South Broadway 15th Floor Box 751 White Plains New York 10602-0751 Tel 914 694 2100 Fax 914 694 9286 www.arcadis-us.com

Water

Date: April 20, 2015 Contact: Kevin Hogan Phone: 518-250-7306

Email: Kevin.Hogan@arcadisus.com

Parameter	er Result Reporting Limit		Water Quality Standard
	-	(RL)	
Fecal	130 cfu\100 ml	10 cfu\100 ml	Geometric mean of five samples shall not exceed
Coliform	190 cfu\100 ml	10 cfu\100 ml	200 cfu\100 ml
Oil and Grease	< 5.0 mg\l < 5.21 mg\l	5.0 mg\l 5.21 mg\l	No residue attributable to sewage, industrial wastes, or other wastes, nor visible oil film or globules of grease
Surfactants (MBAS)	0.172 mg\l <0.1 mg\l	0.1 mg\l 0.1 mg\l	No water quality standard. The limit commonly used in sampling stormwater to start performing further investigations is > 0.25 mg\l.

Table 1 – Summary of Analytical Results

In reviewing and interpreting these results, the main point to consider is that the concentrations for all three parameters were very low. In fact, the oil and grease samples and one of the surfactant samples were below the labs reporting limit, and the other surfactant sample was just above the labs reporting limit. A reporting limit is the laboratory's limit of detection for the target analyte in a specific sample after adjustments have been made for dilutions or percent moisture.

For comparison of the results above, consider the stormwater discharging from a trucking facility with a fueling station would be permitted for a limit of 30 mg/l for oils and grease. In addition, the laboratory indicated that if soap was the cause of the foam collected in the sample bottle, the MBAS result would have been well over 100 mg/l.

The foam observed on the River was likely naturally occurring. When plants and animals die the lipids rise to the surface and coat the surface of the water. When the water is agitated from wind and current the fatty acids entrain the small bubbles that constitute the foam. Naturally occurring foam usually appears white or gray, while foam caused by soap often appears white with a slight pink appearance. Articles on this subject are provided in Appendix C.

Please do not hesitate to contact me at 518-250-7306 if you have any questions or would like additional information.

Sincerely,

ARCADIŞ of NY, Inc.

Kevin Hogan, PE Senior Engineer

# **ARCADIS**

Appendix A

Sampling Location Photos



Photo #1: Jefferson Ave. bridge facing east



Photo #2: Sampling of the river - Clumps of foam can be seen in the background of the photo. Foam was collected in each sample bottle.



1

2



Photo #3: North Berry Ext. bridge facing west



Photo #4: Sampling location on the river - Clumps of foam can be seen on the left hand side of the photo

> VILLAGE OF MAMARONECK RIVER SAMPLING EVENT – FOAM IN THE MAMARONECK RIVER Site #2, North Berry Ext. Bridge **ARCADIS** APPENDIX

3

4



# **ARCADIS**

Appendix **B** 

Analytical Results



## ANALYTICAL REPORT

Job Number: 420-89305-1 SDG Number: Mamaraneck Job Description: Illicit Discharge Detection

> For: Arcadis US, Inc. 855 Route 146 Suite 210 Clifton Park, NY 12065

Attention: Mr. Kevin Hogan

Bereem. Cusock

Renee Cusack Lab Director rcusack@envirotestlaboratories.com 04/17/2015

cc: Mr. A.J. Brooks

NYSDOH ELAP does not certify for all parameters. EnviroTest Laboratories does hold certification for all analytes where certification is offered by ELAP unless otherwise specified. Pursuant to NELAP, this report may not be reproduced, except in full, without written approval of the laboratory. EnviroTest Laboratories Inc. certifies that the analytical results contained herein apply only to the samples tested as received by our laboratory. All questions regarding this report should be directed to the EnviroTest Customer Service Representative.

EnviroTest Laboratories, Inc. Certifications and Approvals: NYSDOH 10142, NJDEP NY015, CTDOPH PH-0554





## **METHOD SUMMARY**

Client: Arcadis US, Inc.

Job Number: 420-89305-1 SDG Number: Mamaraneck

Description	Lab Location	Method	Preparation Method
Matrix: Water			
HEM and SGT-HEM by Extraction and Gravimetry HEM and SGT-HEM by Extraction and	EnvTest EnvTest	1664A 1664A	1664A 1664A
Membrane Filter Technique - Fecal Coliform Procedure	EnvTest	SM18 SM 9222	2D-97
Anionic Surfactants as MBAS	EnvTest	SM21 SM5540	C-00,11
Lab References:			
EnvTest = EnviroTest			

#### Method References:

1664A = EPA-821-98-002

SM18 = "Standard Methods For The Examination Of Water And Wastewater", 18th Edition, 1992.

SM21 = "Standard Methods For The Examination Of Water And Wastewater", 21st Edition

## METHOD / ANALYST SUMMARY

Client: Arcadis US, Inc.

Job Number: 420-89305-1 SDG Number: Mamaraneck

Method	Analyst	Analyst ID
1664A 1664A	Vollmer, William	WB
SM18 SM 9222D-97	Travis, Lyndsey	LT
SM21 SM5540C-00,11	Miller, Kyle A	КАМ

## SAMPLE SUMMARY

Client: Arcadis US, Inc.

Job Number: 420-89305-1 SDG Number: Mamaraneck

			Date/Time	Date/Time
Lab Sample ID	Client Sample ID	Client Matrix	Sampled	Received
420-89305-1	Columbus Park	Water	04/15/2015 1200	04/15/2015 1420
420-89305-2	N Berry Bridge	Water	04/15/2015 1245	04/15/2015 1420

Mr. Kevin Hogan Arcadis US, Inc. 855 Route 146 Suite 210 Clifton Park, NY 12065 Job Number: 420-89305-1 Sdg Number: Mamaraneck

Client Sample ID: Lab Sample ID:	Columbus Park 420-89305-1		Date Sampled: Date Received:	04/15/2015 1200 04/15/2015 1420	
·			Client Matrix:	Water	
Analyte		Result/Qualifier	Unit	RL	Dilution
Method: 1664A			Date Analyzed:	04/16/2015 1000	
Prep Method: 1664A			Date Prepared:	04/16/2015 1000	
HEM		<5.21	mg/L	5.21	1.0
SGT-HEM		<5.21	mg/L	5.21	1.0
Method: SM5540C-0	0,11		Date Analyzed:	04/16/2015 1000	
MBAS		0.172	mg/I LAS MW	0.100	1.0
Method: SM 9222D-9	97		Date Analyzed:	04/15/2015 1600	
Coliform, Fecal		130	CFU/100mL	10.0	10
Mr. Kevin Hogan Arcadis US, Inc. 855 Route 146 Suite 210 Clifton Park, NY 12065 Job Number: 420-89305-1 Sdg Number: Mamaraneck

Client Sample ID: Lab Sample ID:	N Berry Bridge 420-89305-2		Date Sampled: Date Received:	04/15/2015 1245 04/15/2015 1420	
			Client Matrix:	Water	
Analyte		Result/Qualifier	Unit	RL	Dilution
Method: 1664A			Date Analyzed:	04/16/2015 1000	
Prep Method: 1664A			Date Prepared:	04/16/2015 1000	
HEM		<5.00	mg/L	5.00	1.0
SGT-HEM		<5.00	mg/L	5.00	1.0
Method: SM5540C-0	0,11		Date Analyzed:	04/16/2015 1000	
MBAS		<0.100	mg/I LAS MW	0.100	1.0
Method: SM 9222D-9	97		Date Analyzed:	04/15/2015 1600	
Coliform, Fecal		190	CFU/100mL	10.0	10

EnviroTest	J	CHAIN OF	CUSTODY	315 Fullerton Avenue
Laboratories Ir	JC.			SY300 TEL (845) 562-0890 FAX (845) 562-0841
CUSTOMER NAME ARCADTS U.	S. Inc	REPORT TYI	PE TURNAROUND	REPORT # (Lab Use Only)
ADDRESS ADDRESS ATH Bradway	4. ISth Floor		A	
White Plains, N	Y. 10601			SAMPLE TEMP. 10.4 C
NAME OF CONTACT	(914)641°2777	OTHER		
PROJECT LOCATION			Matrix	
PROJECT NUMBER / PO NO.		DW = DRINKIN WW = WASTE WATER	G WATER S = SOIL O = OIL SL = SLUDGE GW = GROUND WA	<b>NY PUBLIC WATER SUPPLIES</b>
NOTE: SAMPLE TER		θμ 		SOURCE ID
RECEIPT MUS	TBE 4° ± 2°C.	CCL Plastic Plastic Plastic Plastic Plastic CCL Plastic Classic CCL Plastic CCL Plastic CCL Plastic CCL Plastic CCL Plastic CCL Plastic CCL Plastic CCL Plastic CCL Plastic CCL CCL Plastic CCL CCL CCL CCL CCL CCL CCL CCC CCC CC	00 01 02 02 02 02 02 02 02 02 02 02	
ETL SAMPLING P. B. H. DATE TIME D. B. MATRIX # AM PM O G	CLIENT I.D.	And the second s	20000 20	
1115/12:00 1 c	colum Jus Park MBAS 3			MBAS / Surfaction to
4/15/12:400 1	owners Part Oil/Genere	7		oil scrase
"Inthe part of	elumbers Park Freel		7	Fecal coliforn
weight is the state of the stat	). Bany Bridge MRAS	~		MBAS/Sarfactants
A VISIN SHUT AND	Bern Bridge Oilthous	N		oils brease
20 HISIS 17:44 V	V. Rong Dridge Fred		Ŋ	Fear altim
SAMPLES SUBMITTED FOR ANALYSIS	S WILL BE SUBJECT TO THE ETL TERM	IS AND CONDITIONS OF SALE UNLE	ESS ALTERNATE TERMS ARE AGREED IN	WRITING.
FELINPUISHED AV TUR	E-CONPANY YI	PTTS TIME 630	REDEIVED BY PAULUN	10 KH SILASHIA AMATHAN
JARED LEADER	ARCADIS 41	ISTIC THE BOINT	RÉCEIVED BY	COMPANY DATE TIME
RELIMOUISHED BY	COMPANY COMPANY	ST/JS TIMETAD	RECEIVED BY	COMPANY DATE TIME
COMMENTS Jared. Lea	der @ascadis-	-us. com		

04/17/2015

NYSDOH 10142 NJDEP NY015 CTDOPH PH-0554 EPA NY00049

.

# ARCADIS

Appendix **C** 

Natural Occurring Foam Articles

July 15, 2009 · 9:53 am

# <u>Science of the Seasons: Bubbling curiosity —</u> <u>Most water foam is no cause for concern</u>



Photo courtesy of David Wartinbee. Naturally occurring foam found in rivers and streams results from the breakdown of organic materials in and around streams and changes the surface tension of the water, causing bubbles to form.

By David Wartinbee, for the Redoubt Reporter

A few weeks ago, a friend asked me if I knew about the pollution going on in a particular stream. He had seen patches of foam and an endless stream of bubbles in a variety of places along the edge of the stream. There were masses of foam floating on the surface and large accumulations of discolored foam trapped behind a couple logs. He was certain something bad was getting into that stream.

About the same time, when launching my boat at Lower Skilak Lake Campground, I saw the entire northern shoreline outlined with a thick mass of pure white foam. The 2-inch-thick foam was blown up on shore in a swath almost a foot wide. It looked like someone spilled a giant bottle of bubble-bath soap into the water. Were these piles of bubbles the result of some untoward act, too?

The answer is simple. No pollution activity is indicated by either of these situations. Masses of bubbles floating on the surface of lakes and streams are perfectly natural. Interestingly, the natural processes that caused these bubbles to form are almost identical to those required to make soap.

People have been making and using soaps for more than 4,000 years. The needed materials haven't changed much through the years and are relatively simple. First, there needs to be a source of fatty acids. American colonists commonly used fat (tallow or lard), but fish oils or even

vegetable oils will do. Caustic lye, an alkaline solution made from wood ashes, was used to cause the fatty acids to combine with sodium or potassium ions. The resulting molecules had a nonpolar end and a polar end, which means that part of the molecule would combine with water and one part would not. These molecules change the surface tension of the water, and that causes foam or bubbles.

Lakes and streams are surrounded by living organisms, and many organisms live within the water itself. Both plants and animals produce lipids like simple fats — three fatty acids combined with a glycerol molecule. When any of these organisms die, they release fats, proteins, sugars and other molecules into the water. Nonpolar molecules like lipids float since they have a lower specific gravity than water and will not mix with water. As fats and other lipids break down, the released fatty acids also float to the surface.



Thus, the surface of the water often has a thin, completely transparent layer of lipids on it. Through reactions similar to those used to make soap, the resulting molecules change the surface tension and, just like soap, they cause bubbles to form.

Agitation of the surface layer of lipids causes bubbles to form. The thick layer of foam I saw at Skilak Lake surely resulted from the heavy wave action the day before. The associated wind then drove the foam up onto the shore where is showed up so distinctly on one side of the lake. In streams, foam collects in backwater areas and gets trapped behind floating obstacles like tree branches or emergent vegetation. As the material oxidizes and debris collects in the foam, it can take on ominous colorations. Lots of floating objects and even microorganisms get trapped within these foam masses.

The fact that foam acts as a floating debris collector has been put to good use by many different scientists. The floating pupal cast skins I use to identify Chironomids can be found by the thousands in these foam collections. My wife jokes that as a graduate student, I could recognize foam in a stream at 60 miles per hour, and then we needed to stop and collect a sample.

Other insects, like caddisflies and mayflies, can leave their pupal skins in these foam masses, too. Those who work with aquatic fungi commonly use foam collections to find representative spores. As well, within these foam masses one can find pollen, seeds, algae, moss spores, minute insects called collembola, and a variety of other minute animal, plant and fungal remains.

It has been shown that some environmentally degrading activities can cause foam to occur in streams and lakes. For example, high concentrations of detergents or faulty sewage treatment facilities are known to cause excess foam creation. Some mining activities like washing gravels or adding materials to lakes can cause extraordinary amounts of foam to be created. The foam itself is not usually the polluting activity, but rather the foam is an indication that something is going on.

Perhaps excess amounts of foam or unusual odors might raise a suspicion of human activity. Seeing lots of dead fish mixed in with the foam certainly indicates that it's time to notify the authorities. Unfortunately, it is very difficult to separate naturally occurring foam from pollutionrelated foam.

While huge masses of foam in a stream or around our lakes could signal a pollution situation, the vast majority of foam we see is from perfectly normal biological processes.

David Wartinbee, Ph.D, J.D., is a biology professor at Kenai Peninsula College's Kenai River Campus. He is writing a series of columns on the ecology of the Kenai River and Cook Inlet watershed.



#### Foam on Surface Waterbodies

**Q.** Why do we see foam on our lakes and streams?

**A.** Foam is a natural phenomenon that occurs on many lakes and streams. Foam is produced when organic matter decomposes and releases fatty acids that act as surfactants or surface active agents. Smaller amounts of dissolved organic matter are also released from living organisms. These foam producing molecules have one end that repels water and another end that attracts water and work to reduce the surface tension on the water surface. These fatty acids are lighter than water so float on the surface of the water as a thin film. Turbulence from waves or currents cause the fatty acids to entrain small bubbles that constitute the foam. In lakes and large rivers the wind causes the foam to form into parallel streaks, due to wind induced surface currents (Langmuir circulation). Large amounts of foam will accumulate on downwind beaches and coves, in stream eddies or against docks, logs, and other floating objects.

**Q.** Where does the organic matter that makes the foam come from?

**A.** The organic matter in surface waters comes mostly from decomposing vegetation such as algae and terrestrial plants, but could also include other natural sources such as spawned out salmon. Anthropogenic sources of organic matter include sewage and agriculture, pulp mill and other organic discharges. In rivers, spring freshet commonly causes a lot of foam as decomposed vegetation (i.e. leaves and needles) are washed out of backchannels and small streams. Along the north coast the brown water that drains bogs and wetlands are high in organic compounds due to the high productivity and slow breakdown of plant material in these ecosystems.

**Q.** Is the foam natural or man-made?

**A.** While it is possible that humans are to blame, it is more likely the foam is just a natural phenomenon. Natural foam is generally white, breaks down relatively quickly and smells like fish or earth. If there is a lot of soil erosion the foam may be a dirty brown and contain small bits of organic matter. During periods of high pollen release, (in B.C. usually from coniferous trees), the foam may have a yellow colour. If the source of the foam is from detergents or other personal care products, then the foam may have a sweet or perfume smell. Whether the organic matter is from natural or man-made sources the main foam constituents are the same. To identify man-made sources of organics some form of tracer compound would need to be sampled, such as chlorinated compounds or the musks used as scents. Man made foam should accumulate near its source, not over large areas, will not persist, will dissipate quickly (once the discharge stops) and is generally not associated with rain storms or winds. Synthetic detergents developed after the Second World War were not biodegradable so this resulted in large accumulations of persist, quickly lose their ability to cause foam and are unable to produce the long-lasting foam found along some shores.

Ministry of Environment

Environmental Protection Thompson Region Mailing Address: 1259 Dalhousie Drive Kamloops BC V2C 5Z5 Telephone: 250-371-6200 Facsimile: 250-828-4000 Website: www.gov.bc.ca/env



#### Q. Is foam hazardous?

**A.** Foam is usually harmless. The foaming agents are primarily proteinaceous or carbonaceous matter. It only takes a small amount of fatty acids or other foaming agents to produce a large amount of foam. Only about 1 % of the foam is made up of the foaming agent, the remaining 99 % being air and water. Small streams can have pockets of foam where fish hide from predators. However, foam can accumulate compounds that are repelled by water (hydrophobic), so foam can be enriched significantly with particulate organic and inorganic compounds such as nutrients (N, P, C), cations (K, Na, Ca, Mg), heavy metals (Cd, Cu, Fe, Pb, Zn) and chlorinated hydrocarbons. The organisms that inhabit the surface layer would be more exposed to these contaminants and this could form a pathway to introduce contaminants into the food web.

Q. Where have there been problems with excessive foam in British Columbia?

**A.** Foam complaints are infrequent but occur regularly on streams and lakes in British Columbia. Foam issues are typically more common on productive eutrophic lakes and brown tannin rich and turbid streams. However, low productivity oligotrophic lakes and relatively pristine high elevation lakes and streams have also had incidents with foam.

There have been several historical foam events that were related to specific circumstances. A recent discharge of manure contaminated runoff into Coldstream Creek created large banks of foam. A cyanobacteria bloom on Loon Lake was blown to the outlet where the thick algae mash constituted most of the flow in Loon Creek. Large banks of foam resulted from the release of algae organics downstream of turbulent reaches of the stream. Some foam complaints are blamed on discharges from pulp mills. On the Thompson River, downstream of the Kamloops pulpmill, foam was collected and analyzed for pulp tracer chemicals. No connection to the pulpmill effluent was found.

Environmental Protection Thompson Region Mailing Address: 1259 Dalhousie Drive Kamloops BC V2C 5Z5 Telephone: 250-371-6200 Facsimile: 250-828-4000 Website: www.gov.bc.ca/env



#### **References:**

Boswell, S. 2001. Foam Fact Sheet. Indiana Department of Environmental Management, Indianapolis, IN

Davis, J.C. 2005. What Causes Foam in Streams and Lakes? Aquatic Restoration and Research Institute, Talkeetna, Alaska. <u>http://www.arrialaska.org/foam-in-streams.html</u>

Fuller, D. 2003. The Occurrence of Foam on Lakes and Streams. Great Lakes Environmental Directory, Duluth MN <u>http://www.greatlakesdirectory.org/zarticles/012903\_great\_lakes1.htm</u>

Manitoba Water Stewardship. Natural Foam, Manitoba's Water Protection Handbook, pg. 41,

New Hampshire. 2001. Lake Foam. Environmental Fact Sheet BB-5. New Hampshire Department of Environmental Services, Concord NH. http://des.nh.gov/organization/commissioner/pip/factsheets/bb/documents/bb-5.pdf

Nordin, R. 2008. Lake Foam. BCLSS Newsletter Vol. 11/No. 1. BC Lake Stewardship Society, Kelowna B.C. http://www.bclss.org/library/library/cat\_view/58-quarterly-newsletters/92-volume-11.html

Pike, R. 2003. Foam: An Introduction. Streamline Watershed Management Bulletin, Vol. 7/No.3. B.C. Ministry of Forests. Victoria, B.C.

Thorpe, T. 2002. Lake Foam. The Waterline, Newsletter of the LVMP. Lakes of Missouri Volunteer Program. Columbia, MO. http://www.lmvp.org/Waterline/win

Personal communications with EIA biologists: Bob Grace, Vic Jenson, Mike Sokal, Chris Swan, Kym Keogh, Dennis Einarson and Tarik Dessouki.

Mailing Address: 1259 Dalhousie Drive Kamloops BC V2C 5Z5



Richard Slingerland Village Manager Village of Mamaroneck 123 Mamaroneck Avenue Mamaroneck, NY 10543

Subject: Sampling Due to Foam Observed in River Sampling Location: Halstead Avenue Bridge

Dear Mr. Slingerland:

At the Village of Mamaroneck's (Village) request, ARCADIS of New York (ARCADIS) collected samples from the Mamaroneck River due to concerns from area residents regarding foam in the Mamaroneck River. The origin and composition of the foam were not known, so the Village directed ARCADIS to sample the foam and to have it analyzed for common pollutants.

ARCADIS staff walked and observed areas along the Mamaroneck River from the Halstead Avenue bridge to the Jefferson Avenue bridge, as well as the Sheldrake River from the confluence with the Mamaroneck River to the Mamaroneck Avenue Bridge. Natural occurring foam was observed on the surface of both the Mamaroneck River and the Sheldrake River, particularly where there was turbulence. The area with the most foam was at the confluence of the Sheldrake and Mamaroneck Rivers. A sample of the foam was collected and observed. It was grayish white in color and there were no odors.

Samples were collected by ARCADIS on Friday May 29, 2015 just downgradient of the Halstead Bridge in the Mamaroneck River. This is the location that residents most recently called the Village with observations of foam. A sample of the foam and river water was collected in each sample bottle.

Photographs of the foam observed on the surface of the Mamaroneck and Sheldrake Rivers are provided as Appendix A, along with a field sketch showing the locations the photographs were taken. The sample was analyzed for fecal coliform, oil & grease, and anionic surfactants. Fecal coliform is present in high concentrations in wastewater and anionic surfactants are present in high concentrations in detergents and foaming agents. The standard test for surfactants is methylene blue active substances assay (MBAS).

The samples were tested by EnviroTest Laboratories, in Newburgh, NY. The lab is certified for environmental testing in New York, New Jersey, and Connecticut. The testing results were received by ARCADIS on June 4<sup>th</sup>. The complete testing results are provided as Appendix B. Table 1 on the next page provides a summary of the testing results.

ARCADIS of NY, Inc. 44 South Broadway 15th Floor Box 751 White Plains New York 10602-0751 Tel 914 694 2100 Fax 914 694 9286 www.arcadis-us.com

Water

Date: June 3, 2015

<sup>Contact:</sup> Kevin Hogan

Phone: 518-250-7306

Email: Kevin.Hogan@arcadisus.com

#### Imagine the result

Parameter	Result	Reporting Limit (RL)	Water Quality Standard
Fecal Coliform	1200 cfu\100 ml	100 cfu\100 ml	Geometric mean of five samples shall not exceed 200 cfu\100 ml
Oil and Grease	< 5.38 mg∖l	5.38 mg\l	No residue attributable to sewage, industrial wastes, or other wastes, nor visible oil film or globules of grease
Surfactants (MBAS)	0.26 mg\l	0.1 mg\l	No water quality standard. The limit commonly used in sampling stormwater to start performing further investigations is > 0.25 mg\l.

Table 1 – Summary of Analytical Results

The oil and grease sample was below the labs reporting limit. A reporting limit is the laboratory's limit of detection for the target analyte in a specific sample after adjustments have been made for dilutions or percent moisture. The surfactants concentration was low, but above the reporting limit, and the fecal coliform concentrations were elevated.

This surface foam on the Sheldrake and Mamaroneck Rivers has been observed and photographed by ARCADIS, the Village residents, and Village staff, but a source, such as stormwater outfall discharging foam, has never been identified. The physical appearance has been the same on both Rivers and it matches the appearance of naturally occurring foam presented in illicit discharge guidance documents. As discussed in the 4/20/2015 letter from the last round of sampling, the laboratory has indicated that if soap was the cause of the foam collected in the sample bottle, the MBAS concentration would have been well over 100 mg/l.

However, nonionic surfactants are used as a wetting agent for herbicides and pesticides. This time of year the application of herbicides and pesticides is high, so it seems feasible that runoff from application of these products could be contributing to a decrease in the surface tension of the water and aiding in the formation of small bubbles that constitute the foam.

Although the foam is not believed to be coming from a point source discharge, the elevated fecal coliform concentration should be investigated further. The elevated concentration could have been an isolated incident, but additional samples should be collected to determine if there is a source of an illicit discharge. We recommend additional sampling in this area of the stream, upgradient of the Halstead Avenue bridge and at outfalls in the vicinity of the Halstead Avenue bridge.



Please do not hesitate to contact me at 518-250-7306 if you have any questions or would like additional information.

Sincerely,

ARCADIS of NY, Inc.

Kevin Hogan, PE Senior Engineer

# **ARCADIS**

Appendix **A** 

Notes and Photos



# Project: Mamaroneck River

Photo No. Date: 05/29/15 1 Description:

Mamaroneck River just north of Station Plaza (looking east). Some foam visible.



Location: Mamaroneck, NY

# **ARCADIS**

### MAMARONECK RIVER

# Project: Mamaroneck River

Location: Mamaroneck, NY

Project No. 01547037.0000

Photo No.	Date:	
2	05/29/15	
Description	):	
Mamaronec north of Stat (looking nor foam visible	k River just ion Plaza th). Some	<image/>



#### Project: Mamaroneck River

Location: Mamaroneck, NY

**Project No.** 01547037.0000

 Photo No.
 Date:

 3
 05/29/15

 Description:
 Image: Content of the second seco

Sheldrake River at the confluence of Mamaroneck River (looking west). Heavy foam visible.



# **ARCADIS**

#### MAMARONECK RIVER

maroneck F	River	Location: Mamaroneck, NY	Project No. 01547037.0000
Date:			
05/29/15			
	<b>Date:</b> 05/29/15	maroneck River Date: 05/29/15	Date:     Location: Mamaroneck, NY

Sheldrake River at the confluence of Mamaroneck River (looking east). Heavy foam visible.





Project: M	amaroneck F	River	Location:	Mamaroneck, NY	<b>Project No.</b> 01547037.0000
Photo No.	Date:				
5	05/29/15			A CARLES AND A CARLES	Sector 1
Description Mamaroneo Jefferson A (looking nor visible.	<b>1:</b> k River at ve. bridge th). Foam				



Project: Mamaroneck River		Location: Mamaroneck	, NY	Project No. 01547037.0000	
Photo No. 6	<b>Date:</b> 05/29/15	Picor 11 11	ARS HEAL BRAND		
Description Mamaronec Jefferson Av (looking nor visible.	k River at /e. bridge th). Foam				



#### Project: Mamaroneck River

Location: Mamaroneck, NY

**Project No.** 01547037.0000



# **ARCADIS**

Project: Mamaroneck River	Location: Mamaroneck, NY	<b>Project No.</b> 01547037.0000
Photo No.         Date: 05/29/15		
Description: Mamaroneck River at Jefferson Ave. bridge (looking south). Some foam visible.		



# Project: Mamaroneck River

Location: Mamaroneck, NY

**Project No.** 01547037.0000





Project: Mamaroneck River	Location: Mamaroneck, NY	Project No. 01547037.0000
Photo No.       Date:         10       05/29/15         Description:       Mamaroneck River at Station Plaza bridge (looking southwest). Some foam visible.         Some foam visible.       Some foam visible.	<image/>	



Project: Mamaroneck River

Location: Mamaroneck, NY

**Project No.** 01547037.0000





Project: Mamaroneck River		Location: Mam	aroneck, NY	<b>Project No.</b> 01547037.0000	
Photo No.	Date:				
12	05/29/15	and the second	and a state of the	CARLON AND ALL AND	
Descriptior	า:				
Sheldrake F	River at		Same and the		and the second
footbridge h	alfway to			Contraction of the	1. 一方方子
Mamaroneo	k Ave.				
(looking we	st). Foam				
visible.		A A A A A A A A A A A A A A A A A A A			
			Alter Alt		
			1 - A 2 - ( )		
			P ASING A STATE		



**Project No.** 01547037.0000

#### Project: Mamaroneck River

 Photo No.
 Date:

 13
 05/29/15

 Description:
 Image: Content of the second sec

Sheldrake River at footbridge halfway to Mamaroneck Ave. (looking west). Foam visible.



Location: Mamaroneck, NY

# **ARCADIS**

Project: Ma	imaroneck F	River	Location:	Mamaroneck, NY	<b>Project No.</b> 01547037.0000
Photo No.	Date:				
14	05/29/15				
Description Sheldrake R footbridge ha Mamaroneck (looking east visible.	: alfway to Ave. t). Foam				



Project: Mamaroneck River	Location: Mamaroneck, NY	<b>Project No.</b> 01547037.0000
Photo No.       Date:         15       05/29/15         Description:         Sheldrake River at         footbridge halfway to         Mamaroneck Ave.         (looking west). Foam         visible.		



Project: M	amaroneck I	River	Location: Mamaroneck, NY	<b>Project No.</b> 01547037.0000
Photo No.	Date:			
16	05/29/15			
Description Sheldrake F confluence Mamaronec (looking we foam visible	n: River at the of k River st). Heavy			



**Project No.** 01547037.0000

#### Project: Mamaroneck River

 Photo No.
 Date:

 17
 05/29/15

 Description:

Mamaroneck River at the confluence of Sheldrake River (looking east). Heavy foam visible.



Location: Mamaroneck, NY

# **ARCADIS**

#### MAMARONECK RIVER

Project: M	amaroneck	River	Location: Mamaroneck,	NY	Project No. 01547037.0000
Photo No.	Date:				
18	05/29/15				
Descriptior	ו:				
Sheldrake F Mamaronec	River near k Ave				

Mamaroneck Ave. (looking north). Foam visible.





**Project No.** 01547037.0000

#### Project: Mamaroneck River

 Photo No.
 Date:

 19
 05/29/15

 Description:
 Image: Content of the second sec

Sheldrake River at Mamaroneck Ave. bridge (looking west). Foam visible.



Location: Mamaroneck, NY

# **ARCADIS**

Project: Ma	amaroneck	River	Location: Mamaroneck, NY	Project No. 01547037.0000
Photo No.	Date:			
20	05/29/15			
Description Sheldrake R Mamaronec bridge (look Foam visible	n: River at k Ave. ing north). e.			



Project: Mamaronec	River	Location:	Mamaroneck, NY	Project No. 01547037.0000
Photo No.       Date:         21       05/29/15         Description:         Jefferson street,         looking south under         railroad bridge. Waste         water from car wash         flowing into storm         drain. No soap         observed in flow.				



Project: M	amaroneck l	River	Location:	Mamaroneck, NY	Project No. 01547037.0000
Photo No.	Date:				
22	05/29/15				
Description Car Wash a intersection Ave. and Je (looking nor	n: of Halstead efferson St. theast).				



Photo No.       Date:         23       05/29/15         Description:         Mamaroneck River at         Halstead Ave. street         bridge, looking south.         Foam visible where         turbulence in the water         seems to occur.	Project: M	amaroneck F	River	Location:	Mamaroneck, NY	Project No. 01547037.0000
	Photo No. 23 Description Mamaronec Halstead Av bridge, look Foam visible turbulence i seems to oc	Date: 05/29/15 n: ck River at ve. street ing south. e where in the water ccur.				

# **ARCADIS**

Project: Mamaroneck	River	Location:	Mamaroneck, NY	<b>Project No.</b> 01547037.0000
Photo No. Date:				
24 05/29/15		1		
Description: Mamaroneck River at Halstead Ave. street bridge, looking south. Foam visible where turbulence in the water seems to occur (especially in the distance).				



Project No.

01547037.0000

#### Project: Mamaroneck River

 Photo No.
 Date:

 25
 05/29/15

 Description:
 Image: Control of the second sec

Mamaroneck River at Halstead Ave. railroad bridge, south side, looking northeast. Minimal foam visible not much turbulence in the moving water.



Location: Mamaroneck, NY

# **ARCADIS**

#### **MAMARONECK RIVER**

 
 Project: Mamaroneck River
 Location: Mamaroneck, NY
 Project No. 01547037.0000

Photo No.	Date:			
26	05/29/15			
Description:				

Mamaroneck River at Halstead Ave. railroad bridge, south side, looking northwest. Minimal foam visible not much turbulence in the moving water.





Project: Mar	maroneck River	Location: Mamaroneck, NY	Project No. 01547037.0000
Photo No. 27 Description: Mamaroneck Halstead Ave bridge, north looking west. foam visible - turbulence in moving water	Date: 05/29/15 River at . street side, Minimal not much the		

Τ

# **ARCADIS**

### MAMARONECK RIVER

Т

Project: Mamaroneck R	iver	Location: Mamaroneck, NY	Project No. 01547037.0000
Photo No. 28Date: 05/29/15Description:Mamaroneck River at Halstead Ave. railroad 			



**Project No.** 01547037.0000

#### Project: Mamaroneck River

Mamaroneck River just north of railroad bridge, eastern shore (looking south). Foam, organic matter visible.



Location: Mamaroneck, NY

# **ARCADIS**

Project: Mama	aroneck R	liver	Location:	Mamaroneck, NY	Project No. 01547037.0000
<b>Photo No.</b> 30 0	<b>Date:</b> 5/29/15				
Description: Mamaroneck R north of railroad eastern shore ( south). Foam, o matter visible.	liver just d bridge, looking organic				

# **ARCADIS**

Appendix **B** 

Analytical Results



#### ANALYTICAL REPORT

Job Number: 420-90859-1

Job Description: Mamaroneck

For: Arcadis US, Inc. 855 Route 146 Suite 210 Clifton Park, NY 12065

Attention: Mr. Kevin Hogan

Bereem. Cusack

Renee Cusack Lab Director rcusack@envirotestlaboratories.com 06/05/2015

cc: Ms. Katherine Clubine

NYSDOH ELAP does not certify for all parameters. EnviroTest Laboratories does hold certification for all analytes where certification is offered by ELAP unless otherwise specified. Pursuant to NELAP, this report may not be reproduced, except in full, without written approval of the laboratory. EnviroTest Laboratories Inc. certifies that the analytical results contained herein apply only to the samples tested as received by our laboratory. All questions regarding this report should be directed to the EnviroTest Customer Service Representative.

EnviroTest Laboratories, Inc. Certifications and Approvals: NYSDOH 10142, NJDEP NY015, CTDOPH PH-0554





#### **METHOD SUMMARY**

Client: Arcadis US, Inc.

Job Number: 420-90859-1

Description	Lab Location	Method Preparation Method
Matrix: Water		
HEM and SGT-HEM by Extraction and Gravimetry HEM and SGT-HEM by Extraction and	EnvTest EnvTest	1664A 1664A 1664A 1664A
Membrane Filter Technique - Fecal Coliform Procedure	EnvTest	SM18 SM 9222D-97
Anionic Surfactants as MBAS	EnvTest	SM21 SM5540C-00,11

#### Lab References:

EnvTest = EnviroTest

#### Method References:

1664A = EPA-821-98-002

SM18 = "Standard Methods For The Examination Of Water And Wastewater", 18th Edition, 1992.

SM21 = "Standard Methods For The Examination Of Water And Wastewater", 21st Edition

#### METHOD / ANALYST SUMMARY

Client: Arcadis US, Inc.

Method	Analyst	Analyst ID
1664A 1664A	Vollmer, William	WB
SM18 SM 9222D-97	Travis, Lyndsey	LT
SM21 SM5540C-00,11	Miller, Kyle A	KAM

#### SAMPLE SUMMARY

Client: Arcadis US, Inc.

Job Number: 420-90859-1

			Date/Time	Date/Time
Lab Sample ID	Client Sample ID	Client Matrix	Sampled	Received
420-90859-1	"SW-MAM-Halstead-S-201 5-05-29"	Water	05/29/2015 0945	05/29/2015 1230

Job Number: 420-90859-1

Mr. Kevin Hogan Arcadis US, Inc. 855 Route 146 Suite 210 Clifton Park, NY 12065

Client Sample ID: Lab Sample ID:	"SW-MAM-Halstead-S-2015-0 420-90859-1	)5-29"	Dat Dat Clie	te Sampled: te Received: ent Matrix:	05/29/2015 05/29/2015 Water	0945 1230	
Analyte	Re	sult/Qualifier	Unit			RL	Dilution
Method: 1664A			Date A	nalyzed:	06/03/2015	1030	
Prep Method: 1664A			Date P	repared:	06/03/2015	1030	
HEM	<	5.38	mg/L		:	5.38	1.0
SGT-HEM	<	5.38	mg/L		:	5.38	1.0
Method: SM5540C-0	0,11		Date A	nalyzed:	05/29/2015	1000	
MBAS	0	.260	mg/L		(	0.100	1.0
Method: SM 9222D-9	17		Date A	nalyzed:	05/29/2015	1645	
Coliform, Fecal	1	200	CFU/100m	ιL		100	100

EnviroTest Laboratories Inc.	CHAIN OF CUS	STODY	315 Fullerton Avenue Newburgh, NY 12550 TEL (845) 562-0890 FAX (845) 562-0841
CUSTOMER NAME A R C A D I S	REPORT TYPE	TURNAROUND	REPORT # (Lab Use Only)
ADDRESS ADDRESS	STANDARD   ISRA		653an
OITVERATEZE		D QUICK	SAMPLE TEMP. C S C C
C/1 Ftes Per K, NY (206 NAME OF CONTACT	OTHER OTHER		
Kevin Hogan (518) 250 73	0 6		
MAMARONECK NY	Matrix		REVIEWED BY:
PROJECT NUMBER / PO NO.	DW = DRINKING WATER WW = WASTE WATER SL = SLUD	S = SOIL 0 = OIL GE GW = GROUND WATER	NY PUBLIC WATER SUPPLIES
NOTE: SAMPLE TEMPERATURE UPON			
RECEIPT MUST BE 4° ≖ 2°C.	blastic blasti	Class Plastic Plastic Plastic	ELAP TYPE
ETL DATE TIME OF MATRIX CLIENTID	Seoull Seoull Seoull Seoull Seoull Seoull Seoull Claure Seoull Claure Seoull Claure Seoull Claure Seoull Claure Seoull Claure Seoull Claure Seoull Se		
			DRAS Fred Outo
5/29/15 0945 VSW-MAM- Halsteat-	5-2015-05-29"	<u>~</u>	
*	X		
. X	X		
			7
5		> please call	Kevin Hogen
			1250-7306
			714 +
		2	
			torast, etc.
			I hank four
·			
SAMPLES SUBMITTED FOR ANALYSIS WILL BE SUBJECT TO THE ETL	TERMS AND CONDITIONS OF SALE UNLESS ALTERN	ATE TERMS ARE AGREED IN WRITIN	°.
RELINQUISHED BY Drvid Fosizen ARCANS SAMPIED BY	S 29 15 TIME RECEIVER		MPANY EST S/29/15 11:15 MPANY DATE TIME
RELIMOULS COMPANY	S/JE/ 5 TIME 230 RECEIVED	DBV Kade 00	MANY CATE 12:30
COMMENTS			
	>		

.

06/05/2015

.

EPA NY00049

СТООРН РН-0554

NJDEP NY015

NYSDOH 10142

#### LOGIN SAMPLE RECEIPT CHECK LIST

Client: Arcadis US, Inc.

Job Number: 420-90859-1

#### Login Number: 90859

T/F/NA	Comment
NA	
NA	
True	
True	
True	6.5 C
True	
NA	
True	
True	
True	
	T/F/NA         NA         NA         True         True
# **APPENDIX E**

Gasoline Odor Investigation Photo Log





Photo filename (.jpg): CB1 Catch basin was dry but had sediment buildup. No odors, flow, or evidence of oil or gasoline present.



Photo filename (.jpg): CB2 Catch basin had some stagnant water; many gas mains are near the catch basin. No odors or evidence of gasoline or odor observed.

2

1



01/25/2016 C:\Users\csuperak\Documents\Mamaroneck Photo Log\Photolog\_20150716\_3.m



3

4

Photo filename (.jpg): CB3 Catch basin was dry. No odors or evidence of oil or gasoilne.



Photo filename (.jpg): Recent Water Main lateral work near CB3 Recent water main lateral work near CB3.

Village of Mamaroneck Mamaroneck, NY Illicit Discharge Detection and Elimination

Gasoline Odor Investigation 07–16–2015

ARCADIS Design & Consultancy for natural and built assets

01/25/2016 C:\Users\csuperak\Documents\Mamaroneck Photo Log\Photolog\_20150716\_3.m APPENDIX

Ε



Photo filename (.jpg): Recent work near Sanitary Manhole



Photo filename (.jpg): CB4 Catch basin was dry. No odors or evidence of oil or gasoline residue.

6

5



01/25/2016 C:\Users\csuperak\Documents\Mamaroneck Photo Log\Photolog\_20150716\_3.m



7

Photo filename (.jpg): CB4.1 Catch basin 4 close up view.



Photo filename (.jpg): Sanitary Manhole 1 No evidence of oil or gasoline. No odd smells. Recent construction activity in vicinity of manhole.



8





Photo filename (.jpg): Storm Manhole No odor and no evidence of oil, grease, or gasoline.



Photo filename (.jpg): CB6 Catch basin had some stagnant water and sediment and leaf buildup. No odors or evidence of oil or gasoline. 12



11



13

Photo filename (.jpg): CB7 Catch basin had flow, but no odors. No evidence or oil or gasoline.



Photo filename (.jpg): Outfall Outfall was wet, but there were no signs of gasoline, oil or grease. It was very muddy and smelled like a swamp or marsh, but there were no abnormal smells.

Village of Mamaroneck Mamaroneck, NY

**Illicit Discharge Detection and Elimination** 

14

**Gasoline Odor Investigation** 07-16-2015

Design & Consultancy for natural and built assets

ARCADIS

APPENDIX

Ε



15

Photo filename (.jpg): Outfall 2



Photo filename (.jpg): Vegetation near outfall Vegetation prevented Arcadis staff from viewing water body. 16





Photo filename (.jpg): Wooded Area left of outfall Vegetated area was investigated for evidence of oil dumping. Nothing was found.



Photo filename (.jpg): Wooded Area left of outfall 1 Vegetated area was investigated for evidence of oil dumping. Nothing was found.

18

17



01/25/2016 C:\Users\csuperak\Documents\Mamaroneck Photo Log\Photolog\_20150716\_3.m



Photo filename (.jpg): More recent Work (far) Recent roadwork covered by metal plates.

19

Village of Mamaroneck Mamaroneck, NY

Illicit Discharge Detection and Elimination

Gasoline Odor Investigation 07–16–2015

Design & Consultancy for natural and built assets

ARCADIS

01/25/2016 C:\Users\csuperak\Documents\Mamaroneck Photo Log\Photolog\_20150716\_3.m APPENDIX

Ε

# **APPENDIX F**

River Sampling Results Map





CITY: CLIFTON PARK, NY DIV/GROUP: WTR DB: CMS LD: PIC: PM: KCH APM: TM: PROJECT: VILLAGE OF MAMARONECK 2015 IDDE PATH: G:\GISMOD\01547034.0000\ArcadisRiverSampling2015.mxd

# **APPENDIX G**

**DNA Sampling Results** 





### Appendix G Summary of DNA Sampling Results

Lab Name	Sample Name	Sample Date	Date Received	Sample Matrix	LIMS Identifier	Extraction Date	Analysis Date	Analysis Method	Parameter	Result	Result Qualifier	Units	Detection Limit	Report Limit
MI	Jefferson 1	9/16/2015	9/17/2015	Water	056MI-1	9/18/2015	9/22/2015	CENSUS	DBACT	4.1	J	gene copies/mL	1.00E-01	4.80E+00
MI	Jefferson 1	9/16/2015	9/17/2015	Water	056MI-1	9/18/2015	9/22/2015	CENSUS	GenBac	245	=	gene copies/mL	1.00E-01	4.80E+00
MI	Jefferson 1	9/16/2015	9/17/2015	Water	056MI-1	9/18/2015	9/22/2015	CENSUS	H-EPA1	3360	=	gene copies/mL	1.00E-01	4.80E+00
MI	Jefferson 1	9/16/2015	9/17/2015	Water	056MI-1	9/18/2015	9/22/2015	CENSUS	H-EPA2	5	<	gene copies/mL	1.00E-01	4.80E+00
MI	Jefferson 1	9/16/2015	9/17/2015	Water	056MI-1	9/18/2015	9/22/2015	CENSUS	HF183	4.8	<	gene copies/mL	1.00E-01	4.80E+00
MI	Jefferson 1	9/16/2015	9/17/2015	Water	056MI-1	9/18/2015	9/22/2015	CENSUS	Gull-CAT	4.8	<	gene copies/mL	1.00E-01	4.80E+00
MI	Jefferson 1	9/16/2015	9/17/2015	Water	056MI-1	9/18/2015	9/22/2015	CENSUS	CG BACT1	0.9	J	gene copies/mL	1.00E-01	4.80E+00
MI	Jefferson 1	9/16/2015	9/17/2015	Water	056MI-1	9/18/2015	9/22/2015	CENSUS	CG BACT2	0.3	J	gene copies/mL	1.00E-01	4.80E+00
MI	Jefferson 2	9/16/2015	9/17/2015	Water	056MI-2	9/18/2015	9/22/2015	CENSUS	DBACT	3.4	J	gene copies/mL	1.00E-01	4.70E+00
MI	Jefferson 2	9/16/2015	9/17/2015	Water	056MI-2	9/18/2015	9/22/2015	CENSUS	GenBac	421	=	gene copies/mL	1.00E-01	4.70E+00
MI	Jefferson 2	9/16/2015	9/17/2015	Water	056MI-2	9/18/2015	9/22/2015	CENSUS	H-EPA1	1710	=	gene copies/mL	1.00E-01	4.70E+00
MI	Jefferson 2	9/16/2015	9/17/2015	Water	056MI-2	9/18/2015	9/22/2015	CENSUS	H-EPA2	5	<	gene copies/mL	1.00E-01	4.70E+00
MI	Jefferson 2	9/16/2015	9/17/2015	Water	056MI-2	9/18/2015	9/22/2015	CENSUS	HF183	4.7	<	gene copies/mL	1.00E-01	4.70E+00
MI	Jefferson 2	9/16/2015	9/17/2015	Water	056MI-2	9/18/2015	9/22/2015	CENSUS	Gull-CAT	4.7	<	gene copies/mL	1.00E-01	4.70E+00
MI	Jefferson 2	9/16/2015	9/17/2015	Water	056MI-2	9/18/2015	9/22/2015	CENSUS	CG BACT1	0.3	J	gene copies/mL	1.00E-01	4.70E+00
MI	Jefferson 2	9/16/2015	9/17/2015	Water	056MI-2	9/18/2015	9/22/2015	CENSUS	CG BACT2	0.3	J	gene copies/mL	1.00E-01	4.70E+00
MI	Shel/Mam 1	9/16/2015	9/17/2015	Water	056MI-3	9/18/2015	9/22/2015	CENSUS	DBACT	1.8	J	gene copies/mL	1.00E-01	4.70E+00
MI	Shel/Mam 1	9/16/2015	9/17/2015	Water	056MI-3	9/18/2015	9/22/2015	CENSUS	GenBac	276	=	gene copies/mL	1.00E-01	4.70E+00
MI	Shel/Mam 1	9/16/2015	9/17/2015	Water	056MI-3	9/18/2015	9/22/2015	CENSUS	H-EPA1	5	<	gene copies/mL	1.00E-01	4.70E+00
MI	Shel/Mam 1	9/16/2015	9/17/2015	Water	056MI-3	9/18/2015	9/22/2015	CENSUS	H-EPA2	37400	=	gene copies/mL	1.00E-01	4.70E+00
MI	Shel/Mam 1	9/16/2015	9/17/2015	Water	056MI-3	9/18/2015	9/22/2015	CENSUS	HF183	4.7	<	gene copies/mL	1.00E-01	4.70E+00
MI	Shel/Mam 1	9/16/2015	9/17/2015	Water	056MI-3	9/18/2015	9/22/2015	CENSUS	Gull-CAT	4.7	<	gene copies/mL	1.00E-01	4.70E+00
MI	Shel/Mam 1	9/16/2015	9/17/2015	Water	056MI-3	9/18/2015	9/22/2015	CENSUS	CG BACT1	0.2	J	gene copies/mL	1.00E-01	4.70E+00
MI	Shel/Mam 1	9/16/2015	9/17/2015	Water	056MI-3	9/18/2015	9/22/2015	CENSUS	CG BACT2	4.7	<	gene copies/mL	1.00E-01	4.70E+00
MI	Shel/Mam 2	9/16/2015	9/17/2015	Water	056MI-4	9/18/2015	9/22/2015	CENSUS	DBACT	3.8	J	gene copies/mL	1.00E-01	4.80E+00
MI	Shel/Mam 2	9/16/2015	9/17/2015	Water	056MI-4	9/18/2015	9/22/2015	CENSUS	GenBac	493	=	gene copies/mL	1.00E-01	4.80E+00
MI	Shel/Mam 2	9/16/2015	9/17/2015	Water	056MI-4	9/18/2015	9/22/2015	CENSUS	H-EPA1	908	=	gene copies/mL	1.00E-01	4.80E+00
MI	Shel/Mam 2	9/16/2015	9/17/2015	Water	056MI-4	9/18/2015	9/22/2015	CENSUS	H-EPA2	9950	=	gene copies/mL	1.00E-01	4.80E+00
MI	Shel/Mam 2	9/16/2015	9/17/2015	Water	056MI-4	9/18/2015	9/22/2015	CENSUS	HF183	4.8	<	gene copies/mL	1.00E-01	4.80E+00
MI	Shel/Mam 2	9/16/2015	9/17/2015	Water	056MI-4	9/18/2015	9/22/2015	CENSUS	Gull-CAT	4.8	<	gene copies/mL	1.00E-01	4.80E+00
MI	Shel/Mam 2	9/16/2015	9/17/2015	Water	056MI-4	9/18/2015	9/22/2015	CENSUS	CG BACT1	0.6	J	gene copies/mL	1.00E-01	4.80E+00
MI	Shel/Mam 2	9/16/2015	9/17/2015	Water	056MI-4	9/18/2015	9/22/2015	CENSUS	CG BACT2	4.8	<	gene copies/mL	1.00E-01	4.80E+00

Notes:

GenBac General Bacteroides

H-EPA1 Human Bacteroides

H-EPA2 Human Bacteroides

HF183 Human Bacteroides

Gull-CAT Sea Gull Bacteroides

CG BACT1 Canadian Goose

CG BACT2 Canadian Goose

DBACT Dog Bacteroides



10515 Research Drive Knoxville, TN 37932 Phone: (865) 573-8188 Fax: (865) 573-8133

Client:	Kevin Hogan Arcadis 855 Route 146 Suite 210			Phone:	518-250-7306
	Clifton Park, NY	12065		Fax:	518-250-7301
Identifier:	056MI	Date Rec:	09/17/2015	Repo	ort Date: 09/22/2015
Client Proj	ect #: 01547038.0	0000	Client Proje	ct Name: Vill	age of Mamavoneck IDDE
Purchase (	Order #:				
Analysis R	equested:	CENSUS			

**Reviewed By:** 

Jow

NOTICE: This report is intended only for the addressee shown above and may contain confidential or privileged information. If the recipient of this material is not the intended recipient or if you have received this in error, please notify Microbial Insights, Inc. immediately. The data and other information in this report represent only the sample(s) analyzed and are rendered upon condition that it is not to be reproduced without approval from Microbial Insights, Inc. Thank you for your cooperation. 10515 Research Dr., Knoxville, TN 37932 Tel. (865) 573-8188 Fax. (865) 573-8133

Client: Arcadis

Project: Village of Mamavoneck IDDE

### Sample Information

MI Project Number:	056MI
Date Received:	09/17/2015

Client Sample ID:		Jefferson 1	Jefferson 2	Shel/Mam 1	Shel/Mam 2
Sample Date:		09/16/2015	09/16/2015	09/16/2015	09/16/2015
Units:		gene copies/mL	gene copies/mL	gene copies/mL	gene copies/mL
Analyst:		JS	JS	JS	JS
vlogenetic Group					
Canada Goose Bacteroidetes	CG BACT1	9.00E-01 (J)	3.00E-01 (J)	2.00E-01 (J)	6.00E-01 (J)
Canada Goose Bacteroidetes	CG BACT2	3.00E-01 (J)	3.00E-01 (J)	<4.70E+00	<4.80E+00
General Bacteroidetes	GenBac	2.45E+02	4.21E+02	2.76E+02	4.93E+02
Human Associated Bacteroidetes	H-EPA1	3.36E+03	1.71E+03	<4.70E+00	9.08E+02
Human Associated Bacteroidetes	H-EPA2	<4.80E+00	<4.70E+00	3.74E+04	9.95E+03
Dog Bacteriodetes	DBACT	4.10E+00 (J)	3.40E+00 (J)	1.80E+00 (J)	3.80E+00 (J)
Human Associated Bacteroidetes	HF183	<4.80E+00	<4.70E+00	<4.70E+00	<4.80E+00
Gull (Catellicoccus sp.)	Gull-CAT	<4.80E+00	<4.70E+00	<4.70E+00	<4.80E+00

### Legend:

NA = Not Analyzed NS = Not Sampled J = Estimated gene copies below PQL but above LQL I = Inhibited

< = Result not detected

# **APPENDIX H**

Grouting Pilot - CCTV Inspection Logs and Videos on CD



## CCTV Inspection and Lateral Grouting Rushmore Avenue Mamaroneck, NY September 2015

FOR:

Village of Mamaroneck 123 Mamaroneck Avenue Mamaroneck, NY 10543

Sewer System Maintenance Rehabilitation Programs C.C.T.V. Inspection Flow Reduction Programs System Surveys Hydraulic Flow Studies Trenchless Rehabilitation

> Phone (860) 274-5469 Fax (860) 945-3219

# PRD North Division HEITKAMP, Inc.

99 CALLENDER ROAD P.O. BOX 730 WATERTOWN CT 06795-0730





PRD North Division Heitkamp, Inc. Phone: (860) 274.5469 Watertown, CT 06795 Fax: (860) 945.3219 99 Callender Road



# **MAMARONECK NY TK-428**

Project Summary

Main ID	Date	Address	Start MH	Finish MH	Pipe As	set length Surveyed Le	anoth
MAMARONECK-1	9/21/2015	RUSHMORE AVE - LSS	65982	65981	ZZZ		245.0
MAMARONECK-2	9/21/2015	RUSHMORE AVE - LSS	65773	65772	ZZZ	251.0 2	251.0
MAMARONECK-3	9/21/2015	RUSHMORE AVE - LSS	65772	65771	ZZZ	214.0 2	214.0
MAMARONECK4	9/21/2015	RUCHMORE AVE - LSS	65771	65770	ZZZ	203.0	03.0
MAMARONECK-5	9/22/2015	RUSHMORE AVE - LSS	65769	65762	ZZZ	348.0 3	148.0
MAMARONECK-6	9/22/2015	RUSHMORE AVE - LSS	65980	65759	ZZZ	264.0	64.0
MAMARONECK-7	9/22/2015	RUSHMORE AVE - LSS	65835	65834	CAS	166.0 1	.66.0
MAMARONECK-8	9/22/2015	RUSHMORE AVE - LSS	65762	65761	ZZZ	e	51.0
MAMARONECK-10	9/23/2015	RUSHMORE AVE - TV	65829	65828	CAS	70.0	70.0

Wednesday, October 07, 2015 4:07 PM

Project Summary

2 of ----

Page

RD North Division Heitkamn Toc	9 Callender Road	/atertown, CT 06795	hone: (860) 274.5469	ax: (860) 945.3219
PRD	0 66	Wate	Phon	Fax:

		4	e
1		CAN	
-	-	Ē	un C
		ī	Ŧ

Main ID	Date	Address	Start MH	Finish MH	Dine	Accet locath Curried	
MAMARONECK-11	9/23/2015	RUSHMORE AVE - TV	65828	65826	CAS	Asset lefigtil bulveyed 186.0	186.0
MAMARONECK-12	9/23/2015	RUSHMORE AVE - TV	65826	65825	CAS	150.0	149.0
MAMARONECK-13	9/23/2015	RUSHMORE AVE - TV	65825	65801	CAS	209.0	209.0
MAMARONECK-9	9/23/2015	RUSHMORE AVE - TV	65834	65829	CAS	170.0	170.0
Number of inspections:	13			Subtot	Ter I	2,231.0 ft 2,820	5.0 ft

2,826.0 ft

2,231.0 ft

Total

Wednesday, October 07, 2015 4:07 PM

Project Summary

Page 2 of

2



PRD North Division Heitkamp, Inc. 99 Callender Road Watertown, CT 06795 Phone: (860) 274.5469 Fax: (860) 945.3219



### Main Inspection with Pipe-Run Graph Project Name: Pipeline segment ref: City: Street: MAMARONECK NY TK-428 MAMARONECK-1 MAMARONECK RUSHMORE AVE - LSS TK-428 Start date/time: Width: Height: Material: Location code: Weather: 9/21/2015 10 ZZZ Direction: Length surveyed: Surveyed by: Additional info: Downstream 245.0 J.PEROTTI At 0.0 ft START WITH FLOW - Start Inspection With the Flow 65982 0 ↓ At 0.0 ft AMH - Manhole MH# 65928 ↓ At 0.0 ft MWL - Water Level ∦ At 94.7 ft 12/. TFA - Tap Factory Active 0 1 FT T 100 0 ft Asset length: 245.0 ft, Surveyed length: 245.0 ft 200.0 11 ♦ At 245.0 ft AMH - Manhole MH# 65981 At 245.0 ft STOP - In spection stopped 0 65981

tD North Division Heitkamp, Inc.	) Callender Road	atertown, CT 06795	ione: (860) 274.5469	x: (860) 945.3219
PRD N	99 Cal	Water	Phone	Fax: (

-	AMP	ANY NA	
	Ě	COMP	
	Ï	AN	

|--|

Remarks	MH# 65928			1 FT T	MH# 65981	
Image Ref.						
Circumferential Location At/From to			10	77		
Joint						
\$		5				
Value : (mm) 2nd						
Inches 1st			9			
ect S/M/L						
ntinuous Def						
Modifier/ Co Severity				+		
Group/ Descriptor	AMH	MWL	TFA		AMH	
Video Ref.	13	26	1122		1539	
Distance (Feet) (Meters)	0.0	0.0	94.7		245.0	

1						1			-	 	 -	 	 		-	-
5082						1865	OMP- TED	SALED	15							
9				EY		65	CC	IR TESTED	v		1					
# HW			←	surv		# HW	ISH ST	3MOH TA TO	N							
0-				3		-0	FLI	ONNECTION CLEAR	э							
			$\leftarrow$	÷10			E1	A SECONDS IME OF TEST	T 11							
		ī					CKAG AIR EST	SSO	n '							
							BLO	an	a .							
				r				TAAT	s '							
	AREA:							N SECONDS LIME OF TEST	30						1	
L			r.		E		OST ALING & TEST	SSO	I ·						OF SEALS:	
POR				:ING:	PERO		SE,	ana	6.0							
<b>RE</b>	പ			T SPAC	ſ			TAATS	6.0						10 #	
ALINC	IORE AV		~	NIOF			ICAL UT GE	CALLONS							0	SED:
AND SE	RUSHN		NSPECTO		REMAN:		CHEM GRO USA	STROKES	,						ALLONS:	F SOCKS L
TEST /		THER:	-	10"	FC			(SECONDS) LIME OF TEST	30					+	-	0#
AIR '		WEA					R ST ILTS	SSOT						+	TS:	
TION	TION:			METER			AI TE RES(	END	0						L AIR TES	
NEC	LOCA	/2015		PIPE DIA				TAATS	0						TOTAL	-
COL		9/21		-			NOI	отнек	z					+	TOT TOT	
DUSE		DATE:			TIME:		HOUSE	ROOTS	z					1		ALED:
HC	CK NY				JT GEL		PF	PROTRUDING TAP (IN)	z					$\uparrow$		AND SE
	MAMARONE		R-INDEX:	iGTH:	GROUT GE		LEAKAGE (GPM)	(мар) этая	NO TEST						CES IN LINE:	CES TESTED
			LA	ON LEN		Γ		HC SIZE	4					1	SERVI	SERVIG
				SECTIO				HC LADE	Ľ.						BER OF	ER OF
	CLIENT:				/-100	NOIL.	D TYPE	евом мн#	X				-	-	MUN	NUMB
				LINED	A.	HOLISE CONNE	LOCATION AN	DISTANCE (FT)	95							
		NUMBER:	NUMBER	IPE TYPE:	UT TYPE:		-	# JSUOH	1 FT T						S:	
		JOB	TAPE	Р	GRO			#HC INFINE					-	1	OTAI	

F FACTORY

**B** BREAK IN

HOUSE CONNECTION ABBREVIATIONS:

PRD North Division Heitkamp, Inc. 99 Callender Road Watertown, CT 06795 Phone: (860) 274.5469 Fax: (860) 945.3219





Page 1 of 2

weanesday, October 07, 2015 4:09 PM

) North Division Heitkamp, Inc.	Callender Road	tertown, CT 06795	ne: (860) 274.5469	: (860) 945.3219
PRD No	99 Call	Vatert	shone:	ax: (8

1	1 N .
	ITKA S P
	Ē

		The Party of Lot, No. of Lot,	-
Sheet number:			
eline segment ref: AMARONECK-2	Remarks	MH# 65772	
Pip. MA	Image Ref.		
ä	Circumferential Location	01	
m manhole No	Joint		-
Upstrea 6577	%		
art date/time: 015/09/21	Value Inches (mm) 1st 2nd		
SI SI	J/W/S		
	Continuous Defect		
ner:	Modifier/ r Severity		
MO	Group/ Descripto	АМН	
	Video Ref.	1394	
Surveyed by: J.PEROTTI	Distance (Feet) (Meters)	251.0	

Wednesday, October 07, 2015 4:09 PM

	1						1				<b>—</b>			-	 	-				-	
	55773						5772	OMP- ETED		EALED	is >										
					/EY		0	53		IR TESTED	v >								1		
	# HW			$\leftarrow$	SUR\ ↓		# HW	ISH ST		<b>JMOH TA TO</b>	N >								1		
	0-				3	-	-0	FLI		ONNECTION CLEAR	>								1		
				<del>(</del>	+L0			6		A SECONDS IME OF TEST	II								1		
			ī					CKAG AIR EST		SSO'	1								1		
								BLO		ana	4 ·								1		
					ř	1 8				TAAT	s '								1		
, INC.	G REPORT	AREA:								N SECONDS LIME OF TEST	30								-		
AMP						E		OST NLING		SSOT	1								ä		
JTK					ING:	PERO		P SE/		GND	6.0								SEAL		
NHE		ш			F SPAC	ſ.				TAATS	6.0								10 #		
VISIO	ALINC	<b>JORE AV</b>			NIOF			ICAL UT GE		CALLONS	3.5								3.5	SED:	
ANY DI	AND SE	RUSHN		INSPECTO		DREMAN:		CHEM GRO USA		SEROKES	,								ALLONS:	F SOCKS U	
COMP.	EST		HER:		10"	E				(SECONDS)	30								_	0#	
ING C	AIR T		WEATHE					R ST ILTS		SSOT									TS:		
ND PIPE CLEANI	ION	:NOI			AETER			AI TE RESU		GND	0								IR TES		
	NECT	LOCAT	/2015		IPE DIAN					TAAT2	0	_						_	TOTAL A	-	
	CO		9/21					ON 1S		язнто	z						+	+	<u> </u> Ĕ	]	
SLAP	DUSE		DATE:			TIME:		HOUSE		SLOON Z						ALED:					
ENC	H	CK NY				IT GEL		COL	(NI	РВОТВОЛИСТАР (	z									AND SE	
NEW		MAMARONE		FR INDEX:	HLDN:	GROL		LEAKAGE (GPM)		RATE (GPM)	z								CES IN LINE:	CES TESTED	
				5	ON LEI					<b>JZIS OH</b>	9								SERVI	SERVIG	
					SECTI					НС ТҮРЕ	٤.,								<b>BER OF</b>	ER OF	
		CLIENT:				V-100		D TYPE		£773 крани кояз	Y							-	NUMB	NUMB	
		9988D/			: LINED	N.		HOUSE CONN LOCATION AN		DISTANCE (FT)	212				,						
			NUMBER:	NUMBER	IPE TYPE	UT TYPE:				# 3SUOH									S:		
			lob	TAPE	4	GRO	L			#HC INFINE									TOTAL		

F FACTORY

**B** BREAK IN

HOUSE CONNECTION ABBREVIATIONS:

PRD North Division Heitkamp, Inc. 99 Callender Road Watertown, CT 06795 Phone: (860) 274.5469 Fax: (860) 945.3219





Page 1 of 1

Wednesday, October 07, 2015 4:09 PM

PACP Sewer Report

Page 1 of 1

	5							4.9	SEALED	s >						1	]
	6577						6577	COMI				+				-	
	# H			TURVEY	$\rightarrow$		 # H		AND IN THE STATE							-	
	₹ ()-		()					FLUSH	CONNECTION CLEAR	~			1			-	
	$\bigcirc$			↑ FLOW	$\rightarrow$		$\bigcirc$		IN SECONDS LIME OF TEST			+				1	
								IR IR ST	SSOT							1	
								BLOC A TE	END							1	
				2					TAATZ	1						1	
INC.		AREA:							HINE OF TEST						-		
AMP,	<u> </u>					L		POST ALING R TEST	sson	r						S:	
JTK	PORT				:SNI	PEROT		P SE	END	6.0						OF SEAL	
NHE	<b>RE</b>	ы			T SPAC	ſ.			TAAT2	6.0						S: 5 #0	
VISIO	ALING	IORE AV		~	NIOF			ICAL UT GE	CALLONS	5							USED:
ANY DI	AND SE	RUSHN		NSPECTOR		REMAN:		CHEM GRO USA	STROKES	1						GALLONS:	OF SOCKS
OMP	<b>FEST</b> /		THER:	-	**8	FC			(SECONDS) LIME OF TEST	30						-	)#
GLAND PIPE CLEANING (	AIR 7		WEA'					R ST JLTS	5507							STS:	
	TION	TION:	1		METER			AL	ana	0						LAIR TH	
	NEC	LOCA	/2015		PIPE DIA		1		TAAT2	0						TOTAL	-
	CO		9/21		_			NOL	отнек	z							
	OUSE		DATE			TIME:		HOUSI NNECT ROBLE	STOOA.	z							EALED
ENG/	Н	CK NY				JT GEL		CO PI	<b>рвот</b> вирійс тар (іи)	z							AND S
NEV		MAMARONE		R INDEX:	GTH:	GROI		LEAKAGE (GPM)	RATE (GPM)	z						CES IN LINE	CES TESTED
		2		VT	ON LEN				HC SIZE	4						SERVI	SERVI
					SECTIC				НС ТАРЕ	í۲.						BER OF	BER OF
		CLIENT:				V-100		ECTION VD TYPE	12259 #НМ ЮОЗЭ	×						IMUN	NUME
					LINED	V		HOUSE CONN LOCATION AP	DISTANCE (FT)	8							
			<b>NUMBER:</b>	E NUMBER	PIPE TYPE:	OUT TYPE:			# 3SUOH							ALS:	
			JOE	TAP	_	GROUT	GROU		#HC INFINE							TOT	

F FACTORY

**B** BREAK IN

HOUSE CONNECTION ABBREVIATIONS:





Main Inspection with Pipe-Run

AMP				:ade:	Ę								
HEITK		number:		Rim to gr	Heigh 1.0	dia label:							
		Sheet	TK-428	nvert:	w control:	Me		curacy:					
			ONECK	Grade to i	Flo	enewed:		GPS ac	ų	# 65771			# 26770
			<sup>City:</sup> MAMAR		irection:	Year re			Remark	HW			ΗW
		area:		to invert:				tem:	Ref.				
		Drainage		Rim	er use:	Year laid:		rdinate sys	Image				
					Sew	1		Coc	rrential ion to	-			
	ų				grade:	h surveyed:			Circumfe Locat At/From	-	-	m	
	epoi	y Customer	SS1 - 3		Rim to	Lengt 203			Joint				
	/er R	Surve	ORE AVE	nanhole No	vert:	th:	ional info:	Elevation:	8				
	Sew		Street: RUCHM	Upstream r 65771	Grade to in	Total leng 203.0	Addit		ie im) 2nd	-	- N		
	ACP		:41				ation code:		Valu Inches (m .st	-		9	
	<b>D</b>	/ner:	: L 15		o invert:	oint length:	rr: Loc	:bui	I/W/S	-			
		Ň	t date/time .5/09/21		Rim to	Pipe j	Weathe	Northi	ous Defect				
		7	Star 201			. method: P	aned:		er/ Continue ity				
		cate No: 107-600				5 O	Date cle		)/ Modifi tor Sever				
mp, Inc.		Certifi U-1	ref: CK4			Material: ZZZ	e-cleaning	asting:	Group Descrip	AMH	MML	TFA	АМН
r Heitkal 795 5469 19			ne segment				ry: Pr ]	oint: B	rideo Ref.	12	21	162	301
i Divisioi der Road 1, CT 06 50) 274. 945.32		St. 44	Pipeli	ŝ	anhole No:	Shape: C	ewer categ	iccess p	et)			,	
RD North 9 Callenc /atertowi hone: (80 ax: (860)		PEROTTI	ork order:	cation detail	ownstream n 5770	Width:	rpose: 5	tarting a	Distance (Fe (Meters)	0.1	0.1	115.0	203.(
PRD North Division Heitkamp, Inc. 99 Callender Road Watertown, CT 06795 Phone: (860) 274.5469 Fax: (860) 945.3219		Surveyed by: Certificate No: J.PEROTTI U-1107-6007	Work order: Pipeline segment ref: Start da MAMARONECK4 2015/	Location details:	Downstream manhole No: 65770	Width: Shape: Material: Ln. method: C ZZZ CP	Purpose: Sewer category: Pre-cleaning Date cleaned: J	Easting: Easting: Starting access point:	Distance (Feet) Video Ref. Group/ Modifier/ Continuous (Meters) Descriptor Severity	0.0 12 AMH	0.0 21 MWL	115.0 462 TFA	203.0 801 AMH

Wednesday, October 07, 2015 4:09 PM

PACP Sewer Report

Page 1 of 1

								[		T			1	Τ						1	1	
	65771						65770	COMP- LETED									_	<u> </u>	_			
	#			RVEY			#		VIB TESTED	-		_			-	-	-	-		1		
	МН			L Sul	$\rightarrow$		МН	TEST	ADD TA TON	4		-	-	-	-	-						
	0-			¢ MO	$ \rightarrow $		$\bigcirc$			<u>}</u>		+	-	-	-	-			-	-		
				E				ı ت	LIME OF TEST													
			Ľ					DCKAG AIR FEST	SSOT					1								
								BLO	END													
					1 1				TAAT		-											
INC.		AREA							IN SECONDS LIME OF TEST											0		
AMP,	r					F		OST ALING ATEST	SSOT											OF SEALS:		
ITK/	ORT				ING:	PEROT		P SEA AIR	END													
NHE	REF	ы			F SPAC	J.			TAAT2											0#		
/ISIO	NLING	ORE AVI			NIOF			CAL UT SE	SNOTTVO											0	SED:	
ENGLAND PIPE CLEANING COMPANY DI	<b>NND SEA</b>	RUSHM		NSPECTOR		REMAN:		CHEMI GROI USAC	STROKES											GALLONS:	JF SOCKS U	
	EST		HER:		10"	FC			(SECONDS) LIME OF TEST											0	)#	
	AIR T		WEAT					R ST LTS	SSOT											STS		
	ION	:NOI	2015		METER			AI TES RESU	END											AIR TES		
	NECI	LOCAT			PE DIAN				ТЯАТ2											TOTAL	0	
	CON		9/21/2		Ы			IS N	отнек	z											]	
	USE		DATE:			TIME:		HOUSE	ROOTS	z											CALED:	
	НО	CK NY				T GEL		CON CON	PROTRUDING TAP (IN)	z											AND SF	
NEW		MAMARONE		R INDEX:	GTH:	GROU		LEAKAGE (GPM)	RATE (GPM)	NO TEST										ICES IN LINE	CES TESTED	
				ΓΛ	ON LEN				HC SIZE	6										SERVI	SERVI	
					SECTIO				НС ТАРЕ	ц										BER OF	BER OF	
		CLIENT:			1	4V-100	ULDN'T FIT	VECTION ND TYPE	евом wh# 65770	Υ										MUN	MUN	
					LINED		PACKER WO	HOUSE CON LOCATION A	DISLVNCE (EL)	88												
			I NUMBER:	E NUMBER	PIPE TYPE	OUT TYPE:			# 3SUOH											ALS:		
			JOE	TAP	Idid	GR			#HC INFINE											TOT		

-

F FACTORY

HOUSE CONNECTION ABBREVIATIONS:

**B** BREAK IN


### Main Inspection with Pipe-Run Graph Project Name: Pipeline segment ref: City: Street: MAMARONECK NY TK-428 MAMARONECK MAMARONECK-5 **RUSHMORE AVE - LSS** TK-428 Start date/time: Width: Height: Material: Location code: Weather: 9/22/2015 10 ZZZ Direction: Length surveyed: Surveyed by: Additional info: J.PEROTTI Downstream 348.0 At 0.0 ft START WITH FLOW - Start Inspection With the Flow 65769 0 ∲ At 0.0 ft AMH - Manhole MH# 65769 At 0.0 ft 4 MWL - Water Level At 42.0 ft 2/. 🖞 TFA - Tap Factory Active 100.01 At 128.0 ft 3/. TF - Tap Factory Asset length: 348.0 ft; urveyed length: 348.0 ft At 182.2 ft 3/. ↓ TF - Tap Factory 200 0 11 TFA - Tap Factory Active 9 300.011 ♦ At 348.0 ft AMH - Manh ole MH# 65762 At 348 0 ft STOP - Inspection stopped V 0 65762

orth Division Heitkamp, Inc.	lender Road	town, CT 06795	: (860) 274.5469	860) 945.3219	PACP Sewer Re
PRD Nortl	99 Callen	Watertow	Phone: (8	Fax: (860	

<		
	<b>-</b>	

					PACP	Sewer Re	sport				
Surveyed by J.PEROT	::	Certificat U-110	te No: 7-6007	Owner:		Survey (	ûustomer:	Drainage area:		Sheet nu	mber:
Work order:	Pipeline segm MAMARON	ent ref: IECK-5	Sta 20	art date/time: 15/09/22	07:56	Street: RUSHMORE AVE -	SS1 -		City: MAMARONEC	K TK-428	
Location det	ails;					Jpstream manhole No: 65769		Rim to invert	:: Grade t	o invert: R	im to grade:
Downstream 65762	manhole No:			Rim to inve	irt:	Grade to invert:	Rim to grade:	Sewer use:	Direction: D	Flow control:	Height: 10
Width:	Shape: C	Material: ZZZ	Ln. method:	Pipe joint le	ength:	Total length: 348.0	Length surveyed: 348.0	Year laid:	Year renewed:	Media	label:
Purpose:	Sewer category:	Pre-cleaning   ]	Date cleaned:	Weather:	Location code:	Additional info:					
Starting	access point:	Easting:		Northing:		Elevation:		Coordinate system:	GPS	accuracy:	

Remarks	MH# 65769						MH# 65762
Image Ref.				MAMARONECK NY TK-428-65769-65762 TF at 128.0 ft (D).jpg		MAMARONECK NY TK-428-65769-65762 TFA at 220.3 ft (D).jpg	
nferential cation to							
Circur Lo At/From			2	ю	3	12	
Joint							
\$		5					
Value (mm) 2nd							
Inches 1st			9	Q	9	9	
t S/M/L							
Continuous Defec							
Modifier/ ( Severity							
Group/ Descriptor	AMH	MWL	TFA	Ŧ	TF	TFA	АМН
Video Ref.	11	25	1109	1480	1640	1752	2212
Distance (Feet) (Meters)	0.0	0.0	42.0	128.0	182.2	220.3	348.0

	65						5	4 0	SVLED	is				Τ					1	7
	657(				_		6576	COM	IK TESTED	V		+	_		-		-	+	-	
	# HV				$\rightarrow$			= _	OT AT HOME	N	+		-	-	+	 _	-		-	
	Õ-						-	FLUS	ONNECTION CLEAR	<u>с</u>				+	-	-	-	+	1	
				+ FI OW	$\rightarrow$		Ũ		N SECONDS IME OF TEST	T 11									1	
								CKAGE AIR EST	SSO	r						1		1	1	
								BLO	an	Э									1	
					1				TAAT	s									1	
, INC.		AREA:	1						N SECONDS IME OF TEST	L									0	
AMP	<u>_</u>			1		E		OST ALING & TEST	SSO	т									S:	
ITK	POR				:SNIC:	PERO'		SE.	ana	4									F SEAL	
N HE	G RE	Э			T SPAC	ſ			TAAT	5									0#	
VISIO	ALING	<b>10RE AV</b>		~	NIOF			ICAL DUT GE	SALLONS										0	SED:
ANY DI	AND SE	RUSHA		NSPECTO		DREMAN:		CHEM GRC USA	STROKES										SALLONS:	F SOCKS I
OMP	EST		HER:		10	FG			(SECONDS) LIWE OF TEST	2									0	#
ING C	AIR T		WEAT					IR ST JLTS	SSOT										STS:	
EAN	lion	:NON:			METER			AI TE RESU	END								_		AIR TES	
PE CL	INECT	LOCAT	2015		IPE DIA				TAATS										TOTAL	0
Id (I)	CON		9/22/		Ч			0N 1S	отнек	z	z	z	z						+	
ILAN	USE		DATE:			TIME:	8	HOUSE	ROOTS	z	z	z	z							ALED:
ENC	НС	CKNY				T GEL		PR	РВОТВИЛІИС ТАР (ІМ)	z	z	z	z							AND SE
NEW		MAMARONE		R INDEX:	GTH:	GROU		LEAKAGE (GPM)	RATE (GPM)	NO TEST	NO TEST	NO TEST	NO TEST						CES IN LINE:	CES TESTED
		1		VT	N LEN				HC SIZE	6	9	6	9						SERVIG	SERVIC
					SECTIC				HC TYPE	Ľ.	٤.,	ш	ίL						BER OF	BER OF 9
		CLIENT:				/-100	LDN'T FI	D TYPE	692S9 #HW WOA3	γ	×	Y	¥						MUN	INUMI
		-			LINED	AI	PACKER WOUI	HOUSE CONNI LOCATION AN	DISLVNCE (EL)	42	128	180	220							
			NUMBER:	<b>NUMBER</b>	IPE TYPE:	UT TYPE:			# 3SUOH										rs:	
			JOB	TAPE	4	GRO	L		#HC INFINE										TOTA	

Γ

F FACTORY

B BREAK IN

HOUSE CONNECTION ABBREVIATIONS:



#### Main Inspection with Pipe-Run Graph Project Name: Pipeline segment ref: City: Street: MAMARONECK NY TK-428 MAMARONECK MAMARONECK-6 **RUSHMORE AVE - LSS** TK-428 Start date/time: Width: Height: Material: Weather: Location code: 9/22/2015 10 ZZZ Direction: Length surveyed: Surveyed by: Additional info: J.PEROTTI Downstream 264.0 At 0.0 ft START WITH FLOW - Start Inspection With the Flow Ŷ 65980 0 ↓ At 0.0 ft AMH - Manhole MH# 65980 ↓ At 0.0 ft 0 MWL - Water Level V At 16.8 ft 12/. TFA - Tap Factory Active ¥ At 68.4 ft 12/. 0 TFA - Tap Factory Active ↓ At 77.0 ft 12/. . TFA - Tap Factory Active ¥ At 102.0 ft 12/. 100.011 0 TFA - Tap Factory Active Asset length: 264.0 ft; urveyed length: 264.0 ft ↓ At 118.3 ft 12/ TFA - Tap Factory Active 0 1 FT T ¥ At 146.7 ft 12/ TFA - Tap Factory Active 10 V At 160.4 ft 12 TFA - Tap Factory Active 0 At 170.9 ft 12/. TFA - Tap Factory Active × -۲ ♦ At 175.0 ft 2/. LFW - Lining Failure Wrinkled Category: Structural V At 208 1 ft 12/. TFC - Tap Factory Capped <u>.</u> BROKEN At 264.0 ft AMH · Manhole MH# 65759 - 65979 At 264 O ft 0 >>>>> STOP - Inspection stopped 65759

📕 🖥 🖪 📕									1	Т								1
	mber:		im to grade	Height:	LU label:													
	Sheet nu	<-428	ert: R	control:	Media		racy:											
		NECK TI	brade to inv	Flow	ewed:		GPS accu		65980									
		ity: 1AMARO	0	ection:	Year ren			Remarks	#HM									
	rea:	02	o invert:	ja C	2		:	ef.										
	Drainage a		Rim t	wer use:	Year laid:		oordinate syste	Image R										
				Se	:p		Ŭ	ferential ation to								1		
t	ï			o grade:	jth surveye 4.0			Circum Loc At/From			12	12	12	12	12	12	12	
Repo	ey Custome	E - LSS	ä	Rim t	Leng 264			Joint										
ver F	Surv	IORE AV	manhole N	nvert:	gth:	tional info:	Elevation	\$		10								
Sev		Street: RUSHN	Upstream 65980	Grade to i	Total len 264.0	: Add		lue nm) 2nd	-			-						
ACF		9:46			Ë	cation code		Va Inches (r 1st			9	9	9	9	9	9	9	
	)wner:	1e: 22 0		to invert:	joint lengtl	her: Lo	hing:	S/M/L										
		art date/tin 15/09/2		Rim	Pipe	Weath	Nort	uous Defect										
	07	50 50			n. method:	eaned:		fier/ Contin erity										
d	ificate No: 1107-60				-	g Date d		up/ Modi iptor Seve	Ŧ	L.	A	4	4	4	Ŧ	-	-	
amp, In	Cert U-1	nt ref: ECK-6			Material: ZZZ	Pre-cleaning ]	Easting:	Gro Descr	AM	MM	TF	TF	TF	TF/	TF/	TF/	TF/	
on Heitk Id 6795 4.5469 219		MARON				gory:	point:	Video Ref.	0	39	178	299	728	458	995	1107	1194	
h Divisid Ider Roa In, CT 0 360) 274 () 945.3	H	Pipe MA	ils:	manhole No	Shape: C	Sewer cate	access	eet)	0.	0	8	4	0	0		2	4	
PRD Nort 99 Callen Watertow Phone: (E Fax: (860	Surveyed by: J.PEROTT	Work order:	Location deta	Downstream (65759	Width:	Purpose:	Starting	Distance (F (Meters)	0.	0.	16.	68.	77.	102.	118.	146.	160.	

Page 1 of 2

Wednesday, October 07, 2015 4:09 PM

PACP Sewer Report

PRD North Division Heitkamp, Inc 99 Callender Road	Watertown, CT 06795	Phone: (860) 274.5469	Fax: (860) 945.3219
---	---------------------	-----------------------	---------------------

Surveyed by: J.PEROTTI

Owner:

Start date/time: 2015/09/22

Upstream manhole No: 65980

Pipeline segment ref: MAMARONECK-6

Sheet number:

Concession in the local division in the loca	1000				
Remarks				BROKEN	MH# 65759 - 65979
Image Ref.		MAMARONECK NY TK-428-65980-65759 TFA at 170.9 ft (D).jpg		MAMARONECK NY TK-428-65980-65759 TFC at 208.1 ft (D).jpg	MAMARONECK NY TK-428-65980-65759 AMH at 264.0 ft (D).jpg
mferential ocation	1 to				
Circu	At/From	12	2	12	
Joint					
%					
ilue (mm)	2nd				Š.
V <sub>7</sub> Inches	lst	9		9	
S/M/L					
Continuous Defect					
Modifier/ Severity					
Group/ escriptor		TFA	LFW	TFC	АМН
Video Ref. D		1275	1360	1494	1997
Distance (Feet) (Meters)		170.9	175.0	208.1	264.0

PACP Sewer Report



							4 0	VED	as	_			Τ						Τ	
6578						65755	COM							_					_	
# H			4	JRVEY		##		B TESTED					_	-				_	_	
W O-				S (			FLUSH					+		_		-	_	_	_	
$\bigcirc$			←	+LOW →		$\bigcirc$		RECONDS			-	_	+	+	-	+	+		-	
							GE	IME OF TEST	LT		_	_	_		_	_	_	_	_	
							BLOCKA AIR TEST	SSO		+			+		-		-		-	
							<b>–</b>		c .	-	-	+-	+			_			-	
	REA:							A SECONDS	30 11	-		+	+			+	+		+	
	×	1					ST	IME OF TEST		+		+	+	+	+		-	-		-
RT					ROTTI		POS SEALI AIR TE			+-	-	+		-			+		CALS:	-
REPO				PACING	J. PE				0				+		-		-	-	# OF SE	
I DNIC	<b>XE AVE</b>			JOINT S			1.	SPLEAK	) s	-	-		+				+			
SEAI	SHMOF		TOR		Ż		EMICA GROUT USAGE		-	-	-		-	+	+	-	-			- ISE
AND	RU		INSPEC		OREMA		E C E	STROKES	5										GALLON	DESOCH
rest		THER:		10"				RECONDS) LIME OF TEST	30										-	#
AIR		WEA					IR ST JLTS	SSOT											TS:	
LION	LION:			METER			A TE RESU	END	0										AIR TES	
INECT	LOCAT	2015		IPE DIA				TAATS	0		1								TOTAL	-
CON		9/22/		Ч			1S 1	отнек	z	z	z	z		z	z					
OUSE		DATE:			TIME:		HOUSE	800TS	z	z	z	z		z	z					ALED:
Н	KAVE				T GEL	- 25	PR	<b>ΓΕΟΤΒ</b> ΩDING TAP (IN)	z	z	z	z		z	z					AND SE
	AMARONE		A INDEX:	GTH:	GROL	SS1	(GPM)	RATE (GPM)	z	z	z	z	NO TEST	z	z	NO TEST			ES IN LINE:	ES TESTED
	N		VTI	ON LEN		RESTO		HC SIZE	9	9	6	6	9	9	6	9			SERVIC	ERVIC
				SECTIC		TO DO		НС ТҮРЕ	í.	íد.	ц	ц	ĹL.	íL.	ч	F			BER OF	ER OF 9
	CLIENT:				-100	DN'T FIT	DTYPE	687280 MH# 65780	٨	٨	Y	Y	>	Y	×	¥			IMUN	NUMB
	-			LINED	A1	PACKER WOUL	OCATION AN	DISTANCE (FT)	17	68	77	102	120	160	170	208				
		NUMBER:	NUMBER:	IPE TYPE:	UT TYPE:			# ЭЅ∩ОН	WRINKLE										S:	
		JOB	TAPE	Ы	GRO		Ì	#HC INFINE			1		1				_		OTAL	

F FACTORY

**B** BREAK IN

HOUSE CONNECTION ABBREVIATIONS:



## Main Inspection with Pipe-Run Graph Project Name: Pipeline segment ref: City: Street: MAMARONECK NY TK-428 MAMARONECK-7 RUSHMORE AVE - LSS MAMARONECK TK-428 Start date/time: Width: Height: Material: Location code: Weather: 9/22/2015 16 CAS Direction: Length surveyed: Surveyed by: Additional info: Downstream 166.0 J.PEROTTI At 0.0 ft START WITH FLOW - Start Inspection With the Flow ⋬ ↓ At 0.0 ft AMH - Manhole 65835 0 MH# 65835 At 0.0 ft MWL - Water Level At 1.0 ft 12/. SRC · Surface Reinforcement Corroded Category: Structural Asset length: 166.0 ft; Surveyed length: 166.0 ft 100.0 /t ♦ At 135.4 ft 12/. TFA - Tap Factory Active ↓ At 166.0 ft MSA - Abandoned Survey HEAVY CLEANING 0 65834

MAMAKUNELK-/     2015/09/22     13:32     RUSHMORE AVE     LSS       cotion details:     Upstream manulole No:     Upstream manulole No:     Upstream manulole No:     Sever use:     Rim to invert:     Upstream manulole No:     Sever use:     Rim to invert:     Rim to invert:     Rim to invert:     Rim to grade:     Sever use:     Sever use: </th <th>PRD North Division F 9 Callender Road Vatertown, CT 0679 hone: (860) 274.54 fax: (860) 945.3219 ax: (860) 945.3219 ax: (860) 945.3219 ork order: Pipeline s</th> <th>eitkamp, Inc. 69 Certifica U-111</th> <th>ate No: 07-6007</th> <th>Owner: t date/time:</th> <th>PACP</th> <th>Sewer R Surve</th> <th><b>eport</b> y Customer:</th> <th></th> <th>Drainage area:</th> <th></th>	PRD North Division F 9 Callender Road Vatertown, CT 0679 hone: (860) 274.54 fax: (860) 945.3219 ax: (860) 945.3219 ax: (860) 945.3219 ork order: Pipeline s	eitkamp, Inc. 69 Certifica U-111	ate No: 07-6007	Owner: t date/time:	PACP	Sewer R Surve	<b>eport</b> y Customer:		Drainage area:	
Structure (Figent)   Figure (Figent)   Figure (Figent)   Sever use:     Structure (Figent)   In method:   Plye joint length:   Total length:   Sever use:     Structure (Figent)   In method:   Plye joint length:   Total length:   Sever use:     Sever category:   Pre-cleaning   Date cleaned:   Weather:   Location code:   Additional info:     Sever category:   Pre-cleaning   Date cleaned:   Weather:   Location code:   Additional info:     Sever category:   Sever category:   Not   Sever category:   Sever category:   Coordinate sys     Cost (Figet)   Not   Coordinate sys     Sever category:   Sever category:   Northing:   Coordinate sys     Coordinate sys     O   O   O   Coordinate sys     Coordinate sys	MAMAI tion details:	RONECK-7	202	15/09/22	13:32	RUSHMORE AVI Upstream manhole No 65835	E - LSS		Rim to invert:	MAMARONECK TK-428 Grade to invert: Rim to grade:
It:Shape:Material:In. method:Pipe joint length:Total length:Length surveyed:Year laid. $C$ CASI.0. method:Material:I.0. method:I.66.0I.66.0I.66.0Year laid.set:Sewer category:Pre-cleaningDate cleaned:Weather:Location code:Additional info:Year laid.set:Sewer category:Pre-cleaningDate cleaned:Weather:Location code:Additional info:Year laid.set:Sewer category:Fre-cleaningDate cleaned:Weather:Northing:Additional info:Coordinate sysstreet frees)Video ReiCoorplyNorthout SeverityNorthout SeverityNorthout SeverityIndues (mun)Northout SeverityImageand0.01AMHIndues (mun)Northout SeverityIndues (mun)Northout SeverityImageand0.01AMHIndues (mun)Northout SeverityImageImage0.029MwLI15II135.4803TFA6I11I166.0868MSAMSAIIIIIIntersitionIntersitionI11IIIIIntersitionIntersitionIntersitionIntersitionIIIIIntersitionIntersitionIntersitionIntersitionIntersitionIntersitionIntersition<	istream manhole No: 34			Rim to inver		Grade to invert:	Rim to grade:	Se	Wer use:	rection: Flow control: Height:
set: Sever category: Pre-cleaning Date cleaned: Weather: Location code: Additional info:   ting access point: Easting: Northing: Image Additional info:   ting access point: Easting: Northing: Elevation: Coordinate sys   access point: Addition Severity Northing: Elevation: Coordinate sys   access point: Addition Severity Severity Severity Severity Severity   access point: Addition Severity Severity Severity Severity Severity   access point Elevation 1 Addition Severity Severity Severity   access point Elevation Severity Severity Severity Severity   access point Elevation Severity Severity Severity Severity   access point Elevation Severity Severity Severity   access point Elevation Severity Severity Severity   access point Elevation Severity Severity Severity   access point Carameterity Severity Severity Severity   access point Carameterity	th: Shape: C	Material: CAS	Ln. method:	Pipe joint ler	igth:	Total length: 166.0	Length surve 166.0	yed:	Year laid:	LO Year renewed: Media label:
Fasting:Forting: <th< td=""><td>se: Sewer category:</td><td>Pre-cleaning ]</td><td>Date cleaned:</td><td>Weather:</td><td>Location code:</td><td>Additional info:</td><td></td><td></td><td></td><td></td></th<>	se: Sewer category:	Pre-cleaning ]	Date cleaned:	Weather:	Location code:	Additional info:				
ance (Feet) Video Ret. Group/ Descriptor Nodifier/ Seventy Continuous Defect Value Joint Circumferential Image   (heters) 0.0 1 AMH 1st 2nd At/From to   0.0 1 AMH 1st 2nd At/From to   0.0 29 MWL 5 12 12 14/28-65   1.0 396 SRC 10 5 12 16/428-65   135.4 803 TFA 6 6 12 17, 428-65   166.0 868 MSA MA 12 17 16/28-65	rting access poil	Easting: <b>11:</b>		Northing:		Elevation:		U	oordinate system:	GPS accuracy:
0.0   1   AMH   Image: Second	ance (Feet) Vide (Meters)	) Ref. Group/ Descripto	Modifier/ Continud Dr Severity	ous Defect S/M/L	Valu Inches (m 1st	e m) % 2nd	Joint Circu LL At/Fron	Imferential ocation n to	Image Ref.	Remarks
0.0   29   MwL   5   5   7   7     1.0   396   SRC   7	0.0 1	AMH								MH# 65835
1.0     396     SRC     MAMARO       135.4     803     TFA     6     12     MAMARO       166.0     868     MSA     6     12     12     MAMARO	0.0 29	MWL				S				
135.4     803     TFA     6     12       166.0     868     MSA     12     12	1.0 396	SRC					12		MAMARONECK NY TK-428-65835-65834 SRC at 10.1 ft (D).ipg	
166.0 868 MSA	135.4 803	TFA			9		12			
	166.0 868	MSA								HEAVY CLEANING

Wednesday, October 07, 2015 4:09 PM

PACP Sewer Report



### Main Inspection with Pipe-Run Graph Project Name: Pipeline segment ref: City: Street: MAMARONECK NY TK-428 MAMARONECK-8 MAMARONECK RUSHMORE AVE - LSS TK-428 Start date/time: Width: Height: Material: Location code: Weather: 9/22/2015 10 ZZZ Direction: Length surveyed: Surveyed by: Additional info: Downstream 351.0 J.PEROTTI At 0.0 ft START WITH FLOW - Start Inspection With the Flow 65762 V At 0.0 ft 0 AMH - Manhole MH# 65762 MWL - Water Level V At 31.4 ft 12/. SRC - Surface Reinforcement Corroded Category: Structural V At 37.0 ft 12/. SRC - Surface Reinforcement Corroded Category: Structural V At 68.4 ft 12/ SRC - Surface Reinforcement Corroded Category: Structural At 80.3 it 12/ 100.0 ft SRC · Surface Reinforcement Corroded Category: Structural Asset length: 351.0 ft, urveyed length: 351.0 ft At 248.0 ft 1 2/. TFA - Tap Factory Active 1 FT T V At 256.2 ft 12/ SRC - Surface Reinforcement Corroded Category: Structural 300.0 ft ↓ At 351.0 ft AMH - Manh ole MH# 65761 At 351.0 ft Ŵ 0 65761 >>>> STOP - Inspection stopped

HEITKAMP	ort	omer: Drainage area: Sheet number:	City: MAMARONECK TK-428	Rim to invert: Grade to invert: Rim to grade:	m to grade: Sewer use: Direction: Flow control: Height:	.ength surveyed: Year laid: Year renewed: Media label: 351.0		Coordinate system: GPS accuracy:	Circumferential Image Ref. Remarks Location At/From to	MH# 65762	MAMARONECK NV TK-428-65762-65761 MWL at 0.0 ft (D).jpg	12	12	12	12 MAMARONECK NY TK-428-65762-65761 SRC at 80.3 ft (D).100	12 MAMARONECK NY TK-428-65761-65761 TFA at 248.0 ft f(b) into	12
	P Sewer Re	Survey Ct	Street: RUSHMORE AVE -	Upstream manhole No: 65762	Grade to invert:	Total length: 351.0	e: Additional info:	Elevation:	alue Jo (mm) % 2nd		10						
	PACE	er:	14:49		nvert:	nt length:	Location code	:6	Va M/L Inches ( 1st							9	
		OWD	Start date/time: 2015/09/22		Rim to i	thod: Pipe joir	: Weather:	Northing	ontinuous Defect S/								
		ertificate No: 1-1107-6007				al: Ln. met	ing Date cleaned:		roup/ Modifier/Co scriptor Severity	HW	IWL	RC	RC	RC	RC	FA	RC
Heitkamp, I 95 i469 9		ŭ⊃	e segment ref: ARONECK-8			Materia ZZZ	y: Pre-cleani J	Easting:	deo Ref. G	0 A	7 M	72 S	20 S.	)1 S.	33 SI	27 T	90 SI
Division der Road η, CT 067 60) 274.5 945.321			Pipelin, MAM,	ö	anhole No:	Shape: C	ewer categor	iccess pc	et) Vi		0	4 15	22	1 3(	3;	22	. 86
PRD North 99 Callenc Watertowr Phone: (80 Fax: (80)		Surveyed by: J.PEROTTI	Work order:	Location detail.	Downstream m 65761	Width:	Purpose: S	Starting a	Distance (Fe (Meters)	0.(	0.0	31.4	37.0	68.4	80.3	248.C	256.2

Wednesday, October 07, 2015 4:09 PM

PACP Sewer Report

PRD North Division Heitkamp, Inc.	9 Callender Road	/atertown, CT 06795	hone: (860) 274.5469	ax: (860) 945.3219
-----------------------------------	------------------	---------------------	----------------------	--------------------

<	ſ	KAMP	BR
		HEIT	-

Sheet number:		
eline segment ref: AMARONECK-8	Remarks	
Pip. M/	Image Ref.	
	Circumferential Location M/From to	
Upstream manhole No: 65762	96 Joint	
Start date/time: 2015/09/22	Value Inches (mm) 1st 2nd	
	T/W/S	
	Continuous Defect	
Owner:	Group/ Modifier/ Descriptor Severity	АМН
	Video Ref.	1078
Surveyed by: J.PEROTTI	Distance (Feet) (Meters)	351.0

MH# 65761

Wednesday, October 07, 2015 4:09 PM

									CALED			1					Τ	]	
	65762						65761	COMP						 		-	-		
	# H			↑ JRVEY	$\rightarrow$		 #		TIS LESTED	1	 			 			-		
	W 			5			WI ()	FLUSH TEST						 		+			
	$\bigcirc$			↑ FLOW	$\rightarrow$		$\bigcirc$		N RECORDS	1				 					
								cAGE R T	SSOT		-			 					
								BLOCH All TES	ana						+				
									TAATS										
INC.		AREA:							IN SECONDS LIWE OF TEST								0		
۸MP,						H		DST LING TEST	SSOT								ŝ		
ITKA	ORT				NG:	PEROT		PC SEA AIR	END								F SEAL		
NHE	REP	(1)			I SPACI	ŗ			TAATS								10 #		
VISIO	ALING	IORE AVE		~	LNIOF			ICAL UT GE	CALLONS								0	USED:	
ANY DI	ND SE	RUSHN		NSPECTOF		REMAN:		CHEM GRO USA	STROKES								SALLONS:	F SOCKS (	
OMP.	EST		HER:	-	01	FC			(SECONDS) LIME OF TEST								0	#0	
NG C	VIR T		WEATI					L	SSOT					_			lS:		
INNE	NOI A	- NO			ETER			AIR TES RESUI	END				-+	 			IR TES		
ECLI	ECT	OCATI	15		E DIAM				LAKIS						+		OTAL A	0	٠
<b>PIPI</b>	NNO	_	9/22/20		IdId			7	OTHER	Z	 			 	+		Ĕ		
AND	JSE C		ATE:			ME:		DUSE ECTIOI BLEMS	SLOOK	z	 							LED:	
ENG	HOL	AN X	D			GEL TI		HC CONN PROI	PROTRUDING TAP (IN)	z	 -			 				ND SEA	
NEW		MARONECH		NDEX:	H:	GROUT		EAKAGE (GPM)	(1110) 7110	IO TEST							S IN LINE:	S TESTED A	
		MA		VTR I	LENG				BATE (CPM)	2	 -			 		-	RVICE	RVICE	
				1	CTION				2111 21		 	_		 	-		t OF SE	OF SE	
		Ë			SE			E N	HC LADE	-	 		_	 _			UMBEI	UMBER	
		CLIEN			T	VV-100		ND TY	EBOW WH# 65762	~							z	Z	
					LINED			HOUSE CONT LOCATION A	DISTANCE (FT)	248									
			<b>B NUMBER:</b>	E NUMBER:	PIPE TYPE:	OUT TVPE:			#ЭЅ∩ОН	I FT T							ALS:		
			Of	TAP		GR	l		#HC INFINE								TOT		

F FACTORY

**B** BREAK IN

HOUSE CONNECTION ABBREVIATIONS:





HEITKAMP	COMPANY	Sheet number:	City: MAMARONFCK TK-428	Grade to invert: Rim to grade:	birection: Flow control: Height:	) 16 Year renewed: Media label:		GPS accuracy:	Remarks		MH# 65829				PIPE WEDGED SIDE TO SIDE OF	PIPE PIPE WEDGED
		Drainage area:		Rim to invert:	Sewer use:	[ Year laid:		Coordinate system:	l Image Ref.		MAMADOMCOM	TK-428-65829-65828 MWL at 0.0 ft (D).jpg	MAMARONECK NY TK-428-65829-65828 SAM at 2.0 ft (D).jpg	MAMARONECK NY TK-428-65829-65828 TFA at 57.7 ft (D) ind		MAMARONECK NY TK-428-65829-65828 MSA at 70.0 ft (D).jpg
	eport	Customer:	- TV		Rim to grade:	Length surveyed: 70.0			Joint Circumferentia Location					12	2	
	<sup>o</sup> Sewer R	Survey	Street: RUSHMORE AVE	Upstream manhole No: 65829	Grade to invert:	Total length: 70,0	: Additional info:	Elevation:	lue mm) % 2nd		4	3			25	
	PACF	vner:	: 08:49		invert:	oint length:	r: Location code	: 60	Va /M/L Inches (r 1st					9		
		00 2	Start date/time 2015/09/23		Rim to	method: Pipe jo	ned: Weathe	Northi	r/ Continuous Defect y							
mp, Inc.		Certificate No: U-1107-600	ref: CK-10			Material: Ln. CAS	e-cleaning Date clea	isting:	Group/ Modifie Descriptor Severit	AMH	MWL		MIAC	TFA	OBZ	MSA
Jivision Heitkaı r Road CT 06795 ) 274.5469 )45.3219			Pipeline segment MAMARONE(		nole No:	Shape: C	er category: Pre J	ess point:	Video Ref.	11	21	757	202	497	783	893
PRD North I 99 Callende Watertown, Phone: (860) Fax: (860) g		Surveyed by: J.PEROTTI	Work order:	Location details:	Downstream man 65828	Width:	Purpose: Sewe	Starting acc	Distance (Feet) (Meters)	0.0	0.0	0.0	2	57.7	70.0	70.0

Wednesday, October 07, 2015 4:09 PM

PACP Sewer Report





HEITKAMP	Соитал	Sheet number:	City: MAMARONECK TK-428	Grade to invert: Rim to grade:	rection: Flow control: Height:	16 Year renewed: Media label:		GPS accuracy:	Remarks	MILH CTOOO	878C0 #UM			MH# 65826	
		Drainage area:		Rim to invert:	Sewer use: D	L Year laid:		Coordinate system:	Image Ref.			MAMARONECK NY TK-428-65828-65826 SRC at 2 0.64 (5) ioo	MAMARONECK NY TK-428-65828-65826 TRA at 31 5 4 (1) ino		
	sport	Customer:	VT		Rim to grade:	Length surveyed: 186.0			oint Circumferential Location At/From to			12	12		
	Sewer Re	Survey (	Street: RUSHMORE AVE -	Upstream manhole No: 65828	Grade to invert:	Total length: 186.0	Additional info:	Elevation:	le 9% J Im) 9% 2nd		20				
	PACP	t.	10:27		vert:	length:	Location code:		L Inches (m 1st				9		
		Owner	Start date/time: 2015/09/23		Rim to in	d: Pipe joint	Weather:	Northing:	inuous Defect S/M						
j		tificate No: 1107-6007				Ln. metho	g Date cleaned:		up/ Modifier/Conti iptor Severity	н		U	4	T	
Heitkamp, In )5 469		Cerl U	segment ref: RONECK-11			Material: CAS	Pre-cleaning J	Easting: <b>nt:</b>	o Ref. Gro	AM	MM	SR	TB/	AMI	
n Division I der Road 1, CT 0679 50) 274.54 945.3219			Pipeline MAMA	10	anhole No:	Shape: C	ewer category:	ccess poi	t) Vide	0	35	267	351	752	
PRD North 99 Callenc Watertowr Phone: (86 Fax: (860)		Surveyed by: J.PEROTTI	Work order:	Location details	Downstream m 65826	Width:	Purpose: Se	Starting a	Distance (Fee (Meters)	0.0	0.0	2.0	31.5	186.0	

Wednesday, October 07, 2015 4:09 PM

PACP Sewer Report



### Main Inspection with Pipe-Run Graph Project Name: Pipeline segment ref: City: Street: MAMARONECK NY TK-428 MAMARONECK MAMARONECK-12 RUSHMORE AVE - TV TK-428 Start date/time: Width: Height: Material: Location code: Weather: 9/23/2015 16 CAS Direction: Length surveyed: Surveyed by: Additional info: Downstream J.PEROTTI 149.0 At 0.0 ft START WITH FLOW - Start Inspection With the Flow 4 65826 V At 0.0 ft 0 AMH - Manhole MH# 65826 At 0.0 ft MWL - Water Level V At 2.0 ft 12/ SAV - Surface Aggregate Visible Category: Structural 30.0 t 40.0 ft 60.0 h Asset length: 150.0 ft; urveyed length: 149.0 ft TFA - Tap Factory Active 2 80 0 h 900h 100.0 ft 130.0 h ♦ At 149.0 ft AMH - Manhole MH# 65825 150 0 it At 150.0 ft STOP - Inspection stopped V 0 65825

PRD North D 99 Callender Watertown, ( Phone: (860) 94 Fax: (860) 94 Surveyed by:	ivision Heitkar Road CT 06795 274.5469 45.3219 45.3219	np, Inc.	Vo:	Owner:	PAC	P Se	Wer R	(eport		Drainade area.		
J.PEROITI Work order:	Pipeline segment r MAMARONEC	U-1107- <sup>ref:</sup> .K-12	-6007 <sup>Sta</sup> 20:	rt date/time: 15/09/23	10:41	Street: RUSF	IMORE AVE	- TV			Sheel ity: 1AMARONECK TK-428	number:
Location details:						Upstrea 6582	am manhole No 6	.,		Rim to invert:	Grade to invert:	Rim to grade:
Downstream manh 65825	ole No:			Rim to inv	ert:	Grade t	o invert:	Rim to gra	ade:	Sewer use: Dir	ection: Flow control:	Height:
Width: S C	hape:	Material: CAS	Ln. method:	Pipe joint I	ength:	150.	length: 0	Length s 149.0	urveyed:	Year laid:	Year renewed: Me	L <b>b</b> Jia label:
Purpose: Sewer	· category: Pre- ]	-cleaning Dal	te cleaned:	Weather:	Location co	ode: A	dditional info:					
Starting acc	ess point:	sting:		Northing:			Elevation:			Coordinate system:	GPS accuracy:	
Distance (Feet) (Meters)	Video Ref.	Group/ N Descriptor	Modifier/ Continu Severity	ous Defect S/M/L	Inche. 1st	Value s (mm) 2nd	8	Joint	Circumferentia Location	I Image Ref.	Remarks	
0.0	29	AMH							11011			
0.0	46	MWL					20		_		MH# 65826	
2.0	138	SAV							12			
66.0	230	TFA			9				12	MAMARONECK NY TK-428-65826-65825 TEA at 65.0 64 (D) 555		
149.0	562	АМН							_	Bdfr(n) to orop to the	MH# 65875	
									_		C70C0 #111.1	

[

PACP Sewer Report





HEITKAMP	COMPANY	Sheet number:	diy: MAMARONECK ти доо	Grade to invert: Rim to grade:	rection: Flow control: Height:	16 Year renewed: Media label:		GPS accuracy:	Remarks		MH# 65825					
		Drainage area:		Rim to invert:	Sewer use: Di	D Year laid:		Coordinate system:	Image Ref.			MAMARONECK NY TK-428-65825-65801 SAV at 4.064 (N)	MAMARONECK NY TK-428-65825-65801	MAMARONECK NY TK-428-65825-65801 TR-428-65825-65801	MAMARONECK NY TK-428-65825-65801 IG at 142-3 76 (D) inor	MAMARONECK NY TK-428-65825-65801 TFA at 172.7 ft (D).jpg
	eport	Customer:	VT -		Rim to grade:	Length surveyed: 200 0			Joint Circumferential Location			12	12	12	6	12
	Sewer R	Survey	Street: RUSHMORE AVE	Upstream manhole No: 65825	Grade to invert:	Total length: 209.0	: Additional info:	Elevation:	ue 1m) % 2nd		15					
	PACP		11:05			gth:	Location code:		Valı Inches (m 1st	E			9	9		9
		Owner:	irt date/time: 15/09/23		Rim to inver	Pipe joint ler	Weather:	Northing:	ous Defect S/M/L							
		cate No: L07-6007	sta 20			Ln. method:	Date cleaned:		Modifier/ Continue or Severity							
imp, Inc.		Certific U-11	t ref: :CK-13			Material: CAS	e-cleaning	asting:	Group/ Descript	AMH	MWL	SAV	TBA	TBA	IG	TFA
ivision Heitka r Road CT 06795 ) 274.5469 45.3219			Pipeline segmen MAMARONE		nole No:	Shape:	er category: Pi J	ess point:	Video Ref.	0	13	67	241	417	871	1764
PRD North E 99 Callender Watertown, Phone: (860) Fax: (860) 9		Surveyed by: J.PEROTTI	Work order:	Location details:	Downstream man 65801	Width:	Purpose: Sewe	Starting acc	Distance (Feet) (Meters)	0.0	0.0	4.4	29.7	43.6	142.3	172.7

Wednesday, October 07, 2015 4:09 PM

PACP Sewer Report

RD North Division Heitkamn The	9 Callender Road	atertown, CT 06795	none: (860) 274.5469	ax: (860) 945.3219	
--------------------------------	------------------	--------------------	----------------------	--------------------	--

MA
HEIT

Sheet number:		
line segment ref: .MARONECK-13	Remarks	MH# 65801
Pipe	Image Ref.	
	Circumferential Location At/From to	
Upstream manhole No. 65825	Joint %	
Start date/time: 2015/09/23	Value Inches (mm) 1st 2nd	
	Continuous Defect S/M/L	
Owner:	Group/ Modifier/ Descriptor Severity	АМН
	Video Ref.	2475
Surveyed by: J.PEROTTI	Distance (Feet) (Meters)	209.0

2



### Main Inspection with Pipe-Run Graph Project Name: Pipeline segment ref: City: Street: MAMARONECK NY TK-428 MAMARONECK-9 MAMARONECK RUSHMORE AVE - TV TK-428 Start date/time: Width: Height: Material: Lo cation code: Weather: 9/23/2015 16 CAS Direction: Length surveyed: Surveyed by: Additional info: Downstream J.PEROTTI 170.0 At 0.0 ft START WITH FLOW - Start Inspection With the Flow ↓ At 0.0 ft 65834 0 AMH - Manhole MH# 65834 At 0.0 ft MWL - Water Level At 2.0 ft 1 2/. SAV · Surface Aggregate Visible Category: Structural ¥ At 39.7 ft 12/. TBA - Tap Break-in Active TBA · Tap Break-in Active Asset length: 170.0 ft; Surveyed length: 170.0 ft 0 V At 80.2 ft 5/ SCP - Surlace Corrosion Metal Pipe Category: Structural 100.0 h At 130.0 ft 7/. SCP - Surface Corrosion Metal Pipe Category: Structural ↓ At 170.0 ft AMH - Manhole MH# 65829 At 170.0 ft STOP - In spection stopped V 0 65829

HEITKAMP		Sheet number:	428	t: Rim to grade:	ontrol: Height:	16 Media label:		cy:									
			<sup>city:</sup> MAMARONECK TK-	Grade to inver	irection: Flow co	year renewed:		GPS accura	Remarks	MH# 65834							MH# 65820
		Drainage area:		Rim to invert:	Sewer use: D	L Year laid:		Coordinate system:	Image Ref.			MAMARONECK NY TK-428-65834-65829 SAV at 2.0 ft (D).ipg		MAMARONECK NY TK-428-65834-65829 TBA at 71.0 ft (D).inn		MAMARONECK NY TK-428-65834-65829 SCD at 130.0.4.00.000	fdfr(a) to proce to the
	port	ustomer:	TV		Rim to grade:	Length surveyed: 170.0			oint Circumferential Location At/From to	·		12	12	12	5	2	
	Sewer Re	Survey C	treet: SUSHMORE AVE -	pstream manhole No: 55834	irade to invert:	Total length: 170.0	Additional info:	Elevation:	) % Jo nd		15						
	PACP		12:46 F		Wert: G	t length:	Location code:		Value VL Inches (mm 1st 2				9	ę			
		Owne	Start date/time: 2015/09/23		Rim to ir	thod: Pipe join	: Weather:	Northing	ontinuous Defect S/M								
Inc.		Certificate No: U-1107-6007	6			rial: Ln. me	ining Date cleaned		Group/ Modifier/ C escriptor Severity	АМН	MWL	SAV	TBA	TBA	SCP	SCP	НМА
sion Heitkamp, oad 06795 74.5469 3219			ipeline segment ref: 1AMARONECK-9		No:	e: Mate CAS	tegory: Pre-clea J	Easting Easting	Video Ref. D	1	32	39	224	326	363	473	548
PRD North Divi: 99 Callender Rc Watertown, CT Phone: (860) 2 Fax: (860) 945.		Surveyed by: J.PEROTTI	Work order: Pi	Location details:	Downstream manhole 65829	Width: Shap C	Purpose: Sewer ca	Starting acces	Distance (Feet) (Meters)	0.0	0.0	2.0	39.7	71.0	80.2	130.0	170.0

Page 1 of 1

Wednesday, October 07, 2015 4:09 PM

PACP Sewer Report



# **APPENDIX I**

Septic System Distance to Sewer - Map and Table





Parcel Boundary within 100 ft of Public Sewer

SepticNumber     Town ID     Village ID     PropAddres     Owner Name     Owner_Na_1     Notes       1     155.29-1-38     4-85-2B     300 Homidge Rd     Board of Education     Sopic tank appea       2     9-2-358     9-9-19     325 Stanley Ave     Barbieri, Domenic     0.00     parcel boundary       3     8-18-15     & 50-1-8     145 New St     Church OT St Vito     0.00     sever along Tex       4     154.58-1-16     4-60-7A1     325 E Boston Post Rd     Orienta Yacht Club     0.00     sever along Tex       5     9-42.668     9-80D-24     1107 Cove Rd North     Hampshire Recreation Lic     0.00     brow rating TeX       6     9-11-176     9-20-9     233 Valley PI     Yannuzzi, Jack & Michael     0.00     parcel     Sever along Valle       7     9-48-277     9-100-1     888 Orienta Lic     0.00     parallel to river be sorved by rth No build       8     9-52-1     9-98-1     1025 Rushmore Ave     Majestic Properties Inc     5.96     Sever along Toxa       10     154.28-1-38     4-49-62A     1503 Rose Ln							Distance to Sewer	
Construction     Disk of End of Education     Disk of Education     Disk of Education       1     155.29-1.36     4-65-28     300 Hornidge Rd     Board of Education     0.00     along parcel     sever along Staril       2     9-2-368     9-9-19     325 Starley Ave     Barbieri, Domenic     0.00     along parcel     0.00     along parcel       3     8.18-15     6.60-7.81     148 New St     Church OT St Vito     0.00     along parcel     0.00	SepticNumber	Town ID	Village ID	PropAddres	Owner Name	Owner Na 1	Line	Notes
1     155.29-1-36     4-65-28     300 Hornidge Rd     Board of Education     0.00     parcel boundary       2     9-2-358     9-9-19     325 Stanley Ave     Barbieri, Domenic     0.00     Sever along New       3     8-18-15     8-50-18     145 New St     Church Of St Vito     0.00     Sever along New       4     154.58-1-16     4-60-7A1     325 E Boston Post Rd     Orienta Yacht Club     0.00     Sever along Cove       5     9-42-568     9-89D-24     1107 Cove Rd North     Hampshire Recreation Lic     0.00     parcelel     Sever along Cove       6     9-1176     9-20-9     233 Valley PI     Yannuzzi, Jack & Michael     0.00     parallel to river bal       7     9-48-277     9-100-1     888 Orienta Ave     888 Orienta Lic     4.14     be served by this 5       8     9-52-1     9-98-1     1025 Rushmore Ave     Orienta Beach Club     5.04     (MH65788 to MH6       9     8-30-292     8-85-18A     0 Fayette Ave     Majestic Properties Inc     5.96     (MH65788 to MH6       9     8-30-292     8-85-18A </td <td>Coption tambon</td> <td></td> <td>villago_iD</td> <td></td> <td></td> <td></td> <td></td> <td>Septic tank appear</td>	Coption tambon		villago_iD					Septic tank appear
1     1000000000000000000000000000000000000	1	155 29-1-36	4-65-2B	300 Hornidae Rd	Board of Education		0.00	parcel boundary
2     9-2-358     9-9-19     325 Stanley Ave     Barbieri, Domenic     0.00     along parcel       3     8-18-15     8-50-1-8     145 New St.     Church O'S Vito     0.00     Sever along E Bo       4     154.58-1-16     4-60-7A1     325 E Boston Post Rd     Orienta Yacht Club     0.00     Bever along Cove       5     9-42-568     9-80D-24     1107 Cove Rd North     Hampshire Recreation Lic     0.00     Bever along Cove       6     9-11-176     9-20-9     233 Valley PI     Yannuzzi, Jack & Michael     0.00     Bever along Orie       7     9-48-277     9-100-1     888 Orienta Ave     888 Orienta Lic     4.14     be served by this 3       8     9-52-1     9-81-1     1025 Rushmore Ave     Orienta Beach Club     5.04     (MH65788 to MH6       9     8-30-292     8-85-18A     0 Fayette Ave     Majestic Properties Inc     5.96     (MH65508 to MH6       9     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH721491 adjace       10     154.28-1-38     4-49-62A     1503 Rose Ln		100.20 1 00	1 00 28				0.00	Sewer along Stanl
3     8-18-15     8-50-1-8     145 New St     Church OF St Vito     0.00     Sever along New.       4     154.58-1-16     4-60-7A1     325 E Boston Post Rd     Orienta Yacht Club     0.00     gever along Cove       5     9-42-568     9-89-24     1107 Cove Rd North     Hampshire Recreation Llc     0.00     gever along Ove       6     9-1-176     9-20-9     233 Valley Pl     Yannuzzi, Jack & Michael     0.00     gever along Orier       7     9-48-277     9-100-1     888 Orienta Ave     888 Orienta Llc     4.14     be served by this :       8     9-52-1     9-98-1     1025 Rushmore Ave     Orienta Beach Club     5.96     (MH65788 to MH6       9     8-30-292     8-85-18A     0 Fayette Ave     Majestic Properties Inc     5.96     (MH65788 to MH6       10     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH72184) adjace       11     154.50-1-34     4-55-16A     207 Union Ave     Carvarho, Orlando     10.99     property       12     9-42-419     9-989-18     1031 Cove Rd South	2	9-2-358	9-9-19	325 Stanley Ave	Barbieri, Domenic		0.00	along parcel
1     1	3	8-18-15	8-50-1-8	145 New St	Church Of St Vito		0.00	Sewer along New
4     154.58-1-16     4-60-7A1     325 E Boston Post Rd     Orienta Yacht Club     0.00     parcel       5     9-42-568     9-89D-24     1107 Cove Rd North     Hampshire Recreation Llc     0.00     Sewer along Cove       6     9-1176     9-20-9     233 Valley PI     Yannuzzi, Jack & Michael     0.00     parallel to river be       7     9-48-277     9-100-1     888 Orienta Ave     888 Orienta Llc     4.14     be served by this 3       8     9-52-1     9-98-1     1025 Rushmore Ave     Orienta Beach Club     5.04     (MH65788 to MH6       9     8-30-292     8-85-138     O Fayette Ave     Majestic Properties Inc     5.96     (MH65786 to MH6       9     8-30-292     8-85-138     0 Fayette Ave     Majestic Properties Inc     5.96     (MH65786 to MH6       10     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH72184) adjacet       11     154.50-1-34     4-55-1382     207 Union Ave     Carvalho, Orlando     10.29     sewer along Rose       12     9-42-419     9-88-148     1031								Sewer along E Bo
5     9-42-568     9-89D-24     1107 Cove Rd North     Hampshire Recreation LIc     0.00     Sewer along Cove 65928, 65927, and Sewer along Valle       6     9-1-176     9-20-9     233 Valley PI     Yannuzzi, Jack & Michael     0.00     parallel to river bel Sewer along Ovie       7     9-48-277     9-100-1     888 Orienta Ave     888 Orienta LIc     4.14     be served by this 5       8     9-52-1     9-98-1     1025 Rushmore Ave     Orienta Beach Club     5.04     (MH65788 to MH6       9     8-30-292     8-85-18A     0 Fayette Ave     Majestic Properties Inc     5.96     (MH65596 to MH6       9     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH721843) adjacet       11     154.50-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH721843) adjacet       12     9-42-419     9-89B-18     1031 Cove Rd South     Shifrin, Leslie & Fran     12.07     MH652824       13     9-11-342     9-22-16     200 Fution Rd     Paul, Elizabeth     14.25     Sewer along Futio       14     154.50-1-	4	154.58-1-16	4-60-7A1	325 E Boston Post Rd	Orienta Yacht Club		0.00	parcel
5     9-42-568     9-89D-24     1107 Cove Rd North     Hampshire Recreation Llc     0.00     65928, 65927, and Sever along Valle       6     9-1-176     9-20-9     233 Valley PI     Yanuzzi, Jack & Michael     0.00     fsewer along Valle parallel to river be property. No build property. No build be served by this s       7     9-48-277     9-100-1     888 Orienta Ave     888 Orienta Llc     4.14     be served by this s       8     9-52-1     9-98-1     1025 Rushmore Ave     0rienta Beach Club     5.04     (MH65788 to MH6 Sever along Valle       9     8-30-292     8-85-18A     0 Fayette Ave     Majestic Properties Inc     5.96     Sever along Forint (MH65788 to MH6 Sever along Rose       10     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MI72184) adjace       11     154.50-1-38     4-55-13B3     207 Union Ave     Carvalho, Orlando     10.99     property       12     9-42-419     9-89B-18     1031 Cove Rd South     Shifrin, Leslie & Fran     12.07     MH565924       13     9-11-34     4-55-16A     225 Union Ave     Quadrini, Mario     14.25								Sewer along Cove
6     9-1.176     9-20-9     233 Valley PI     Yanuzzi, Jack & Michael     0.00     garallel to rive bel property.       7     9-48-277     9-100-1     888 Orienta Ave     888 Orienta Llc     4.14     beserved by this 5. Sever along Orienta       8     9-52-1     9-98-1     1025 Rushmore Ave     Orienta Beach Club     5.04     (MH65788 to MH6       9     8:30-292     8-85-13A     0 Fayette Ave     Majestic Properties Inc     5.96     (MH65586 to MH6       9     8:30-292     8-85-13B3     0 Fayette Ave     Majestic Properties Inc     5.96     (MH65596 to MH6       10     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH72184) adjacet       11     154.50-1-38     4-55-13B3     207 Union Ave     Carvalho, Orlando     10.99     property       12     9-42-419     9-898-18     1031 Cove Rd South     Shifrin, Leslie & Fran     12.07     MH65924       13     9-11-344     -55-16A     225 Union Ave     Quadrini, Mario     14.85     Sever along Fuith       15     154.75-1-17     4-55-16A	5	9-42-568	9-89D-24	1107 Cove Rd North	Hampshire Recreation Llc		0.00	65928, 65927, and
6     9-1-176     9-20-9     233 Valley PI     Yannuzzi, Jack & Michael     0.00     parallel to river being Sewer along Orient       7     9-48-277     9-100-1     888 Orienta Ave     888 Orienta Lic     4.14     be served by this in the severed by this in the severe along Feinith       8     9-52-1     9-98-1     1025 Rushmore Ave     Orienta Beach Club     5.04     (MH65788 to MH6       9     8-30-292     8-85-18A     0 Fayette Ave     Majestic Properties Inc     5.96     MiH65788 to MH6       9     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH72184) adjace       11     154.50-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     10.99     property       12     9-42-419     9-89B-18     1031 Cove Rd South     Shiftrin, Leslie & Fran     12.07     MH65924       13     9-11-342     9-22-16     200 Fulton Rd     Paul, Elizabeth     14.25     Sewer along The sever along The se					·			Sewer along Valle
7     9-48-277     9-100-1     888 Orienta Ave     888 Orienta Llc     Sewer along Orient property, No build be served by this s       8     9-52-1     9-98-1     1025 Rushmore Ave     Orienta Beach Club     5.04     (MH65596 to MH6 Sewer along Patit be served along Fenir 9       9     8-30-292     8-85-18A     0 Fayette Ave     Majestic Properties Inc     5.96     (MH65596 to MH6 Sewer along Fenir 9       10     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH72184) adjace       11     154.50-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     9     Sewer along oriethe 9       12     9-42-419     9-89B-18     1031 Cove Rd South     Shifrin, Leslie & Fran     12.07     MH65924       13     9-11-342     9-22-16     200 Fulton Rd     Paul, Elizabeth     14.25     Sewer along Fulto       14     154.50-1-38     4-55-16A     225 Union Ave     Quadrini, Mario     18.71     Sewer along Tulto       15     154.75-117     4-76-16B     519 Alda Rd     Mann, J Robert Jr     15.59     Sewer along Tulto       16 <td< td=""><td>6</td><td>9-1-176</td><td>9-20-9</td><td>233 Valley Pl</td><td>Yannuzzi, Jack &amp; Michael</td><td></td><td>0.00</td><td>parallel to river bet</td></td<>	6	9-1-176	9-20-9	233 Valley Pl	Yannuzzi, Jack & Michael		0.00	parallel to river bet
7     9-48-277     9-100-1     888 Orienta Ave     888 Orienta Llc     4.14     be served by this :       8     9-52-1     9-98-1     1025 Rushmore Ave     Orienta Beach Club     5.04     (MH652816 MH6       9     8-30-292     8-85-18A     0 Fayette Ave     Majestic Properties Inc     5.04     (MH652596 to MH6       9     8-30-292     8-85-18A     0 Fayette Ave     Majestic Properties Inc     5.96     (MH652596 to MH6       10     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH72184) adjacet       11     154.50-1-38     4-55-13B3     207 Union Ave     Carvalho, Orlando     10.99     property       12     9-42-419     9-89B-18     1031 Cove Rd South     Shifrin, Leslie & Fran     12.07     MH65924       13     9-11-342     9-22-16     200 Fulton Rd     Paul, Elizabeth     14.25     Sewer along Fulto       14     154.75-1-17     4-75-16A     225 Union Ave     Quadrini, Mario     14.28     Sewer along Tulto       15     154.75-1-17     4-75-16A     225 Union Ave								Sewer along Orier
7     9-48-277     9-100-1     888 Orienta Ave     888 Orienta Llc     4.14     be served by this s       8     9-52-1     9-98-1     1025 Rushmore Ave     Orienta Beach Club     5.04     (MH65286 to MH6       9     8-30-292     8-85-18A     0 Fayette Ave     Majestic Properties Inc     5.96     (MH65528 to MH6       10     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH72184) adjacet       10     154.50-1-38     4-55-13B3     207 Union Ave     Carvalho, Orlando     10.99     property       11     154.50-1-34     4-55-16A     207 Union Ave     Carvalho, Orlando     10.99     property       12     9-42-419     9-89B-18     1031 Cove Rd South     Shifrin, Leslie & Fran     12.07     MH65924       13     9-11-342     9-922-16     200 Fulton Rd     Paul, Elizabeth     Sever along Fulto       14     154.50-1-34     4-55-16A     225 Union Ave     Quadrini, Mario     14.88     property       15     154.75-117     4-76-18     519 Alda Rd     Mann, J Robert Jr								property, No buildi
8     9-52-1     9-98-1     1025 Rushmore Ave     Orienta Beach Club     5.04     (MH65788 to MH6       9     8-30-292     8-85-18A     0 Fayette Ave     Majestic Properties Inc     5.96     (MH65596 to MH6       10     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH72184) adjacer       11     154.50-1-38     4-55-13B3     207 Union Ave     Carvalho, Orlando     10.99     property       12     9-42-419     9-89B-18     1031 Cove Rd South     Shifrin, Leslie & Fran     12.07     MH65924       13     9-11-342     9-22-16     200 Fulton Rd     Paul, Elizabeth     14.25     Sewer along Droperty       14     154.50-1-34     4-55-16A     225 Union Ave     Quadrini, Mario     14.88     property       15     154.75-1-17     4-76-1B     519 Alda Rd     Mann, J Robert Jr     15.59     Sewer along Drop       16     9-37-159     9-85-34B     818 The Crescent     Ottinger, Richard     18.71     Sewer along Drop       17     9-26-36     9-64-PLOT     347 Orienta Ave <td< td=""><td>7</td><td>9-48-277</td><td>9-100-1</td><td>888 Orienta Ave</td><td>888 Orienta Llc</td><td></td><td>4.14</td><td>be served by this s</td></td<>	7	9-48-277	9-100-1	888 Orienta Ave	888 Orienta Llc		4.14	be served by this s
8     9-52-1     9-98-1     1025 Rushmore Ave     Orienta Beach Club     5.04     (MH65788 to MH6 Sever along Fenir Sever along Fenir Sever along Rose       9     8-30-292     8-85-18A     0 Fayette Ave     Majestic Properties Inc     5.96     (MH65578 to MH6       10     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH72184) adjacet       11     154.50-1-38     4-55-13B3     207 Union Ave     Carvalho, Orlando     10.99     property       12     9-42-419     9-89B-18     1031 Cove Rd South     Shifrin, Leslie & Fran     12.07     Sewer along Rose       13     9-11-342     9-22-16     200 Fulton Rd     Paul, Elizabeth     14.25     Sewer along Fulto       14     154.50-1-34     4-55-16A     225 Union Ave     Quadrini, Mario     14.88     property       15     154.75-1-17     4-76-1B     519 Alda Rd     Mann, J Robert Jr     15.59     Sewer along Alda       16     9-37-159     9-85-34B     818 The Crescent     Ottinger, Richard     18.71     Sewer along Alda       19     8-2-489								Sewer along Walto
9     8-30-292     8-85-18A     0 Fayette Ave     Majestic Properties Inc     5.96     Sever along Fenir (MH65596 to MH6       10     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH72184) adjacer       11     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH72184) adjacer       11     154.28-1-38     4-55-13B3     207 Union Ave     Carvalho, Orlando     10.99     Sever along Union       12     9-42-419     9-89B-18     1031 Cove Rd South     Shifrin, Leslie & Fran     12.07     MH65924       13     9-11-342     9-22-16     200 Fulton Rd     Paul, Elizabeth     14.25     Sever along Union       14     154.50-1-34     4-55-16A     225 Union Ave     Quadrini, Mario     14.88     property       15     154.75-1.17     4-76-1B     519 Alda Rd     Mann, J Robert Jr     15.59     Sever along Olda       16     9-37-159     9-85-34B     818 The Crescent     Ottinger, Richard     18.75     Sever along Olda       17     9-26-36     9-64-PLOT     347 Orie	8	9-52-1	9-98-1	1025 Rushmore Ave	Orienta Beach Club		5.04	(MH65788 to MH6
9     8-30-292     8-85-18A     0 Fayette Ave     Majestic Properties Inc     5.96     (IMH65596 to MH6       10     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH72184) adjacer       11     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH72184) adjacer       11     154.50-1-38     4-55-13B3     207 Union Ave     Carvalho, Orlando     10.99     property       12     9-42-419     9-89B-18     1031 Cove Rd South     Shifrin, Leslie & Fran     12.07     MH65924       13     9-11-342     9-22-16     200 Fulton Rd     Paul, Elizabeth     14.25     Sewer along Fulto       14     154.50-1-34     4-55-16A     225 Union Ave     Quadrini, Mario     14.88     property       15     154.75-1-17     4-76-1B     519 Alda Rd     Mann, J Robert Jr     15.59     Sewer along The O       17     9-26-36     9-64-PLOT     347 Orienta Ave     Sharus, Sarene     36.33     Sewer along Alda       19     8-2-489     8-58-25B     222 Highview St     Cirac								Sewer along Fenir
10154.28-1-384-49-62A1503 Rose LnAntolino, RoseSewer along Rose11154.28-1-384-49-62A1503 Rose LnAntolino, Rose8.99MH72184) adjacet11154.50-1-384-55-13B3207 Union AveCarvalho, Orlando10.99property129-42-4199-89B-181031 Cove Rd SouthShifrin, Leslie & Fran12.07MH65924139-11-3429-22-16200 Fulton RdPaul, Elizabeth14.25Sewer along Fulto14154.50-1-344-55-16A225 Union AveQuadrini, Mario14.88property15154.75-1-174-76-1B519 Alda RdMann, J Robert Jr15.59Sewer along Alda169-37-1599-85-34B818 The CrescentOttinger, Richard18.71Sewer along Old E179-26-369-64-PLOT347 Orienta AveSharus, Sarene36.33Sewer along Hido18154.68-1-14-76-16A575 Alda RdHenley, Mark & Barbara36.82Sewer along Hido198-2-4898-58-25B222 Highview StCiraco, Anne & Giovanni44.55Sewer along High20155.29-1-334-65-9B1600 Harrison Ave1600 Harrison LlcSo.92along Ryewood Fa21154.34-2-134-20-32500 Halstead AveRemodeling Consultants OfWestchester Inc Gj Zaccaria62.47property21154.34-2-134-20-32500 Halstead AveRemodeling Consultants OfWestchester Inc Gj ZaccariaSewer along Raddi	9	8-30-292	8-85-18A	0 Fayette Ave	Majestic Properties Inc		5.96	(MH65596 to MH6
10     154.28-1-38     4-49-62A     1503 Rose Ln     Antolino, Rose     8.99     MH72184) adjacet       11     154.50-1-38     4-55-13B3     207 Union Ave     Carvalho, Orlando     10.99     property       12     9-42-419     9-89B-18     1031 Cove Rd South     Shifrin, Leslie & Fran     12.07     MH65924       13     9-11-342     9-22-16     200 Fulton Rd     Paul, Elizabeth     14.25     Sewer along Fulto       14     154.50-1-34     4-55-16A     225 Union Ave     Quadrini, Mario     14.88     property       15     154.75-1-17     4-76-18     519 Alda Rd     Mann, J Robert Jr     15.59     Sewer along Pulto       16     9-37-159     9-85-34B     818 The Crescent     Ottinger, Richard     18.71     Sewer along Old E       18     154.68-1-1     4-76-16A     575 Alda Rd     Henley, Mark & Barbara     36.82     Sewer along Alda       19     8-2-489     8-58-25B     222 Highview St     Ciraco, Anne & Giovanni     44.55     Sewer along Harit       20     155.29-1-33     4-65-9B     1600 Harrison Llc </td <td></td> <td></td> <td></td> <td>_</td> <td></td> <td></td> <td></td> <td>Sewer along Rose</td>				_				Sewer along Rose
11154.50-1-384-55-13B3207 Union AveCarvalho, Orlando10.99Sewer along Union129-42-4199-89B-181031 Cove Rd SouthShifrin, Leslie & Fran12.07MH65924139-11-3429-22-16200 Fulton RdPaul, Elizabeth14.25Sewer along Fulto14154.50-1-344-55-16A225 Union AveQuadrini, Mario14.88property15154.75-1-174-76-18519 Alda RdMann, J Robert Jr15.59Sewer along Alda169-37-1599-85-34B818 The CrescentOttinger, Richard18.71Sewer along Old E179-26-369-64-PLOT347 Orienta AveShanus, Sarene36.33Sewer along Alda198-2-48985-825B222 Highview StCiraco, Anne & Giovanni44.55Sewer along High20155.29-1-334-65-9B1600 Harrison Ave1600 Harrison Llc50.92along Ryewood Fa21154.34-2-134-20-32500 Halstead AveRemodeling Consultants OfWestchester Inc Gj Zaccaria62.47propertySwer along Bradd	10	154.28-1-38	4-49-62A	1503 Rose Ln	Antolino, Rose		8.99	MH72184) adjacer
11   154.50-1-38   4-55-13B3   207 Union Ave   Carvalho, Orlando   10.99   property     12   9-42-419   9-89B-18   1031 Cove Rd South   Shifrin, Leslie & Fran   12.07   MH65924     13   9-11-342   9-22-16   200 Fulton Rd   Paul, Elizabeth   14.25   Sewer along Fulto     14   154.50-1-34   4-55-16A   225 Union Ave   Quadrini, Mario   14.88   property     15   154.75-1-17   4-76-1B   519 Alda Rd   Mann, J Robert Jr   15.59   Sewer along Alda     16   9-37-159   9-85-34B   818 The Crescent   Ottinger, Richard   18.71   Sewer along Nida     17   9-26-36   9-64-PLOT   347 Orienta Ave   Shanus, Sarene   36.33   Sewer along Nida     19   8-2-489   8-58-25B   222 Highview St   Ciraco, Anne & Giovanni   44.55   Sewer along High     20   155.29-1-33   4-65-9B   1600 Harrison Llc   50.92   along Ryewood Fa     21   154.34-2-13   4-20-32   500 Halstead Ave   Remodeling Consultants Of   Westchester Inc Gj Zaccaria   Sewer along Bradt								Sewer along Unior
129-42-4199-89B-181031 Cove Rd SouthShifrin, Leslie & Fran12.07MH65924139-11-3429-22-16200 Fulton RdPaul, Elizabeth14.25Sewer along Fulto14154.50-1-344-55-16A225 Union AveQuadrini, Mario14.88property15154.75-1774-76-1B519 Alda RdMann, J Robert Jr15.59Sewer along Alda169-37-1599-85-34B818 The CrescentOttinger, Richard18.71Sewer along Old E179-26-369-64-PLOT347 Orienta AveShanus, Sarene36.33Sewer along Alda198-2-4898-58-25B222 Highview StCiraco, Anne & Giovanni44.55Sewer along High20155.29-1-334-65-9B1600 Harrison Ave1600 Harrison Llc50.92along Ryewood Fa21154.34-2-134-20-32500 Halstead AveRemodeling Consultants OfWestchester Inc Gj Zaccaria62.47property	11	154.50-1-38	4-55-13B3	207 Union Ave	Carvalho, Orlando		10.99	property
12   9-42-419   9-898-18   1031 Cove Rd South   Shifrin, Lesile & Fran   12.07   MH65924     13   9-11-342   9-22-16   200 Fulton Rd   Paul, Elizabeth   14.25   Sewer along Fulto     14   154.50-1-34   4-55-16A   225 Union Ave   Quadrini, Mario   14.88   property     15   154.75-1-17   4-76-1B   519 Alda Rd   Mann, J Robert Jr   15.59   Sewer along Alda     16   9-37-159   9-85-34B   818 The Crescent   Ottinger, Richard   18.71   Sewer along Old E     17   9-26-36   9-64-PLOT   347 Orienta Ave   Shanus, Sarene   36.33   Sewer along Alda     19   8-2-489   8-58-25B   222 Highview St   Ciraco, Anne & Giovanni   44.55   Sewer along High     20   155.29-1-33   4-65-9B   1600 Harrison Ave   1600 Harrison Llc   50.92   along Ryewood Fa     21   154.34-2-13   4-20-32   500 Halstead Ave   Remodeling Consultants Of   Westchester Inc Gj Zaccaria   62.47   property	10	0.40.440	0.005.40				10.07	Sewer along either
139-11-3429-22-16200 Fulton RdPaul, Elizabeth14.25Sewer along Fulton14154.50-1-344-55-16A225 Union AveQuadrini, Mario14.88property15154.75-1-174-76-1B519 Alda RdMann, J Robert Jr15.59Sewer along Alda169-37-1599-85-34B818 The CrescentOttinger, Richard18.71Sewer along The O179-26-369-64-PLOT347 Orienta AveShanus, Sarene36.33Sewer along Old E18154.68-1-14-76-16A575 Alda RdHenley, Mark & Barbara36.82Sewer along Alda198-2-4898-58-25B222 Highview StCiraco, Anne & Giovanni44.55Sewer along Highview20155.29-1-334-65-9B1600 Harrison Ave1600 Harrison Llc50.92along Ryewood Fa21154.34-2-134-20-32500 Halstead AveRemodeling Consultants OfWestchester Inc Gj Zaccaria62.47propertySewer along Bradt	12	9-42-419	9-89B-18	1031 Cove Rd South	Shifrin, Leslie & Fran		12.07	MH65924
14154.50-1-344-55-16A225 Union AveQuadrini, Mario14.88property15154.75-1-174-76-1B519 Alda RdMann, J Robert Jr15.59Sewer along Alda169-37-1599-85-34B818 The CrescentOttinger, Richard18.71Sewer along Alda179-26-369-64-PLOT347 Orienta AveShanus, Sarene36.33Sewer along Old E18154.68-1-14-76-16A575 Alda RdHenley, Mark & Barbara36.82Sewer along Alda198-2-4898-58-25B222 Highview StCiraco, Anne & Giovanni44.55Sewer along Highview St20155.29-1-334-65-9B1600 Harrison Ave1600 Harrison Llc50.92Sewer along Ryewood Fa21154.34-2-134-20-32500 Halstead AveRemodeling Consultants OfWestchester Inc Gj Zaccaria62.47property	13	9-11-342	9-22-16	200 Fulton Rd	Paul, Elizabeth		14.25	Sewer along Fulto
14154.50-1-344-55-16A225 Union AveQuadrini, Mario14.88property15154.75-1-174-76-1B519 Alda RdMann, J Robert Jr15.59Sewer along Alda169-37-1599-85-34B818 The CrescentOttinger, Richard18.71Sewer along The G179-26-369-64-PLOT347 Orienta AveShanus, Sarene36.33Sewer along Old E18154.68-1-14-76-16A575 Alda RdHenley, Mark & Barbara36.82Sewer along Alda198-2-4898-58-25B222 Highview StCiraco, Anne & Giovanni44.55Sewer along Highview20155.29-1-334-65-9B1600 Harrison Ave1600 Harrison Llc50.92along Ryewood Fa21154.34-2-134-20-32500 Halstead AveRemodeling Consultants OfWestchester Inc Gj Zaccaria62.47property	4.4				Quadria: Maria		14.00	Sewer along Unior
15154.75-1-174-76-18519 Alda RdMarrin, J Robert Ji15.59Sewer along Alda169-37-1599-85-34B818 The CrescentOttinger, Richard18.71Sewer along The G179-26-369-64-PLOT347 Orienta AveShanus, Sarene36.33Sewer along Old E18154.68-1-14-76-16A575 Alda RdHenley, Mark & Barbara36.82Sewer along Alda198-2-4898-58-25B222 Highview StCiraco, Anne & Giovanni44.55Sewer along Highview20155.29-1-334-65-9B1600 Harrison Ave1600 Harrison Llc50.92along Ryewood Fa21154.34-2-134-20-32500 Halstead AveRemodeling Consultants OfWestchester Inc Gj Zaccaria62.47property	14	154.50-1-34	4-55-16A	225 Union Ave	Quadrini, Mario		14.88	property Sower clong Aldo
169-37-1599-63-34B818 The CrescentOttinger, Richard16.71Sewer along The Crescent179-26-369-64-PLOT347 Orienta AveShanus, Sarene36.33Sewer along Old E18154.68-1-14-76-16A575 Alda RdHenley, Mark & Barbara36.82Sewer along Alda198-2-4898-58-25B222 Highview StCiraco, Anne & Giovanni44.55Sewer along Highview20155.29-1-334-65-9B1600 Harrison Ave1600 Harrison Llc50.92along Ryewood Fa21154.34-2-134-20-32500 Halstead AveRemodeling Consultants OfWestchester Inc Gj Zaccaria62.47propertySewer along Bradt	15	154.75-1-17	4-70-1D	S19 Alua Ru	Ottinger Richard		10.09	Sewer along Alda
179-20-369-04-PLOT347 Orienta AveStrands, safelie36.33Sewer along Oid E18154.68-1-14-76-16A575 Alda RdHenley, Mark & Barbara36.82Sewer along Alda198-2-4898-58-25B222 Highview StCiraco, Anne & Giovanni44.55Sewer along Highview20155.29-1-334-65-9B1600 Harrison Ave1600 Harrison Llc50.92along Ryewood Fa21154.34-2-134-20-32500 Halstead AveRemodeling Consultants OfWestchester Inc Gj Zaccaria62.47propertySewer along Bradt	10	9-37-159	9-00-34D	247 Orienta Ave	Shapura Sarana		10.71	Sewer along The C
16134.06-1-14-76-16A575 Alda KuHerney, Mark & Barbara50.02Sewer along Alda198-2-4898-58-25B222 Highview StCiraco, Anne & Giovanni44.55Sewer along Highview20155.29-1-334-65-9B1600 Harrison Ave1600 Harrison Llc50.92along Ryewood Fa21154.34-2-134-20-32500 Halstead AveRemodeling Consultants OfWestchester Inc Gj Zaccaria62.47propertySewer along Bradt	17	9-20-30	9-04-FLOT	575 Aldo Pd	Hoploy Mark & Barbara		36.82	Sewer along Alda
13   0-2-403   0-30-250   222 High west   Chack, Anne & Glovanni   Sewer along High     20   155.29-1-33   4-65-9B   1600 Harrison Ave   1600 Harrison Llc   50.92   along Ryewood Fa     21   154.34-2-13   4-20-32   500 Halstead Ave   Remodeling Consultants Of   Westchester Inc Gj Zaccaria   62.47   property	10	8-2-480	4-70-10A 8-58-25B	222 Highview St	Ciraco, Anne & Giovanni		30.02	Sewer along High
20   155.29-1-33   4-65-9B   1600 Harrison Ave   1600 Harrison Llc   50.92   along Ryewood Fa     21   154.34-2-13   4-20-32   500 Halstead Ave   Remodeling Consultants Of   Westchester Inc Gj Zaccaria   62.47   property	13	0-2-409	0-30-230				44.55	Sewer along High
20   100.25 + 30   4 00 3D   1000 Hallstein NVC   1000 Hallstein Lic   0 00.02   doing NyCwood + 20     21   154.34-2-13   4-20-32   500 Halstead Ave   Remodeling Consultants Of   Westchester Inc Gj Zaccaria   62.47   property	20	155 29-1-33	4-65-9B	1600 Harrison Ave	1600 Harrison Llc		50.92	along Ryewood Fa
21   154.34-2-13   4-20-32   500 Halstead Ave   Remodeling Consultants Of   Westchester Inc Gj Zaccaria   62.47   property     Sewer along Bradt	20	100.20 1 00	+ 00 0D				00.02	Sewer along Halst
2. To the 2 to 1 20 02 for that day the first had all grant and on the of 2000 had black in the	21	154 34-2-13	4-20-32	500 Halstead Ave	Remodeling Consultants Of	Westchester Inc Gi Zaccaria	62 47	property
	21	104.04 2 10	7 20 02				52.77	Sewer along Brad
border between tw								border between tw
22 8-17-703.1 8-52-1 125 Gertrude Ave Di Nota, Thomas Jr 81.39 Ave MH65448 se	22	8-17-703 1	8-52-1	125 Gertrude Ave	Di Nota, Thomas Jr		81 39	Ave. MH65448 se
Address associate								Address associate
23 154.68-1-17 4-77-35B 506 S Barry Ave Klein, Lawrence & Judith 86.78 of property	23	154.68-1-17	4-77-35B	506 S Barry Ave	Klein, Lawrence & Judith		86.78	of property

rs outside of Village school parcel; Sewer lines cross

ley Ave, MH65492 in front of property, additional property

St, MH65450 adjacent to property ston Post Rd, and through parcel; MH66307 is within

e Rd in front of property, between MH65930, 65929, d 65926. Illegal connection at this location

ey PI between MH 68431 and MH68430, Sewer located tween MH65071 and MH65070 on either side of property inta Ave between MH65967 and MH65964 in front of ings on parcel with septic, but house in next parcel may septic tank

on Ave (MH65887 to MH65855) and Rushmore Ave 65786) on either side of property (Orienta Beach Club) more Rd (MH65592 to MH65591) and Fayette Ave 65592) adjacent to property

e Ln (MH72187 to MH72184) and Hunter St (MH72185 to nt to property

n Ave between MH65041 and MH65040 adjacent to

r side of property on Cove Rd, MH65942, MH65943,

on Rd, MH VG54

n Ave, between MH65043 and MH65041, in front of

Rd, between MH66447 and MH66448, in front of

Crescent, MH65782, adjacent to property

Boston Post Rd, MH VK53, in front of property

Rd, MH66452, in front of property

view St, MH65527, in front of property

ison Ave, (MH67052) approx 150 feet from building, or arm Drive (MH67153) approx 300 feet from building tead Ave, between MH65086 and MH65087, in front of

lford Ave, MH65432 (pipe would have to travel along vo parcels under paved surface) or sewer along Gertrude ewer may be abandoned?

ed with septic location is 506 S Barry, MH66505 is in front



# Parcel Boundary between 100 ft and 150 ft of Public Sewer

						Distance	
						to Sewer	
SepticNumber	Town_ID	Village_ID	PropAddres	Owner_Name	Owner_Na_1	Line	Notes
24	154.28-2-71	4-50-14A	1634 Harrison Ave	Schlotter, Karen		104.51	Sewer along Harris
							Sewer along Bishc
25	8-25-615	8-111-1B8	420 Railroad Way	Spatz Industries Inc		115.91	of railroad tracks; \$
							Sewer along Old B
26	9-27-114	9-62-5B	325 Cooper Ave	Clinton, James B		121.31	would cross other
							Sewer along Gree
27	9-56-1	9-99-1F	1010 Greacen Pt Rd	Weinstein, Pierre & Caroline		133.17	parcel to reach clo
							Closest sewer is a
							closer to Alda Rd S
							parcels or follow S
28	154.68-1-20	4-77-21	0 Taylors Ln	The Nature Conservancy		133.89	Nature Conservan
29	154.28-2-69	4-50-15B	1620 Harrison Ave	Figliola, Josephine		134.44	Closest sewer is o
							Closest sewer is o
30	155.45-1-2	4-77-16-2	533 Taylors Ln	O'Brien, Tracy		137.32	without crossing of
31	154.28-2-68	4-50-15A	1616 Harrison Ave	Wright, Scott J		148.93	Closest sewer is o

son Ave (MH67146) toward Tulip Tree Ln

op Ave (MH68458), 115' away from parcel on other side Sewer along Ogden Ave, MH65605, 150' away from Boston Post Rd, between MH VK55A and VK55, new line

parcel or would follow Cooper Ave

en Meadow Ln (MH65966), new line would cross other osest manhole

along Soundview Dr, Indicated location of septic tank is Sewer, but a new line would have to cross several B Barry Ave and turn to connect with Alda Rd Sewer; hcy Land

on Harrison Ave/Tulip Tree Ln, MH67147 or MH67146 on Colonial Ct, MH66550. Could be accessed along road other parcels

on Harrison Ave/Tulip Tree Ln, MH67147 or MH67146



# Parcel Boundary over 150 ft from Public Sewer

						Distance	
						to Sewer	
SepticNumber	Town_ID	Village_ID	PropAddres	Owner_Name	Owner_Na_1	Line	Notes
32	154.28-2-73	4-50-13B2	116 Standish Pl	Ybarra, Peter Brian		180.54	Sewer more than 150 feet from property line
33	154.76-1-5	4-76-12A	0 S Barry Ave - Rear	Village Of Mam'K		186.17	Sewer more than 150 feet from property line
34	9-27-87	9-62-5C	329 Cooper Ave	Joyce, James		187.65	Sewer more than 150 feet from property line
35	9-49-268	9-94-11A	930 Greacen Ln	Allen, Michael		189.43	Sewer more than 150 feet from property line
36	9-49-1	9-93A-16	1019 Greacen Pt Rd	Grehan, Kevin & Pamela		206.44	Sewer more than 150 feet from property line
37	154.68-1-19	4-77-32	0 S Barry Ave	The Nature Conservancy		207.68	Sewer more than 150 feet from property line
38	9-26-26	9-63-13	340 Cooper Ave	Lasagne, Robert & Lisa		250.14	Sewer more than 150 feet from property line
39	9-44-60	9-92-3D	11 Oak Ln	Hinerfeld, Ruth		256.02	Sewer more than 150 feet from property line
40	9-44-81	9-92-9B	10 Oak Ln	Mccance, Sean & Zsuzsanna		308.52	Sewer more than 150 feet from property line
41	9-49-12	9-93C-19	1011 Greacen Pt Rd	Bauer, John		311.87	Sewer more than 150 feet from property line
42	9-34-600	9-72-14F	940 Fairway Ln	Schneiderman, Scott M		342.96	Sewer more than 150 feet from property line
43	154.76-1-2	4-77-30A2	604 S Barry Ave	520 S Barry Llc		343.66	Sewer more than 150 feet from property line
44	9-50-410	9-93A-14	1115 Greacen Pt Rd	Cohen, Benjamin & Bella		387.79	Sewer more than 150 feet from property line
45	9-50-83	9-93B-9	1160 Greacen Pt Rd	Bernstein, Richard K Trustee		389.53	Sewer more than 150 feet from property line
46	8-4-796	8-41B-6	111 Rockridge Rd	Snyder, Thomas R		415.15	Sewer more than 150 feet from property line
47	154.68-1-21	4-77-21A	600 S Barry Ave	Crosby, John P		448.86	Sewer more than 150 feet from property line
48	9-50-357	9-93A-8	1175 Greacen Pt Rd	Lieber, Constance E		517.92	Sewer more than 150 feet from property line
49	9-50-69	9-93B-7	1170 Greacen Pt Rd	Nodiff, Bradley & Pamela		521.10	Sewer more than 150 feet from property line
50	155.53-1-1	4-77-16A	942 Taylors Ln	Field, Marvin J.		568.82	Sewer more than 150 feet from property line
51	9-44-1	9-92-3A	3 Oak Ln	Cantwell, Paul & Sally		569.88	Sewer more than 150 feet from property line
52	9-50-337	9-93A-6	1185 Greacen Pt Rd	Bassuk,B, Kaufman,M, Tosi,J		596.53	Sewer more than 150 feet from property line
53	9-50-58	9-93B-5B	1180 Greacen Pt Rd	Rosenberg, Eric M & Helen K		654.19	Sewer more than 150 feet from property line
54	9-50-1	9-93B-2A	1210 Greacen Pt Rd	Lieber, Constance E		680.70	Sewer more than 150 feet from property line
55	9-50-44	9-93B-3C	1190 Greacen Pt Rd	Weinberg Family Trust 2011		718.77	Sewer more than 150 feet from property line
56	9-51-78	9-93B-2	1248 Greacen Pt Rd	Wetzel, Carroll & Bert		727.53	Sewer more than 150 feet from property line
57 2	155.53-1-17.1	4-79-8A1	907 Taylors Ln	Neubardt, Seth		836.71	Sewer more than 150 feet from property line
58	9-45-98	9-92-5	205 Hommocks Rd	Hoffman, Richard D	Hoffman Mills Attn: Dru Chapman	859.04	Sewer more than 150 feet from property line
59	9-51-45	9-93B-1B	1308 Greacen Pt Rd	Koeppel, Maureen		874.83	Sewer more than 150 feet from property line
60	155.53-1-19	4-79-8B5	843 Taylors Ln	Mawe, John & Alison		878.50	Sewer more than 150 feet from property line
61	154.68-1-24	4-77A-8	770 Taylors Ln	Bogart, Frederic & Jeannette		900.88	Sewer more than 150 feet from property line
62	155.53-1-20	4-79-8B4	841 Taylors Ln	Hackenburg, Frederick W		912.64	Sewer more than 150 feet from property line
63	154.68-1-23	4-77A-6	0 Taylors Ln	Wolff, Jesse D	Elizabeth H Wolff C/O Daniel Wolff	923.86	Sewer more than 150 feet from property line
64	9-51-20	9-93B-1A	1326 Greacen Pt Rd	Chapey, Fredrick J Jr		998.03	Sewer more than 150 feet from property line
65	9-35-134	9-72A-8	541 Eagle Knolls Rd	Libo, Andrew		1026.33	Sewer more than 150 feet from property line
66	9-35-65	9-72A-7	520 Hommocks Rd	Bargiuirdjian, Henri		1045.66	Sewer more than 150 feet from property line
67	9-35-56	9-72A-6B	516 Hommocks Rd	516 HOMMOCKS Rd LIC		1108.03	Sewer more than 150 feet from property line
68	9-45-37	9-92-5	205 Hommocks Rd	Hoffman, Richard D	Hoffman Mills Attn: Dru Chapman	11/3.18	Sewer more than 150 feet from property line
69	9-35-47	9-72A-5B	512 Hommocks Rd	512 HOMMOCKS Rd LIC		11/3.80	Sewer more than 150 feet from property line
70	9-35-149	9-72A-9B		Cecii, Jonn & Cella		1176.54	Sewer more than 150 feet from property line
71	155.61-1-3	4-77-22	833 Taylors Ln	Derosa, John, Margit & Lisa	Builders Inc	1326.45	Sewer more than 150 feet from property line
72	155.61-1-12	4-77-14A	14 Shore Rd	Fensterstock, Jay		1534.68	Sewer more than 150 feet from property line
73	155.61-1-9	4-77-25-1A	1 Shore Rd	Friede, John A		1590.96	Sewer more than 150 feet from property line
74	155.69-1-1.1	4-77-28B1-A	700 Taylors Ln	Tabaddor, Kamran Md		1750.96	Sewer more than 150 feet from property line





## Arcadis U.S., Inc.

855 Route 146 Suite 210 Clifton Park, New York 12065 Tel 518 250 7300 Fax 518 250 7301

### www.arcadis.com